

# Repair Points - Low Priority

Point Type NOT IN ('Repair Point', 'Road Repair')  
 Feature Status = 'Approved'  
 Delete This NOT IN ('Yes - No Longer Needed', 'Yes - Editing Mistake')  
 Repair Status NOT IN ('In Use - Fire Management', 'No Repair Needed')  
 Repair Priority = Low

GISS Misc	Point Type	Repair Status	Repairs Needed	Repair Comments
10	Helispot	Repair Needed	Slash Piles	REAF Maginel, 8/31. Seed area that has received forwarder and skidder and truck use. Area to be seeded is about 200 x 200 square feet.
340	Resource Location	Repair Needed	Cut high stumps	
425	Dozer Push	Needs Assessment		Bring to grade and provide drainage. 08/05 REAF KC. ARCH CARDARELLA 8/30 - cleared but minor road grade push low priority.
426	Dozer Push	Needs Assessment	Full Repair	Bring to grade and provide drainage. 08/05-REAF KC. 8/30-ARCH CARDARELLA - seeding and berm knocked down
468	Culvert	Needs Assessment	Full repair	Clear uphill culvert entrance
469	Culvert	Needs Assessment		Clear culvert of debris on uphill side
	Other	Repair Needed		READ Sargent 8/28/23. Lookout spot. Remove flagging when no longer needed.
	Dozer Push	Repair Needed	Recommend repairing with REAF on site. Pull back berms along road. Pull up side casted material to the extent possible on outlet side of culvert. Clean out around inlet side of culvert. Keep material out of drainage feature. 8/29 ARCH Cardarella cleared.	Forest Engineers need to come look, damage was done prior to fire. Dozer push made road passable
	Dozer Push	Repair Needed	Recommend repairing with REAF on site. Pull berms along road section near culvert. Pull up side casted materials and place away from drainage. 8/29 ARCH Cardarella cleared.	Forest Engineers need to come look, damage was done prior to fire. Dozer push made road passable

# Repair Points - Medium Priority

Point Type NOT IN ('Repair Point', 'Road Repair')  
 FeatureStatus = 'Approved'  
 DeleteThis NOT IN ('Yes - No Longer Needed', 'Yes - Editing Mistake')  
 Repair Status NOT IN ('In Use - Fire Management', 'No Repair Needed')  
 Repair Priority = Medium

GISS Misc	Point Type	Repair Status	Repairs Needed	Repair Comments
3	Helispot	Repair Needed	READ Sargent 82723. Large landing converted to helispot. May need native re-seeding.	Light repair, part of POD
174	Dozer Push	Repair Needed	Light Repair	Leave as a permanent parking area, seed and mulch to prevent invasives. REAF Martin 8/27
251	Water Source	Repair Needed	backhaul and restore	9/3 ARCH CARDARELLA-backhaul pump, fuel, hoses, and kit. remove plastic from stream and undam. return screens to READS
428	Dozer Push	Repair Needed	Full Repair	Bring to grade and provide drainage. 08/05 REAF KC. 8/30 arch Cardarella- mitigate hazard trees on uphill side.
	Culvert	Repair Needed	Replace culvert. Pipe got hit by masticator and is now destroyed. REAF Olin 8/26	