Repair Points - High Priority

| GISS Misc | Point Type | Repair Status | Repairs Needed | Repair Comments |
|--------------|--------------------------|--------------------------------|--|---|
| 152 | Other | Needs Assessment | | |
| 43 | Drop Point | Repair Needed | | |
| 160 | Dozer Push | Completed - Inspected | Full repair | Pull in berms, seed and straw. cleared for arch by Slaton 8.2.23 |
| 4 | Helispot | Completed - Inspected | | |
| 60 | Drop Point | Repair Needed | | remove flagging, no other repairs needed. BM 8/22 |
| 177 | Repair Point | Repair Needed | Light Repair Meadow Repair | Seed. No straw. Danthonia californica and/or Elymus glaucus |
| 189 190 | Other Repair Point | Needs Assessment Repair Needed | Full repair | Seed, straw, block entrances, cover in veg |
| 29 | Drop Point | Repair Needed | | (REAF Johannsen)100x200 ft BM8/22 |
| 27 | Drop Point | Repair Needed | | no repair needed BM 8/22 |
| 202 | Repair Point | Repair Needed | Pull in berms, scatter veg, seed and straw 75x50ft BM 8/22 | Pull in berms, scatter slash, seed and straw |
| 205 | Resource Location | Repair Needed | Repair Light | Pull in equipment ruts and bring to grade for erosion control. |
| 208 | Repair Point | Repair Needed | Yes | End of complete repair section. Check with Tbird - working on plan with Ptarmagin trails (forest partner) |
| 209 | Repair Point | Repair Needed | Yes | Replace boulders to block this area from OHV. |
| 211 | Repair Point | Repair Needed | Yes | Hide the line from the road and block entrance with tank trap type thing to prevent OHV use |
| 10 | Helispot | Repair Needed | Mulch & seed with dry seed on sloped SE corner | REAF Maginel, 8/31. Seed area that has received forwarder and skidder and truck use. Area to be seeded is about 200 x 200 square feet. |
| 34 | Drop Point | Repair Needed | | |
| 282 | Repair Point | Repair Needed | Block and water bar. REAF JRH 7/27 | Repair Dozer line. REAF JRH 7/27 |
| 130 333 | Drop Point Repair Point | Repair Needed Repair Needed | Repair Light. Block, waterbar | Old road prism/dozer line opened. REAF JRH |
| 333 | Repair Foint | Repair Needed | and slash. REAF JRH 7/28 | 7/28 |
| 339 | Landing or Log Deck | Repair Needed | Full repair | French broom growing across on 1503, pulled, but seed source could be presentin landing. seed and mulch once logs are moved. REAF Martin 8/26 |
| 344 | Resource Location | Repair Needed | | handwork only, MIST Tactics, pull flagging |
| 345 | Landing or Log Deck | Repair Needed | Full repair | Seed and mulch once logs are removed to prevent invasives. REAF Martin 8/26 |
| 413 | Repair Point | Repair Needed | remove when no longer needed | photos in ESA box folder |
| 519 | Bridge | Completed - Inspected | remove when no longer needed | |
| 109 | Drop Point | Repair Needed | Light repair | Mulch & seed with dry seed mix along Rd 37 200ft on disturbed side |
| 570 | Repair Point | Repair Needed | Yes | Pull back berm through dozer line to access trail tread- pups trail |
| 571 | Repair Point | Repair Needed | Full | Dozer uprooted posts along road/trail |
| 593 | Repair Point | Completed - Inspected | | |
| 594 | Dozer Push | Completed - Inspected | | pull in berms, scatter slash, seed. ingasives present BM 8/23 |
| 613 | Stream Crossing | Repair Needed | full repair stream crossing | coconut matting to maintain stability of steep drainage crossing. REAF Calvin 8/25 Div T approved to change status |
| 617 | Stream Crossing | Repair Needed | full repair, stream crossing | stabilize dozer line leading to stream with coconut matting. READ present during repair. REAF EL 8/25 DIV T approved to change status |
| 615 | Stream Crossing | Repair Needed | full repair, stream crossing | stabilize dozer line leading to stream with coconut matting. read present during repair. REAF EL 8/25 DIV T approved to change status. |
| | Dozer Push | Repair Needed | Light repair | Push back and spread out soil, 20230909 READ miller |
| | Repair Point | Repair Needed | Light repair | Mulch & seed with dry seed mix 200ft from road, pull in slash. Small portion of seed spread over former log deck at top |
| | Repair Point | Repair Needed | Light repair | Mulch & seed with dry seed mix newly disturbed area |
| | Repair Point | Repair Needed | Light repair | Mulch & seed with dry seed mix 200ft from road |
| | Repair Point | Repair Needed | Light repair | Mulch & seed with dry seed mix 200 ft from road |
| | Repair Point | Repair Needed | Light repair | Mulch & seed with dry seed on sloped SE corner |
| | Repair Point | Repair Needed | Light repair | Seed with dry mix 200 ft from road, already mulched. |