



Repair Div A

# Repair

Lookout  
ORWIF-230327  
09/22/2023

Acres from IR & GPS  
25,659 acres at 9/20/2023 @ 2224

- |                          |                                  |                         |                                 |
|--------------------------|----------------------------------|-------------------------|---------------------------------|
| In Use - Fire Management | In Progress                      | Unimproved Landing Area | Other                           |
| Needs Assessment         | Completed - Ready for Inspection | Division Break          | Gate                            |
| Repair Needed            | Completed - Inspected            | Branch Break            | Bridge                          |
| Completed - Inspected    | No Repair Needed                 | Incident Command Post   | Water Development or Draft Site |
| Other - See Comments     | Airstrip or Airport              | Drop Point              | Stream Crossing                 |
| In Use - Fire Management | Dip Site                         | Closure                 | Road Repair                     |
| Needs Assessment         | Mobile Retardant Base            | Camp                    | Resource Location               |
| Repair Needed            | Helispot                         | Staging Area            | Repair Point                    |
|                          |                                  | Value at Risk           | Landing or Log Deck             |

- |                     |                                   |                               |
|---------------------|-----------------------------------|-------------------------------|
| Hazard Tree         | Completed Dozer Line              | Repair Line                   |
| Dozer Push          | Completed Fuel Break              | Road Repair                   |
| Clean Up Area       | Completed Hand Line               | Culvert                       |
| Mobile Weather Unit | Completed Mixed Construction Line | Retardant Drop                |
| Safety Zone         | Planned Dozer Line                | UAS Launch and Recovery Zone  |
| Hazard              | Access or Improved Road           | Contained                     |
| Completed Burnout   | Other                             | Uncontained Fire Edge         |
|                     |                                   | Wildfire Daily Fire Perimeter |

- |                                 |
|---------------------------------|
| Franklin-Clarkson Timber Co LLC |
| Giustina (Winberry)             |
| Oregon Dept of State Lands      |



9/21/2023 2026  
North American 1983 Datum. LatLong Grid  
0 0.25 0.5 1 1.5 Miles

Repair Div A