

Repair

Repair


Lookout

ORWIF-230327

10/10/2023

25754 acres at 10/04/2023 @ 1940
Acres from IR & GPS

<ul style="list-style-type: none"> ○ In Use - Fire Management Needs Assessment ● Repair Needed ○ In Progress ○ Completed - Ready for Inspection 	<ul style="list-style-type: none"> ■ Completed - Inspected ■ No Repair Needed ● Other - See Comments ■ In Use - Fire Management Needs Assessment ■ Repair Needed 	<ul style="list-style-type: none"> — In Progress — Completed - Ready for Inspection — Completed - Inspected — No Repair Needed — Other - See Comments 	<ul style="list-style-type: none"> ✕ Airstrip or Airport ○ Dip Site ○ Mobile Retardant Base ○ Helispot ○ Sling Site ○ Unimproved Landing Area 	<ul style="list-style-type: none">) Division Break ■ Incident Command Post ■ Drop Point ✕ Closure ■ Camp ■ Staging Area ■ Value at Risk 	<ul style="list-style-type: none"> ■ Other ■ Gate ■ Bridge ■ Water Development or Draft Site ■ Structure Wrap ■ Stream Crossing 	<ul style="list-style-type: none"> ■ Road Repair ■ Resource Location ■ Repair Point ■ Landing or Log Deck ■ Hazard Tree ■ Fence - Cut/ Damaged 	<ul style="list-style-type: none"> ■ Dozer Push ■ Culvert ■ Clean Up Area ■ Mobile Weather Unit ■ Repeater ■ Safety Zone ■ Hazard 	<ul style="list-style-type: none"> — Contained — Uncontained Fire Edge — Completed Burnout — Completed Dozer Line — Completed Fuel Break — Completed Hand Line 	<ul style="list-style-type: none"> — Completed Mixed Construction Line — Completed Road as Line — Planned Dozer Line — Access or Improved Road — Other — Repair Line 	<ul style="list-style-type: none"> — Road Repair — Retardant Drop — UAS Launch and Recovery Zone — Wildfire Daily Fire Perimeter — Cadore Timber Co — Franklin-Clarkson Timber Co LLC 	<ul style="list-style-type: none"> ■ Giustina (Winberry) ■ Oregon Dept of State Lands ■ Weyerhaeuser ■ Timber Holdings Inc
---	--	---	--	--	--	--	--	--	--	--	--



10/9/2023 2003
North American 1983 Datum, Lat/Long Grid
0 0.5 1 2 3 4 Miles

Repair