



Repair

Repair

Lookout

ORWIF-230327

10/12/2023

Acres from IR & GPS

25,754 acres at 10/04/2023 @ 1940

In Use - Fire Management	In Progress	Sling Site	Gate	Dozer Push	Completed Fuel Break	Road Repair	Giustina (Winberry)
Needs Assessment	Completed - Ready for Inspection	Unimproved Landing Area	Water Development or Draft Site	Culvert	Completed Hand Line	Retardant Drop	Oregon Dept of State Lands
Repair Needed	Completed - Inspected	Incident Command Post	Stream Crossing	Clean Up Area	Completed Mixed Construction Line	UAS Launch and Recovery Zone	Weyerhaeuser Timber Holdings Inc
Completed - Inspected	No Repair Needed	Drop Point	Road Repair	Mobile Weather Unit	Completed Road as Line	Contained	
Other - See Comments	Other - See Comments	Closure	Resource Location	Repeater	Planned Dozer Line	Wildfire Daily Fire Perimeter	
In Use - Fire Management	Airstrip or Airport	Camp	Dip Site	Safety Zone	Access or Improved Road	Cadore Timber Co	
Needs Assessment	Staging Area	Repair Point	Mobile Retardant Base	Hazard	Other	Franklin-Clarkson Timber Co LLC	
Repair Needed	Helispot	Value at Risk	Other	Completed Burnout	Repair Line		

10/12/2023 2045

North American 1983 Datum. LatLong Grid

0 0.25 0.5 1 1.5 2 Miles

Repair

Repair