



<h1>Repair</h1>	<h2>Repair</h2>		<h3>Lookout</h3>		<h3>ORWIF-230327</h3>		<h3>10/13/2023</h3>		<h3>Acres from IR & GPS</h3>		<h3>25,754 acres at 10/04/2023 @ 1940</h3>		
	<ul style="list-style-type: none"> ○ In Use - Fire Management ● Needs Assessment ● Repair Needed ● Completed - Inspected ● Other - See Comments ○ In Use - Fire Management ● Needs Assessment ● Repair Needed 	<ul style="list-style-type: none"> — In Progress — Completed - Ready for Inspection — Completed - Inspected — No Repair Needed — Other - See Comments ○ Airstrip or Airport ○ Dip Site ○ Mobile Retardant Base ● Helispot 	<ul style="list-style-type: none"> ○ Sling Site ○ Unimproved Landing Area ○ Incident Command Post ○ Drop Point ○ Closure ○ Camp ○ Staging Area ○ Value at Risk ○ Other 	<ul style="list-style-type: none"> ○ Gate ○ Bridge ○ Water Development or Draft Site ○ Stream Crossing ○ Road Repair ○ Resource Location ○ Repair Point ○ Landing or Log Deck ○ Hazard Tree 	<ul style="list-style-type: none"> ○ Dozer Push ○ Culvert ○ Clean Up Area ○ Mobile Weather Unit ○ Repeater ○ Safety Zone ○ Hazard ○ Completed Burnout ○ Completed Dozer Line 	<ul style="list-style-type: none"> — Completed Fuel Break — Completed Hand Line — Completed Mixed Construction Line — Completed Road as Line — Planned Dozer Line — Access or Improved Road — Other — Repair Line 	<ul style="list-style-type: none"> — Road Repair — Retardant Drop — UAS Launch and Recovery Zone — Contained — Wildfire Daily Fire Perimeter — Cadore Timber Co — Franklin-Clarkson Timber Co LLC 	<ul style="list-style-type: none"> — Giustina (Winberry) — Oregon Dept of State Lands — Weyerhaeuser Timber Holdings Inc 					
<p>Repair</p>										<p style="text-align: center;">10/13/2023 2019 North American 1983 Datum. LatLong Grid</p>		<p style="text-align: center;">Repair</p>	