

Line Type	Collector Name	Length	FootComments	Repair Status	Repair Comments	
100	Road as Completed Line	ortega	6195	171J Road	Repair Needed	
101	Completed Hand Line	Donley	9624	Proposed indirect	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
102	Road as Completed Line	Donley	23209	Proposed indirect	Repair Needed	
103	Completed Dozer Line	T Bruch Fobs	5071	This is a completed one blade wide dozer line there is no hand lane except at the very north end for the last six chains	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
104	Road as Completed Line	Hallam	19536	Road prepped by feller buncher and skidder	Repair Needed	A squad or crew will need to go back and low stump the area that has been cut by feller buncher landings on the edge of road will need to be rehabbed and seeded
106	Road as Completed Line	Megal DIV# & T Bruch FOBS	3326	Road has been prepped and line is complete	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
107	Completed Dozer Line	Megal DIV# & T Bruch FOBS; amendment Lake	12564	Part of West Sand Creek line, completed dozer line, line was felled with feller buncher prior to line installation, logs are stacked in small turns along the entire length of the dozer line	Repair Needed	
108	Completed Dozer Line	T. Stevens	2391	Needs saw prep	Repair Needed	
109	Completed Dozer Line	T. Stevens	2340		Repair Needed	
112	Access or Improved Road	Joe Murray	778		Repair Needed	
114	Completed Dozer Line	Lipp	2101		Repair Needed	Need to pull berms as necessary and put slash and logs back on Trail, roughen surfacing on slopes to prevent run off.
115	Completed Dozer Line	Hallam	5551	Line follows clear cut up top then dives into the north fork drainage. hand line continues on into drainage bottom	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
116	Completed Dozer Line	Lipp	3123		Repair Needed	
117	Road as Completed Line	Hallam	3993	Linking road to clear cuts	Repair Needed	
118	Completed Dozer Line	Lipp	1032	Completed dozer line	Repair Needed	pull beams and water bar as needed
119	Completed Hand Line	Greg Gilbert - TFLD	866		Repair Needed	
120	Completed Hand Line	Greg Gilbert - TFLD	138		Repair Needed	
121	Completed Dozer Line	Greg Gilbert - TFLD	530		Repair Needed	
124	Completed Dozer Line	Lipp	553		Repair Needed	pull berms and seed line
125	Completed Hand Line	Lipp	424		Repair Needed	pull beams
127	Completed Hand Line		840		Repair Needed	
128	Completed Hand Line	Joe Murray	2922	Eyebrow around CSU campus to the west, lined plumbed with laterals, sprinklers around upper student cabins and demo cabins	Repair Needed	
129	Road as Completed Line	Lipp	2891		Repair Needed	
130	Completed Hand Line	Lipp	296		Repair Needed	
131	Road as Completed Line	Lipp	12338		Repair Needed	
132	Road as Completed Line	T. Stevens	11331		Repair Needed	Wood chipper
134	Completed Dozer Line		3819		Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
135	Access or Improved Road	PHI Graham	11315	NFSR 259	Repair Needed	READ to assess
138	Completed Hand Line	PHI Graham	1866		Repair Needed	
140	Access or Improved Road	Daniel Perkins, CRWB Maine #1	14321	Access to remote structures	Repair Needed	
142	Road as Completed Line	Lipp	5728	Road around campground used as control line	Repair Needed	
143	Access or Improved Road		2475		Repair Needed	
144	Completed Dozer Line	T. Stevens	708		Repair Needed	Pull berms and add slash when available. Repair road point access to prevent OHV use by public. Add pitting to slopes.
145	Completed Dozer Line	T. Stevens	1072		Repair Needed	Mixture of trail and dozer push
146	Completed Dozer Line	T. Stevens	7521	Prepped on west side. 50 foot prep	Repair Needed	Mixture of trail and dozer line
147	Road as Completed Line	T. Stevens	2964	Secondary line	Repair Needed	
149	Completed Hand Line	T Bruch FOBS	2162	handline on 70% slopes, line has been brushed 50 feet wide and jack piles on the green side, water bars will be needed extensively on much of the line and brush pulled back on the line too	Repair Needed	water bars
150	Completed Dozer Line		1984		Repair Needed	
151	Completed Hand Line		578		Repair Needed	
152	Completed Dozer Line	T Bruch FOBS	5382	dozer line complete	Repair Needed	water bars , beams pulled back
153	Road as Completed Line	T. Stevens	3406	Mixture of road and drivable trail. Tight. T6 only. 50 foot prep on west side	Repair Needed	
154	Completed Dozer Line	T. Stevens	1919	Prep on west side 50 foot	Repair Needed	
155	Road as Completed Line	T. Stevens	1046	Old road bed opened by dozer	Repair Needed	
156	Completed Dozer Line	Daniel Perkins, CRWB Maine #1	517	Burned both sides	Repair Needed	
157	Completed Dozer Line	Daniel Perkins, CRWB Maine #1	588		Repair Needed	
158	Completed Hand Line	Daniel Perkins, CRWB Maine #1	244		Repair Needed	
159	Completed Dozer Line	Daniel Perkins, CRWB Maine #1	906		Repair Needed	
160	Completed Dozer Line	Daniel Perkins, CRWB Maine #1	454		Repair Needed	
161	Road as Completed Line	Daniel Perkins, CRWB Maine #1	372		Repair Needed	
162	Completed Dozer Line	Daniel Perkins	927		Repair Needed	
164	Road as Completed Line	Donley	10472	Mechanical work along road completed.	Repair Needed	
165	Road as Completed Line		2066		Repair Needed	
166	Completed Dozer Line		1260		Repair Needed	
167	Completed Dozer Line	Jake Wolff DIV F Trainee	8736	One blade wide dozer line berms will need to be pulled back water bars will need to be installed line will need to be closed and rehabbed	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
169	Road as Completed Line		3067		Repair Needed	
172	Completed Hand Line		5630	Change from planned to completed per branch.	Repair Needed	
173	Completed Dozer Line	TBruch FOBS	1245	Completed Dozer line ties into a large meadow at the terminus. Line is one chain wide was previously cut with a feller buncher And the logs were skidded to the landing located in the Clear cut	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
175	Completed Dozer Line		623		Repair Needed	
176	Completed Dozer Line	Hallam	3398	Linking road to clear cuts	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
177	Completed Dozer Line	Donley updated by FOBS Franks	1771	Completed. Update: not a dozer line, existing road, no evidence of dozer	Repair Needed	
178	Road as Completed Line	Hallam	3012	Linking road to clear cuts	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
179	Completed Dozer Line	Hallam	512	Linking road to clear cuts	Repair Needed	
180	Road as Completed Line		26142	Change from planned secondary to road as completed line per branch.	Repair Needed	consult with district road engineer.
181	Access or Improved Road	NBASFOR	1519	Improved Fs road 168 from Ben Delairor scout Ranch. About 1/4 mile private approved by ranch manager. Install water bars where needed.	Repair Needed	a few water bars are needed minor work here
182	Access or Improved Road	DIVS R: Turnbow	14409		Repair Needed	
183	Completed Dozer Line	DIVS R: Turnbow	10586		Repair Needed	
184	Completed Dozer Line	T Bruch Fobs	3124	this feature is a completed Dozer line that was placed on top of an old Road	Repair Needed	Minimal need here if any, the only possibility would be to pull the berms, there is a fair amount of wood/firewood on the side of the road
186	Access or Improved Road	Nbasford	5274	Improvement of road from ben Delatour scout camp access west on road 168.	Repair Needed	
187	Road as Completed Line		2306	20' cut on both sides of road	Repair Needed	
188	Completed Hand Line	TFLD Hatch	111		Repair Needed	
189	Completed Dozer Line		614		Repair Needed	
190	Road as Completed Line		25215	319 road prepped from Foxtro spike to H-93 but straight line NE was a mistake	Repair Needed	
191	Access or Improved Road	Bestwick	402		Repair Needed	
192	Access or Improved Road	Bestwick	777	River Ridge	Repair Needed	
193	Completed Dozer Line		1287	State Hatchery Dozer built line. Needs minor cleanup to hold and make drivable.	Repair Needed	
194	Access or Improved Road	Bestwick	231	Drive way	Repair Needed	
195	Road as Completed Line	David Wolf	1671	On two track road	Repair Needed	
196	Road as Completed Line	TFLD Sams	4794	Planned Handline off existing two track.	Repair Needed	
197	Access or Improved Road	Bestwick	1017		Repair Needed	
198	Road as Completed Line	DIV VV	901	Gravel road and driveway using a ridge line feature. Some brushing along road may be needed	Repair Needed	
199	Road as Completed Line	DIV VV	6335	Brushing on both sides is necessary. West of the road is light grassy fuels in Bobcat fire scar	Repair Needed	
200	Road as Completed Line	DIV VV	914	Brushing will need to be done on both sides.	Repair Needed	
201	Completed Dozer Line		3398		Repair Needed	Standard dozer line repair with excavator
202	Completed Dozer Line		3288		Repair Needed	Standard dozer line repair with excavator; extra care at gully crossing to repair intermittent channel
203	Completed Dozer Line		5183		Repair Needed	Standard dozer line repair with excavator; extra care at west end by Elkhorn Cr valley bottom with channel repair at creek.
204	Access or Improved Road	dotated by FOBS Franks	16968	Line is accessible by 4x4 high clearance from North end. Dozer line is blocked near the south end of line. Plumbed with 1.5 and 1". Every 100-200' is a rolled 1" hose with a nozzle.	Repair Needed	Old road bed?
205	Road as Completed Line	Bestwick	1097	Point protection for fish hatchery	Repair Needed	
206	Access or Improved Road	Bestwick	478	Access rd	Repair Needed	
207	Access or Improved Road	Bestwick	366	Big Bend CG	Repair Needed	
208	Access or Improved Road	Bestwick	737	Big Bend Ln	Repair Needed	
210	Road as Completed Line		32711		Repair Needed	
211	Completed Dozer Line	Nbasford	8269		Repair Needed	Check admin road status; Standard dozer line repair with excavator
212	Completed Dozer Line	C-68 / Donley	2873	UTV use only	Repair Needed	pull beams and install water bars, needs to be closed to future use
213	Completed Dozer Line	Columbine WFM	579		Repair Needed	
214	Completed Dozer Line	Columbine WFM	7336	Converted from proposed dozer line. Ties into campground logs slightly further west than shown on map	Completed - Ready for Inspection	pull beams and water bar as necessary use logs and slash to assist with the rehabilitation. Consult with Read to ensure there is enough slash to stop ohv access
215	Access or Improved Road	Mario Orozco	4346	4x4 vehicle access road to Crosier Mt. Trail, or also called old sawmill rd. This is also access to the single structure on top of this ridge.	Repair Needed	
216	Completed Dozer Line	J. Seales	3068	Needs prepped with feller buncher	Repair Needed	
217	Completed Dozer Line	David Veater	6972		Repair Needed	
218	Access or Improved Road	Shea Koch	3113	UTV / ATV / skidengine access line to 177 road	Repair Needed	
219	Completed Dozer Line	Skoch_nfc	2921	Dozer line to access fire	Repair Needed	
220	Completed Dozer Line	Skoch_nfc	1206	Control line	Repair Needed	
221	Completed Dozer Line	Skoch_nfc	1060	Dozer line as control line	Repair Needed	
222	Completed Dozer Line	Skoch_nfc	1084		Repair Needed	
223	Completed Dozer Line	Skoch_nfc	2039		Repair Needed	
224	Completed Dozer Line	Skoch_nfc	4985		Repair Needed	
225	Completed Dozer Line	Skoch_nfc	1295		Repair Needed	
226	Completed Hand Line	Columbine WFM/ update FOBS Franks	572	Short sections of hand line connected by beaver pond. Update: handline has filled in with water from beaver pond	Other - See Comments	Water has filled in handline from beaver pond
227	Road as Completed Line	Columbine WFM	958	Existing 2 track	Repair Needed	
228	Completed Dozer Line	Columbine WFM	124		Repair Needed	
229	Completed Dozer Line	Columbine WFM/ update FOBS Franks	5327	Plumbed with hose lay	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
230	Road as Completed Line	Columbine WFM	1279	Steep 2 track. No engine access. Utv only	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
231	Road as Completed Line	Skoch_nfc	12098	Cut by equipment	Repair Needed	
232	Completed Dozer Line	Skoch_nfc	2166	Dozer line with equipment cut	Repair Needed	
233	Completed Dozer Line	Skoch_nfc	8934	Dozer line with equipment cut	Repair Needed	
234	Access or Improved Road	Skoch_nfc	10067	Access for ATV/utv minimal scrape	Repair Needed	repeated traffic will require additional repair work.
235	Completed Hand Line	Yeoman	1111		Repair Needed	
236	Completed Dozer Line	Yeoman	1779	Dozer line along old road/previous dozer line	Repair Needed	
237	Completed Hand Line	Yeoman	698	Hand line with hose lay	Repair Needed	
238	Completed Dozer Line	Yeoman	1596	Light dozer push. Unsure of this was completed by fire operations or private landowners.	Repair Needed	
239	Completed Dozer Line	Yeoman	1700		Repair Needed	
240	Completed Hand Line	Yeoman	413		Repair Needed	
241	Completed Dozer Line	Yeoman	15963		Repair Needed	
242	Completed Hand Line	Yeoman	1758		Repair Needed	
243	Completed Dozer Line	Yeoman	1027		Repair Needed	
244	Completed Dozer Line	Yeoman	8526		Repair Needed	
245	Completed Dozer Line	Yeoman	258	Changed from hand to dozer. FOBS Franks 10/13/2020	Repair Needed	
246	Completed Dozer Line	Yeoman	164		Repair Needed	
247	Completed Dozer Line	Yeoman	2657	Changed hand line to dozer line. FOBS Franks 10/13/2020	Repair Needed	
248	Road as Completed Line	Lipp	2357	Proposed dozer line down a two track	Repair Needed	
249	Completed Dozer Line		6059		Completed - Ready for Inspection	
250	Completed Dozer Line	Jamie Geendes	1009	Dozer line off the 225	Repair Needed	
251	Completed Dozer Line		9594		Repair Needed	
252	Completed Dozer Line		7074		Repair Needed	
253	Completed Dozer Line	tobates_nfc, REAF	6127		Repair Needed	
254	Completed Dozer Line	tobates_nfc, REAF	4843	route was originally just un bladed access, till a dozer operator took it upon himself to "improve" the access by blading it. cut trees are off to side.	Repair Needed	surface will need pitting and organics pulled back in by excavator with a thumb.
255	Access or Improved Road	tobates_nfc, REAF	4469	517.8 used to access the fire edge via extension. dozer has subsequently bladed road.	Repair Needed	only tracked in on road rd bladed, consult district engineer for specs.
256	Access or Improved Road	tobates_nfc, REAF	13756		Repair Needed	surface rock is largely pushed off most of the prim. Washboards and ruts developing.
257	Road as Completed Line		4603	Prepped south of road. **needs to be chipped	Repair Needed	
258	Road as Completed Line	Jamie Geendes TFLD	6645	171L UTV only	Repair Needed	
259	Completed Hand Line	Jamie Geendes TFLD	786		Repair Needed	
260	Completed Dozer Line	Jamie Geendes TFLD	1871		Repair Needed	
261	Completed Dozer Line	Jamie Geendes TFLD	1073		Repair Needed	
262	Completed Dozer Line	Daniel Perkins, FOBS	1290	30' mechanical thinning both sides	Repair Needed	
263	Completed Dozer Line	Daniel Perkins, FOBS	1354	1 chain of mechanical thinning on black side	Repair Needed	
264	Completed Dozer Line	Daniel Perkins, FOBS	656	access line, not fireline	Repair Needed	
265	Completed Dozer Line	Daniel Perkins, FOBS	751	access line, not fireline	Repair Needed	
266	Access or Improved Road	Daniel Perkins, FOBS	1356	No prep work to road segment	Repair Needed	
267	Road as Completed Line	Daniel Perkins, FOBS	1188	brush has been chipped	Repair Needed	
268	Access or Improved Road	Daniel Perkins, FOBS	4117	brush roadside needs chipping	Repair Needed	
269	Road as Completed Line	Daniel Perkins, FOBS	8767		Repair Needed	
270	Road as Completed Line	Daniel Perkins, FOBS	1334		Repair Needed	
271	Road as Completed Line	Daniel Perkins, FOBS	15466	Road recently improved by grader. Not sure if work was fire related.	Repair Needed	
272	Completed Dozer Line		2426		Repair Needed	
273	Completed Dozer Line		6437		Repair Needed	
274	Completed Dozer Line	T Bruch FOBS	1642	Completed Dozer line	Repair Needed	Retain line for future control feature; close access to public; stabilize slopes with pitting
275	Road as Completed Line	T Bruch FOBS	866	Ties into meadows on both ends	Repair Needed	
276	Completed Dozer Line	tobates_nfc, REAF	1232	Road is used here as a line that ties into the dozer line area was masticated	Unknown	No repair needed on old Road
277	Completed Dozer Line	tobates_nfc, REAF	226	initial direct line.	Repair Needed	steep slopes, will require excavator with thumb to pit surface, and pull slash and organics back in, once fire is controlled.
278	Completed Dozer Line	tobates_nfc, REAF	2441	dozer line down to flowing trib or Roaring creek. dozer tracked through creek. see photo point.	Repair Needed	see fish bio and hydro for repair standards. line continuous uphill.
279	Completed Dozer Line	tobates_nfc, REAF	2047	direct line. walked actual completed line. stopped at a seep incursion.	Repair Needed	standard dozer
280	Completed Dozer Line	tobates_nfc, REAF	368	stopped to collect point	Repair Needed	standard dozer repair
281	Completed Dozer Line	tobates_nfc, REAF	374	ended at stream crossing	Repair Needed	standard
282	Completed Dozer Line	tobates_nfc, REAF	470	spur	Repair Needed	
283	Completed Dozer Line	tobates_nfc, REAF	6919	top part is indirect, lower down is direct. actual line walked.	Repair Needed	standard dozer repair on steep bladed sections. flat areas with no blading can be left to natural rehab.
284	Completed Dozer Line	tobates_nfc	3409		Repair Needed	standard dozer repair
285	Completed Dozer Line	Tobates_nfc, REAF	1978	Line down from helispot circling spot then connecting to completed dozer line.	Repair Needed	Standard dozer repair.
286	Road as Completed Line	Daniel Perkins, FOBS	1542		Repair Needed	
287	Completed Dozer Line	Daniel Perkins, FOBS	3453		Repair Needed	
288	Completed Dozer Line	TFLD Jamie Geendes	1510		Repair Needed	pull beams and install water bars
289	Completed Dozer Line	TFLD Geendes	213		Repair Needed	
290	Completed Hand Line	TFLD Geendes	211		Repair Needed	
291	Completed Dozer Line	TFLD Geendes	2863		Repair Needed	pull beams and water bar as needed
292	Road as Completed Line	Daniel Perkins, FOBS	78610	30-60' brushed and limbed on black side	Repair Needed	
293	Completed Dozer Line		1482		Repair Needed	Improved road, not dozerline. Leave open and ensure proper drainage
294	Completed Dozer Line		801		Completed - Inspected	
295	Completed Dozer Line		538		Completed - Inspected	
296	Completed Dozer Line		941		Completed - Inspected	
297	Completed Dozer Line		1352		Completed - Inspected	
298	Completed Dozer Line		261		Completed - Inspected	
299	Completed Dozer Line	TFLD Geendes	1942		Repair Needed	Pull beams, water bar, place slash and logback on Trail to help with rehab
300	Completed Hand Line	TFLD Geendes	224		Repair Needed	
301	Completed Hand Line	TFLD Geendes	175		Repair Needed	
302	Completed Hand Line	TFLD Geendes	209		Repair Needed	
304	Completed Dozer Line	Daniel Perkins, FOBS	360		Repair Needed	
305	Completed Dozer Line	Daniel Perkins, FOBS	1256		Repair Needed	
306	Completed Dozer Line	Daniel Perkins, FOBS	2583		Repair Needed	
307	Completed Dozer Line	T bruch Fobs	604		Repair Needed	1 blade wide lone in open area water bar's needed
308	Completed Dozer Line	READ Laura Aker	335		Completed - Inspected	Pull back berm and recontour, pull back material
309	Completed Hand Line	TFLD Geendes	401		Repair Needed	
310	Completed Hand Line	TFLD Geendes				