	belFC Line Type Collector Name	-	eetComments	Repair Status
536 102	 Road as Completed Line ortega Completed Hand Line Donley Road as Completed Line Donley Completed Dozer Line T Bruch Fobs 	6195 7468 23209 5071	171J Road Proposed indirect Proposed indirect This is a completed one blade wide dozer line. Line crosses private land at North end. Wet meadow repair necessary on private.	Repair Needed Repair Needed Repair Needed Repair Needed
104 537	 Road as Completed Line Hallam Road as Completed Line Megel DIVF, T bruch FOBS, READ Carroll Completed Dozer Line Megel DIVF, T Bruch FOBS; amnd Laker, READ Carro 	10936 3278	Road prepped by feller buncher and skidder Road has been prepped and line is complete Part of West Sand Creek line, completed dozer line, line was felled with feller buncher prior to line installation, logs are stacked in small turns along the entire length of the dozer line	Repair Needed Repair Needed Repair Needed Repair Needed
109	 Completed Dozer Line T. Stevens Completed Dozer Line T. Stevens Access or Improved RoadJoe Murray 	2391 2340 778	Needs saw prep	Repair Needed Repair Needed Repair Needed
115 116	 4 Completed Dozer Line Lipp 5 Completed Dozer Line Hallam 6 Completed Dozer Line 	2078 5551 3123	Line follows clear cut up top then dives into the north fork drainage. hand line continues on into drainage bottom	Repair Needed Repair Needed Repair Needed
118 119	 7 Road as Completed Line Hallam 8 Completed Dozer Line Lipp 9 Completed Hand Line Greg Gilbert - TFLD 9 Completed Hand Line Greg Gilbert - TFLD 	3993 1032 866 128	Linking road to clear cuts Completed dozer line	Repair Needed Repair Needed Repair Needed
121 124	 Completed Hand Line Greg Gilbert - TFLD Completed Dozer Line Greg Gilbert - TFLD Completed Dozer Line Lipp Completed Hand Line Lipp 	138 530 553 424		Repair Needed Repair Needed Repair Needed Repair Needed
127 128	7 Completed Hand Line 8 Completed Hand Line 9 Road as Completed Line Lipp	840 2923 2891	Eyebrow around CSU campus to the west, lined plumbed with laterals, sprinklers around upper student cabins and demo cabins	Repair Needed Repair Needed Repair Needed Repair Needed
13:	Completed Hand Line Lipp Road as Completed Line Lipp Road as Completed Line T. Stevens	296 12338 11331		Repair Needed Repair Needed Repair Needed
135 136	 Completed Dozer Line Access or Improved RoadPhil Graham Completed Hand Line Phil Graham 	3821 11320 1867	NFSR 259	Repair Needed Repair Needed Repair Needed
142 143	 Access or Improved RoadDaniel Perkins, CRWB Maine #1 Road as Completed Line Lipp Access or Improved Road Completed Line Traction 	14321 5728 2475	Access to remote structures Road around campground used as control line	Repair Needed Repair Needed Repair Needed
145 146	 Completed Dozer Line T. Stevens Completed Dozer Line T. Stevens Completed Dozer Line T. Stevens Road as Completed Line T. Stevens 	708 1072 7521 2964	Dozer line just west of Elkhorn Creek TH Dozer line on non-system trail? Prepped on west side. 50 foot prep Secondary line	Repair Needed Repair Needed Repair Needed Repair Needed
149 150	 Completed Hand Line T Bruch FOBS Completed Dozer Line Completed Hand Line 	2162 1984 578	handline on 70% slopes. line has been brushed 50 feet wide and jack piles on the green side, water bars will be needed extensively on much of the line and brush pulled back on the line too	Repair Needed Repair Needed Repair Needed
152 153	2 Completed Dozer Line T Bruch FOBS 3 Road as Completed Line T. Stevens 4 Completed Dozer Line T. Stevens	5382 3406 1919	dozer line complete Mixture of road and drivable trail. Tight. T6 only. 50 foot prep on west side Prep on west side 50 foot	Repair Needed Repair Needed Repair Needed
156	 Road as Completed Line T. Stevens Completed Dozer Line Daniel Perkins, CRWB Maine #1 Completed Dozer Line Daniel Perkins, CRWB Maine #1 	1046 518 558	Old road bed opened by dozer Burned both sides	Repair Needed Repair Needed Repair Needed
159 160	 Completed Hand Line Daniel Perkins, CRWB Maine #1 Completed Dozer Line Daniel Perkins, CRWB Maine #1 Completed Dozer Line Daniel Perkins, CRWB Maine #1 	244 906 454		Repair Needed Repair Needed Repair Needed
162 164	 Road as Completed Line Daniel Perkins, CRWB Maine #1 Completed Dozer Line Daniel Perkins Road as Completed Line Donley 	372 927 10472	Mechanical work along road completed.	Repair Needed Repair Needed Repair Needed
166 167	 Road as Completed Line Completed Dozer Line Completed Dozer Line Jake Wolff DIV F Trainee, READ Carroll 	2066 1260 8736	One blade wide dozer line berms will need to be pulled back in and line will need to be closed and rehabbed	Repair Needed Repair Needed Repair Needed
169 172	 Road as Completed Line Jake Wolff DIV F Trainee, READ Carroll Road as Completed Line repairs READ Carroll Completed Hand Line Completed Descention Thrush EORS DEAD Carroll 	6655 3067 5630	A feller Buncher was used to clear this road approximately a chain wide. Change from planned to completed per branch.	Repair Needed Repair Needed Repair Needed
175 176	 Completed Dozer Line TBruch FOBS, READ Carroll Completed Dozer Line Completed Dozer Line Hallam Read as Completed Line Depley undeted by EOBS Franks 	1245 623 3398	Completed Dozer line ties into a large meadow at the terminus. Line Is one chain wide was previously cut with a feller buncher And the logs were skidded to the landing located in the Clear cut Linking road to clear cuts	Repair Needed Repair Needed Repair Needed
178 179	 Road as Completed Line Donley updated by FOBS Franks Road as Completed Line Hallam, READ Carroll Completed Dozer Line Hallam Road as Completed Line 	1771 3012 512 26142	Completed. Update: not a dozer line, existing road, no evidence of dozer Linking road to clear cuts Linking road to clear cuts Change from planned secondary to road as completed line per branch.	Repair Needed Repair Needed Repair Needed Repair Needed
181 183	 Road as Completed Line Access or Improved RoadNBASFORD Completed Dozer Line DIVS R- Turnbow Completed Dozer Line T Bruch Fobs, READ Carroll 	26142 1519 10586 3076	Change from planned secondary to road as completed line per branch. Improved Fs road 168 from Ben Delaroir scout Ranch. About 1/4 mile private approved by ranch manager. Install water bars where needed. this feature is a completed Dozer line that was placed on top of an admin Road	Repair Needed Repair Needed Repair Needed Repair Needed
187 188	 Completed Dozer Line T Bruch Fobs, READ Carroll Road as Completed Line Completed Hand Line TFLD Hatch Completed Dozer Line 	3076 2306 111 614	this feature is a completed Dozer line that was placed on top of an admin Road 20' cut on both sides of road	Repair Needed Repair Needed Repair Needed Repair Needed
190	 Completed Dozer Line Road as Completed Line Completed Hand Line Road as Completed Line David Wolf 	25215 480 1671	319 road prepped from Foxtrot spike to H-93 but straight line NE was a mistake Handline to river. Follows old 2 track. On two track road	Repair Needed Repair Needed Repair Needed Repair Needed
196 198		4796 901 6338	Planned Handline off existing two track. Gravel road and driveway using a ridge line feature. Some brushing along road may be needed Brushing on both sides is necessary. West of the road is light grassy fuels in Bobcat fire scar	Repair Needed Repair Needed Repair Needed Repair Needed
200 201	 Road as Completed Line DIV VV Road as Completed Line DIV VV Completed Dozer Line Completed Dozer Line 	914 3400 3289	Brushing will need to be done on both sides.	Repair Needed Repair Needed Repair Needed
204	 Completed Dozer Line Access or Improved RoadUpdated FOBS Franks, Repair update by READ Carro Road as Completed Line Bostwick 	5185 16968 1097	Line is accessible by 4x4 high clearance from North end. Dozer line is blocked near the south end of line. Plumbed with 1.5 and 1". Every 100-200' is a rolled 1" hose with a nozzle. Point protection for fish hatchery	Repair Needed Repair Needed Repair Needed
21	 Road as Completed Line Completed Dozer Line Nbasford Completed Dozer Line C-68 / Donley 	32711 8272 2873	UTV use only	Repair Needed Repair Needed Repair Needed
214 215	 Completed Dozer Line Columbine WFM Completed Dozer Line Columbine WFM Access or Improved RoadMario Orozco 	579 7336 4348	Converted from proposed dozer line. Ties into campground loops slightly further west than shown on map 4x4 vehicle access road to Crosier Mnt. Trail, or also called old sawmill road. This is also access to the single structure on top of this ridge.	Repair Needed Completed - Ready for Inspection Repair Needed
217 218	 Completed Dozer Line J. Searles Completed Dozer Line David Veater Access or Improved RoadShea Koch 	3069 6974 3113	Needs prepped with feller buncher UTV / ATV / skidengine access line to 177 road	Repair Needed Repair Needed Repair Needed
220 221	O Completed Dozer Line Skoch_nifc O Completed Dozer Line Skoch_nifc 1 Completed Dozer Line Skoch_nifc	2921 1206 1060	Dozer line to access fire Control line Dozer line as control line	Repair Needed Repair Needed Repair Needed
223 224	2 Completed Dozer Line Skoch_nifc 3 Completed Dozer Line Skoch_nifc 4 Completed Dozer Line Skoch_nifc	1084 2039 4985		Repair Needed Repair Needed Repair Needed
226 227	 5 Completed Dozer Line Skoch_nifc 5 Completed Hand Line Columbine WFM/ update FOBS Franks 7 Road as Completed Line Columbine WFM 8 Completed Dozer Line Columbine WFM 	1295 572 958 1324	Short sections of hand line connected by beaver pond. Update: handline has filled in with water from beaver pond Existing 2 track	Repair Needed Other - See Comments Repair Needed Repair Needed
229 231	 Completed Dozer Line Columbine WFM/ update FOBS Franks Road as Completed Line Skoch_nifc Completed Dozer Line Skoch nifc 	5327 12098 2166	Plumbed with hose lay Cut by equipment Dozer line with equipment cut	Repair Needed Repair Needed Repair Needed
233 234	3 Completed Dozer Line Skoch_nifc 4 Access or Improved RoadSkoch_nifc 5 Completed Hand Line Yeoman	8934 10067 1111	Dozer line with equipment cut Access for ATV/Utv minimal scrape	Repair Needed Repair Needed Repair Needed
236 237	5 Completed Dozer Line Yeoman 7 Completed Hand Line Yeoman 8 Completed Dozer Line Yeoman	1779 698 1596	Dozer line along old road/previous dozer line Hand line with hose lay Light dozer push. Unsure of this was completed by fire operations or private landowners.	Repair Needed Repair Needed Repair Needed
240	 Completed Dozer Line Yeoman Completed Hand Line Yeoman Completed Dozer Line Yeoman 	1700 413 1963		Repair Needed Repair Needed Repair Needed
243	2Completed Hand LineYeoman3Completed Dozer LineYeoman4Completed Dozer LineYeoman	1758 1027 8526		Repair Needed Repair Needed Repair Needed
246	 5 Completed Dozer Line Yeoman 6 Completed Dozer Line Yeoman 7 Completed Dozer Line Yeoman 	258 164 267	Changed from hand to dozer. FOBS Franks 10/13/2020 Changed hand line to dozer line. FOBS Franks 10/13/2020	Repair Needed Repair Needed Repair Needed
249 250	 Road as Completed Line Lipp Completed Dozer Line Completed Dozer Line Jamie Geerdes 	2357 5032 1009	Proposed dozer line down a two track Dozer line off the 225	Repair Needed Completed - Ready for Inspection Repair Needed
252 253	 Completed Dozer Line Completed Dozer Line Completed Dozer Line tobates_nifc, REAF Completed Dozer Line tobates_nifc_REAF 	9594 7074 6127 4942		Repair Needed Repair Needed Repair Needed
255 256	 Completed Dozer Line tobates_nifc, REAF Access or Improved Roadtobates_nifc, REAF Access or Improved Roadtobates_nifc, REAF Road as Completed Line 	4843 4469 13756 5231	route was originally just un bladed access, till a dozer operator took it upon himself to "improve" the access by blading it. cut trees are off to side. 517.B used to access the fire edge via extension. dozer has subsequently bladed road. Prepped south of road. **needs to be chipped	Repair Needed Repair Needed Repair Needed Repair Needed
258 259	 Road as Completed Line Road as Completed Line Jamie Geerdes TFLD Completed Hand Line Jamie Geerdes TFLD Completed Dozer Line Jamie Geerdes TFLD 	5231 6645 786 1871	171L UTV only	Repair Needed Repair Needed Repair Needed Repair Needed
26: 262	1Completed Dozer LineJamie Geerdes TFLD2Completed Dozer LineDaniel Perkins, FOBSt3Completed Dozer LineDaniel Perkins, FOBSt	1073 1290 1354	30' mechanical thinning both sides 1 chain of mechanical thinning on black side	Repair Needed Repair Needed Repair Needed
264 265	 Completed Dozer Line Daniel Perkins, FOBSt Completed Dozer Line Daniel Perkins, FOBSt Access or Improved RoadDaniel Perkins, FOBSt 	656 751 1356	access line, not fireline access line, not fireline No prep work to road segment	Repair Needed Repair Needed Repair Needed
269 27(27:	 Road as Completed Line Daniel Perkins, FOBSt Road as Completed Line Daniel Perkins, FOBSt Road as Completed Line Daniel Perkins, FOBSt 	8771 1334 15472	Road recently improved by grader. Not sure if work was fire related.	Repair Needed Repair Needed Repair Needed
273	 Completed Dozer Line Completed Dozer Line Completed Dozer Line T Bruch FOBS, READ Carroll 	2426 6437 1642	Completed Dozer line Ties into meadows on both ends	Repair Needed Repair Needed Repair Needed
276	 Road as Completed Line T Bruch FOBS, READ Carroll Completed Dozer Line tobates_nifc, REAF Completed Dozer Line tobates_nifc, REAF 	866 1232 226	Ties into meadows on both ends Road is used here as a line that ties into the dozer line area was masticated initial direct line. dozer line down to flowing trib or Roaring creek. dozer tracked through creek. see photo point.	Repair Needed Repair Needed Repair Needed
278 279	Completed Dozer Line tobates_nifc, REAF Completed Dozer Line tobates_nifc, REAF Completed Dozer Line tobates_nifc, REAF Completed Dozer Line tobates_nifc, REAF	226 2441 2047 368	dozer line down to nowing trib or Roaring creek. dozer tracked through creek. see photo point. direct line. walked actual completed line. stopped at a seep incursion. stopped to collect point	Repair Needed Repair Needed Repair Needed Repair Needed
28: 282	Completed Dozer Line tobates_nifc, REAF Completed Dozer Line tobates_nifc, REAF Completed Dozer Line tobates_nifc, REAF	374 470 6919	ended at stream crossing spur top part is indirect, lower down is direct. actual line walked.	Repair Needed Repair Needed Repair Needed Repair Needed
284 285 287	 Completed Dozer Line tobates_nifc Completed Dozer Line Tobates_nifc, REAF Completed Dozer Line Daniel Perkins, FOBSt, READ Carroll 	3409 1978 3453	Line down from helispot circling spot then connecting to completed dozer line. Dozer line on top of handline.	Repair Needed Repair Needed Repair Needed
289 291	 Completed Dozer Line TFLD Jamie Geerdes Completed Dozer Line TFLD Geerdes Completed Dozer Line TFLD Geerdes 	1457 213 2855		Repair Needed Repair Needed Repair Needed
293 294	 2 Road as Completed Line Daniel Perkins, FOBSt 3 Completed Dozer Line 4 Completed Dozer Line 5 Completed Dozer Line 	78640 1482 801	30-60' brushed and limbed on black side	Repair Needed Repair Needed Completed - Inspected
296 297	 Completed Dozer Line Completed Dozer Line Completed Dozer Line 	538 941 1352		Completed - Inspected Completed - Inspected Completed - Inspected
299 300	 Completed Dozer Line Completed Dozer Line TFLD Geerdes Completed Hand Line TFLD Geerdes Completed Hand Line TFLD Geerdes 	261 1942 234 175		Completed - Inspected Repair Needed Repair Needed Repair Needed
302 304	 Completed Hand Line TFLD Geerdes Completed Hand Line TFLD Geerdes Completed Dozer Line Daniel Perkins, FOBSt Completed Dozer Line Daniel Perkins, FOBSt 	175 209 360 1256		Repair Needed Repair Needed Repair Needed Repair Needed
306 307	5 Completed Dozer Line Daniel Perkins, FOBSt 5 Completed Dozer Line Daniel Perkins, FOBSt 7 Completed Dozer Line T bruch Fobs, READ Carroll 8 Completed Dozer Line READ Laura Aker	2583 624	Process and remove timber material. Leave slash for rehab. Dozer line in cut timber sale unit	Repair Needed Repair Needed Repair Needed Completed - Inspected
312 313	 Completed Dozer Line READ Laura Aker Completed Dozer Line T Bruch Fobs Completed Hand Line T bruch Fobs Completed Dozer Line T bruch Fobs 	335 143 216 254		Completed - Inspected Repair Needed Repair Needed Repair Needed
315 316	 Completed Dozer Line T bruch Fobs Completed Hand Line T Bruch Fobs Completed Hand Line T bruch Fobs Road as Completed Line T Bruch Fobs 	254 898 385 7839	517.0 road Has been treated on both sides with a feller Buncher and possibly a masticator most piles have been chipped line is approximately 125 feet wide. Prep on the road stops here.	Repair Needed Repair Needed Repair Needed In Progress
318	Access or Improved Road Completed Dozer Line Access or Improved Road	6592 1609 921	Improved Road Submitted from READ Avenza Submitted from READ Avenza Wided Road Submitted from READ Avenza	Completed - Ready for Inspection Completed - Ready for Inspection Repair Needed
320 321	 Completed Dozer Line Completed Dozer Line Completed Dozer Line Daniel Perkins, FOBSt/update FOBS Franks 	388 6441 146	Submitted from READ Avenza Submitted from READ Avenza likely done by landowner due to appearance: update, land owner stated it was them who put dozer line in	Completed - Inspected Completed - Ready for Inspection Repair Needed
323 325	 Completed Dozer Line Completed Dozer Line Daniel Perkins, FOBSt/ update FOBS Franks Daniel Perkins, FOBSt/ update FOBS Franks Daniel Perkins, FOBSt Daniel Perkins, FOBSt 	412 328 388	likely done by landowner due to appearance: update, land owner stated it was not them who put dozer line in likely done by landowner due to appearance. Update, land owner stated it was not them that put in dozer line	Repair Needed Repair Needed Repair Needed
327 328	 Completed Dozer Line Daniel Perkins, FOBSt 	819 1553 5241		Repair Needed Repair Needed Repair Needed
330 331	 Completed Dozer Line Daniel Perkins, FOBSt 	993 1463 780 2004		Repair Needed Repair Needed Repair Needed
333 334	 Completed Dozer Line Daniel Perkins, FOBSt 	2004 968 466 504	possibility done by landowner due to appearance possibility done by landowner due to appearance	Repair Needed Repair Needed Repair Needed Repair Needed
336 337	 Completed Dozer Line Daniel Perkins, FOBSt Completed Hand Line Daniel Perkins, FOBSt Completed Dozer Line Daniel Perkins, FOBSt Completed Dozer Line Daniel Perkins, FOBSt 	504 589 224 756		Repair Needed Repair Needed Repair Needed Repair Needed
339 340	 Completed Dozer Line Daniel Perkins, FOBSt Completed Dozer Line Daniel Perkins, FOBSt Completed Dozer Line Daniel Perkins, FOBSt Completed Dozer Line T Bruch Fobs 	2165 1534 263		Repair Needed Repair Needed Repair Needed Repair Needed
342 343	2 Completed Dozer Line T Bruch Fobs 3 Completed Dozer Line T Bruch Fobs 4 Completed Dozer Line T Bruch Fobs	416 1156 2451	2 blades wide	Repair Needed Repair Needed Repair Needed
345 346	 Completed Dozer Line T Bruch Fobs Completed Dozer Line T Bruch Fobs Completed Dozer Line T Bruch Fobs 	1941 6086 1568	double blade dozer lone	Repair Needed Repair Needed Repair Needed