LabelFC Line Type Collector Name L	ength FeetComments	Repair Status
100 Road as Completed Line ortega 6 536 Completed Hand Line Donley 7	195 171J Road 468 Proposed indirect	Repair Needed Repair Needed
103 Completed Dozer Line T Bruch Fobs 5	Proposed indirect  This is a completed one blade wide dozer line. Line crosses private land at North end. Wet meadow repair necessary on private.  Road prepped by feller buncher and skidder	Repair Needed Repair Needed Repair Needed
107 Completed Dozer Line Megel DIVF, T Bruch FOBS; amnd Laker, READ Carroll1	278 Road has been prepped and line is complete 2564 Part of West Sand Creek line, completed dozer line, line was felled with feller buncher prior to line installation, logs are stacked in small turns along the entire length of the dozer line 391 Needs saw prep	Repair Needed Repair Needed Repair Needed
109 Completed Dozer Line T. Stevens 2 112 Access or Improved RoadJoe Murray 7	340 78	Repair Needed Repair Needed
115 Completed Dozer Line Hallam 5	078 551 Line follows clear cut up top then dives into the north fork drainage. hand line continues on into drainage bottom 123	Repair Needed Repair Needed Repair Needed
118 Completed Dozer Line Lipp 1	Linking road to clear cuts  Completed dozer line  66	Repair Needed Repair Needed Repair Needed
120Completed Hand LineGreg Gilbert - TFLD1121Completed Dozer LineGreg Gilbert - TFLD5	38 30	Repair Needed Repair Needed
125 Completed Hand Line Lipp 4	53 24 40	Repair Needed Repair Needed Repair Needed
128 Completed Hand Line Joe Murray 2 129 Road as Completed Line Lipp 2	Eyebrow around CSU campus to the west, lined plumbed with laterals, sprinklers around upper student cabins and demo cabins 891	Repair Needed Repair Needed
131 Road as Completed Line Lipp 1	96 2338 1331	Repair Needed Repair Needed Repair Needed
135 Access or Improved RoadPhil Graham 1	821 1320 NFSR 259 867	Repair Needed Repair Needed Repair Needed
140 Access or Improved RoadDaniel Perkins, CRWB Maine #1 142 Road as Completed Line Lipp 5	Access to remote structures Road around campground used as control line	Repair Needed Repair Needed Repair Needed
144 Completed Dozer Line T. Stevens 7	475 08 Dozer line just west of Elkhorn Creek TH 072 Dozer line on non-system trail?	Repair Needed Repair Needed Repair Needed
146 Completed Dozer Line T. Stevens 7 147 Road as Completed Line T. Stevens 2	Prepped on west side. 50 foot prep Secondary line	Repair Needed Repair Needed
150 Completed Dozer Line 1	handline on 70% slopes. line has been brushed 50 feet wide and jack piles on the green side, water bars will be needed extensively on much of the line and brush pulled back on the line too 984 78	Repair Needed Repair Needed Repair Needed
153 Road as Completed Line T. Stevens 3	dozer line complete  406 Mixture of road and drivable trail. Tight. T6 only. 50 foot prep on west side  Prep on west side 50 foot	Repair Needed Repair Needed Repair Needed
155 Road as Completed Line T. Stevens 1 156 Completed Dozer Line Daniel Perkins, CRWB Maine #1 5	Old road bed opened by dozer  Burned both sides	Repair Needed Repair Needed
158 Completed Hand Line Daniel Perkins, CRWB Maine #1 2	58 44 06	Repair Needed Repair Needed Repair Needed
161 Road as Completed Line Daniel Perkins, CRWB Maine #1 3	54 72 27	Repair Needed Repair Needed Repair Needed
164 Road as Completed Line Donley 1 165 Road as Completed Line 2	Mechanical work along road completed.  0472 Mechanical work along road completed.	Repair Needed Repair Needed Repair Needed
167 Completed Dozer Line Jake Wolff DIV F Trainee, READ Carroll 8	260 736 One blade wide dozer line berms will need to be pulled back in and line will need to be closed and rehabbed 655 A feller Buncher was used to clear this road approximately a chain wide.	Repair Needed Repair Needed Repair Needed
169 Road as Completed Line repairs READ Carroll  172 Completed Hand Line  5	067 630 Change from planned to completed per branch.	Repair Needed Repair Needed
175 Completed Dozer Line 6	Completed Dozer line ties into a large meadow at the terminus. Line Is one chain wide was previously cut with a feller buncher And the logs were skidded to the landing located in the Clear cut  23  298 Linking road to clear cuts	Repair Needed Repair Needed Repair Needed
	Completed. Update: not a dozer line, existing road, no evidence of dozer  Linking road to clear cuts  Linking road to clear cuts	Repair Needed Repair Needed Repair Needed
180 Road as Completed Line 2 181 Access or Improved RoadNBASFORD 1	Change from planned secondary to road as completed line per branch.  Improved Fs road 168 from Ben Delaroir scout Ranch. About 1/4 mile private approved by ranch manager. Install water bars where needed.	Repair Needed Repair Needed
184 Completed Dozer Line T Bruch Fobs, READ Carroll 3	0586 076 this feature is a completed Dozer line that was placed on top of an admin Road 306 20' cut on both sides of road	Repair Needed Repair Needed Repair Needed
188 Completed Hand Line TFLD Hatch 1 189 Completed Dozer Line 6	11 14	Repair Needed Repair Needed
Completed Hand Line 4 195 Road as Completed Line David Wolf 1	319 road prepped from Foxtrot spike to H-93 but straight line NE was a mistake Handline to river. Follows old 2 track. On two track road	Repair Needed Repair Needed In Progress
198 Road as Completed Line DIV VV 9	Planned Handline off existing two track.  Gravel road and driveway using a ridge line feature. Some brushing along road may be needed  Brushing on both sides is necessary. West of the road is light grassy fuels in Bobcat fire scar	In Progress Repair Needed Repair Needed
200 Road as Completed Line DIV VV 9 201 Completed Dozer Line 3	Brushing will need to be done on both sides. 400	Repair Needed Repair Needed Repair Needed
203 Completed Dozer Line 5	289 185 6968 Line is accessible by 4x4 high clearance from North end. Dozer line is blocked near the south end of line. Plumbed with 1.5 and 1". Every 100-200' is a rolled 1" hose with a nozzle.	Repair Needed Repair Needed Repair Needed
205 Road as Completed Line Bostwick 1 210 Road as Completed Line 3	Point protection for fish hatchery 2711	Repair Needed Repair Needed
212 Completed Dozer Line C-68 / Donley 2	272 873 UTV use only 79	Repair Needed Repair Needed Repair Needed
214Completed Dozer LineColumbine WFM7215Access or Improved RoadMario Orozco4	Converted from proposed dozer line. Ties into campground loops slightly further west than shown on map  4x4 vehicle access road to Crosier Mnt. Trail, or also called old sawmill road. This is also access to the single structure on top of this ridge.	Completed - Ready for Inspection Repair Needed Repair Needed
217Completed Dozer LineDavid Veater6218Access or Improved RoadShea Koch3	Needs prepped with feller buncher  974  113 UTV / ATV / skidengine access line to 177 road	Repair Needed Repair Needed Repair Needed
220 Completed Dozer Line Skoch_nifc 1	Dozer line to access fire  Control line  Dozer line as control line	Repair Needed Repair Needed Repair Needed
222 Completed Dozer LineSkoch_nifc1223 Completed Dozer LineSkoch_nifc2	084 039	Repair Needed Repair Needed
225 Completed Dozer Line Skoch_nifc 1	985 295 72 Short sections of hand line connected by beaver pond. Update: handline has filled in with water from beaver pond	Repair Needed Repair Needed Other - See Comments
228 Completed Dozer Line Columbine WFM 1	Existing 2 track  324  327 Plumbed with hose lay	Repair Needed Repair Needed Repair Needed
231 Road as Completed Line Skoch_nifc 1 232 Completed Dozer Line Skoch_nifc 2	2098 Cut by equipment 166 Dozer line with equipment cut	Repair Needed Repair Needed
234 Access or Improved RoadSkoch_nifc 1	Dozer line with equipment cut  One of the control o	Repair Needed Repair Needed Repair Needed
237 Completed Hand Line Yeoman 6	Dozer line along old road/previous dozer line  Hand line with hose lay  Light dozer push. Unsure of this was completed by fire operations or private landowners.	Repair Needed Repair Needed Repair Needed
239 Completed Dozer Line Yeoman 1 240 Completed Hand Line Yeoman 4	700 13	Repair Needed Repair Needed
242 Completed Hand Line Yeoman 1	963 758 027	Repair Needed Repair Needed Repair Needed
244Completed Dozer LineYeoman8245Completed Dozer LineYeoman2	526 58 Changed from hand to dozer. FOBS Franks 10/13/2020	Repair Needed Repair Needed
247 Completed Dozer Line Yeoman 2	64 67 Changed hand line to dozer line. FOBS Franks 10/13/2020 357 Proposed dozer line down a two track	Repair Needed Repair Needed Repair Needed
250 Completed Dozer Line Jamie Geerdes 1	032 009 Dozer line off the 225 594	Completed - Ready for Inspection Repair Needed Repair Needed
252 Completed Dozer Line 7 253 Completed Dozer Line tobates_nifc, REAF 6	074 127	Repair Needed Repair Needed
255 Access or Improved Roadtobates_nifc, REAF 4	route was originally just un bladed access, till a dozer operator took it upon himself to "improve" the access by blading it. cut trees are off to side.  517.B used to access the fire edge via extension. dozer has subsequently bladed road.  3756	Repair Needed Repair Needed Repair Needed
258 Road as Completed Line Jamie Geerdes TFLD 6	Prepped south of road. **needs to be chipped  171L UTV only  86	Repair Needed Repair Needed Repair Needed
260Completed Dozer LineJamie Geerdes TFLD1261Completed Dozer LineJamie Geerdes TFLD1	871 073	Repair Needed Repair Needed
	30' mechanical thinning both sides 354 1 chain of mechanical thinning on black side 36 access line, not fireline	Repair Needed Repair Needed Repair Needed
266 Access or Improved RoadDaniel Perkins, FOBSt 1	access line, not fireline  No prep work to road segment  771	Repair Needed Repair Needed Repair Needed
<ul> <li>270 Road as Completed Line Daniel Perkins, FOBSt</li> <li>271 Road as Completed Line Daniel Perkins, FOBSt</li> <li>1</li> </ul>	Road recently improved by grader. Not sure if work was fire related.	Repair Needed Repair Needed
273 Completed Dozer Line 6	426 437 642 Completed Dozer line	Repair Needed Repair Needed Repair Needed
	Ties into meadows on both ends  Road is used here as a line that ties into the dozer line area was masticated  initial direct line.	Repair Needed Repair Needed
277Completed Dozer Linetobates_nifc, REAF2278Completed Dozer Linetobates_nifc, REAF2	dozer line down to flowing trib or Roaring creek. dozer tracked through creek. see photo point.  direct line. walked actual completed line. stopped at a seep incursion.	Repair Needed Repair Needed Repair Needed Repair Needed
280 Completed Dozer Line tobates_nifc, REAF 3 281 Completed Dozer Line 3	stopped to collect point ended at stream crossing	Repair Needed Repair Needed
283 Completed Dozer Line tobates_nifc, REAF 6	spur 919 top part is indirect, lower down is direct. actual line walked. 409	Repair Needed Repair Needed Repair Needed
285 Completed Dozer Line Tobates_nifc, REAF 1 287 Completed Dozer Line Daniel Perkins, FOBSt, READ Carroll 3	Line down from helispot circling spot then connecting to completed dozer line.  Dozer line on top of handline.  Dozer line on top of handline.	Repair Needed  Repair Needed  Repair Needed  Repair Needed
289Completed Dozer LineTFLD Geerdes2291Completed Dozer LineTFLD Geerdes2	13 855	Repair Needed Repair Needed
	8640 30-60' brushed and limbed on black side 482 01	Repair Needed Repair Needed Completed - Inspected
295 Completed Dozer Line 5 296 Completed Dozer Line 9	38 41	Completed - Inspected  Completed - Inspected
298 Completed Dozer Line 2	352 61 942	Completed - Inspected Completed - Inspected Repair Needed
301 Completed Hand Line TFLD Geerdes 1	34 75 09	Repair Needed Repair Needed Repair Needed
304 Completed Dozer Line Daniel Perkins, FOBSt 3 305 Completed Dozer Line Daniel Perkins, FOBSt 1	60 256	Repair Needed Repair Needed
307 Completed Dozer Line T bruch Fobs, READ Carroll 6 308 Completed Dozer Line READ Laura Aker 3	583 24 Process and remove timber material. Leave slash for rehab. Dozer line in cut timber sale unit 35	Repair Needed Repair Needed Completed - Inspected
312 Completed Dozer Line T Bruch Fobs 1 313 Completed Hand Line T bruch Fobs 2	43 16 54	Repair Needed  Repair Needed  Repair Needed
315 Completed Hand Line T Bruch Fobs 8 316 Completed Hand Line T bruch Fobs 3	98 85	Repair Needed Repair Needed
Access or Improved Road 6	517.0 road Has been treated on both sides with a feller Buncher and possibly a masticator most piles have been chipped line is approximately 125 feet wide. Prep on the road stops here.  Improved Road Submitted from READ Avenza  Submitted from READ Avenza	In Progress Completed - Ready for Inspection Completed - Ready for Inspection
Access or Improved Road 9 319 Completed Dozer Line 3		Repair Needed  Completed - Inspected  Completed - Ready for Inspection
321 Completed Dozer Line Daniel Perkins, FOBSt/update FOBS Franks 322 Completed Dozer Line Daniel Perkins, FOBSt/ update FOBS Franks 4	likely done by landowner due to appearance: update, land owner stated it was them who put dozer line in  likely done by landowner due to appearance: update, land owner stated it was not them who put dozer line in	Repair Needed Repair Needed
325 Completed Dozer Line Daniel Perkins, FOBSt 3	likely done by landowner due to appearance. Update,land owner stated it was not them that put in dozer line  19	Repair Needed Repair Needed Repair Needed
327 Completed Dozer Line Daniel Perkins, FOBSt 1 328 Completed Dozer Line Daniel Perkins, FOBSt 5	553 241	Repair Needed Repair Needed
330 Completed Dozer Line Daniel Perkins, FOBSt  331 Completed Dozer Line Daniel Perkins, FOBSt  7	93 463 80	Repair Needed Repair Needed Repair Needed
333 Completed Dozer Line Daniel Perkins, FOBSt 9	004 68 possibility done by landowner due to appearance 66 possibility done by landowner due to appearance	Repair Needed Repair Needed Repair Needed
335 Completed Dozer Line Daniel Perkins, FOBSt 5 336 Completed Hand Line Daniel Perkins, FOBSt 5	04 89	Repair Needed Repair Needed
338 Completed Dozer Line Daniel Perkins, FOBSt 7 339 Completed Dozer Line 2	24 56 165	Repair Needed Repair Needed Repair Needed
341 Completed Dozer Line T Bruch Fobs 2	534	Repair Needed Repair Needed
342 Completed Dozer Line T Bruch Fobs 4	63 16	Repair Needed
343 Completed Dozer Line T Bruch Fobs 1 344 Completed Dozer Line T Bruch Fobs 2		·

Repair Needed

347 Completed Dozer Line T Bruch Fobs

1568