


# DIV A

Suppression Repair  
Grizzly Creek  
CO-WRF-00348  
Sep. 5, 2020

Est. 32,464 acres at  
9/4/2020 0035 IR Flight



|                                    |                             |                               |
|------------------------------------|-----------------------------|-------------------------------|
| <b>Event Items</b>                 | <b>Accountable Property</b> | <b>Powerlines</b>             |
| <b>Event Point - Repair Status</b> | <b>Event Line</b>           | <b>HCE Powerlines</b>         |
| Completed - Inspected              | Completed Dozer Line        | 1                             |
| Repair Needed                      | Completed Hand Line         | 3                             |
| No Repair Needed                   | Road as Completed Line      | 5                             |
| Unknown                            | Access or Improved Road     | 8                             |
| <b>Event Line - Repair Status</b>  | Line Break Completed        | <b>HCE Powerlines</b>         |
| Completed - Inspected              | Proposed Dozer Line         | HCE Powerlines                |
| Completed - Ready for Inspection   | Planned Fire Line           | Wildfire Daily Fire Perimeter |
| Repair Needed                      | Planned Secondary Line      | Prescribed Fire               |
| No Repair Needed                   | Aerial Retardant Drop       | Unburned Island               |
| Unknown                            | Ridge/Geographic Feature    | Proposed Burnout              |
| <b>Structures</b>                  | Repair Line                 | Active Burnout                |
| Structures                         | Other                       | Completed Burnout             |
| <b>Event Items</b>                 | <b>Roads</b>                | Value at Risk                 |
| Event Point                        | RedCanyonSp_Route           | Closure Area                  |
| Aerial Hazard                      |                             | Evacuation Area               |
| Camp                               |                             | Retardant Avoidance Area      |
| Culvert                            |                             | Unknown                       |
|                                    |                             | Other                         |

|                                      |
|--------------------------------------|
| <b>Suppression Repair Status</b>     |
| <b>Event Point - Repair Status</b>   |
| Completed - Inspected (2)            |
| In Use - Fire Management (0)         |
| Completed - Ready for Inspection (0) |
| In Progress (0)                      |
| Repair Needed (1)                    |
| No Repair Needed (8)                 |
| Other - See Comments (0)             |
| Unknown (18)                         |
| <b>Event Line - Repair Status</b>    |
| Completed - Inspected (4)            |
| In Use - Fire Management (0)         |
| Completed - Ready for Inspection (1) |
| In Progress (0)                      |
| Repair Needed (30)                   |
| No Repair Needed (10)                |
| Other - See Comments (0)             |
| Unknown (17)                         |

