


Apalachicola National Forest Hurricane Michael Response

FL-FNF-018011 Trails Assessment Map Northeast

10/22/18



Helispots

Status

- Ready for Air Operations
- Not Ready for Air Operations
- Trails Not Assessed by Air
- ANF Trails Aerial Assessment

Forest System Roads Level 3, 4, & 5

- 5 - High Degree Of User Comfort
- 4 - Moderate Degree Of User Comfort
- 3 - Suitable For Passenger Cars
- County Boundary (Florida)
- Forest Boundary (Unofficial)
- Forest Service Land (Unofficial)

OWNER

- USFWS
- Private
- State

Level one Trauma Center AND Burn Unit:
Shands at the University of Florida
(29 38.20° N -82 20.33° W)

Level one Trauma Center ONLY:
Shands Jacksonville TraumaOne
(30 20.50° N -81 39.50° W)

This map was produced by the SA Red Team GIS on 10/21/2018 at 1825 Hours.

This product is reproduced from geospatial information prepared by the U.S. Department of Agriculture, Forest Service. GIS data and product accuracy may vary. They may be developed from sources of differing accuracy, accurate only at certain scales, based on modeling or interpretation, incomplete while being created or revised, etc. Using GIS products for purposes other than those for which they were created may yield inaccurate or misleading results. The Forest Service reserves the right to correct, update, modify, or replace GIS products without notification.

For more information, contact: Apalachicola National Forest (850) 926-3561, 57 Taff Drive, Crawfordville, FL 32327.

Data Projection:
NAD_1983_StatePlane_Florida_North_FIPS_0903_Feet



Helispot	Assessment	Status
H-1 (KTLH)	KTLH/Helibase	Ready
H-2	Air ops ready.	Ready
H-3	Wakulla work center, air ops ready.	Ready
H-4	South end of Bradwell Bay. Ready for air ops. Road access through FSR 341	Ready
H-5	North end of Bradwell Bay. Needs to be mowed. Road access good. Not air ops ready.	Ready
H-9	Air ops ready.	Ready
H-11	Not air ops ready. Will be HOGE for takeoff and landing.	Not Ready
H-21	Good condition No work needed	Ready
H-22	Needs mowed, Road access: FSR 131 (southern end) & FSR 136 (northern end) impassable; both roads have light timber debris. Not air ops ready.	Not Ready
H-23	Good condition, light access, out of ground effect for both in bound and out bound egress. FSR 128, impassable due to light timber debris. Not ready for air ops.	Not Ready
H-24	Fair condition, needs mowing, tree removal needed for departure path. Northern access roads FSR 187 and 176 and southern access roads FSR 176 to 107 to 126. All roads are impassable due to light timber debris. Not air ops ready.	Not Ready
H-27	Needs to be mowed. Road access good. Not ready for air ops.	Not Ready
H-28	Air ops ready, needs mowed.	Ready
H-29	Good condition, livestock in the area; broken fence around Wilma work center. Ready for air ops.	Ready
H-30	Needs to be mowed. FSR 112DD impassable; light timber debris. Not ready for air ops.	Not Ready
H-31	Not ready for air ops.	Not Ready
H-32	Not ready for air ops.	Not Ready
H-33	Good condition, road access good, needs light mowing. Ready for air ops.	Ready
H-34	Good condition, road access good. Ready for air ops.	Ready
H-35	Poor condition, needs mowing, access road FSR 187C has no debris but one mud hole needs rock. Not air ops ready.	Not Ready

