


Suppression Repair

Poplar Drive
NC-NCS-230039

11/15/2023

434 acres at 11/9/2023 @ 1632 hrs



Div A

Div D

Div B

Div C

- Contained
- Uncontained
- ▭ Wildfire Daily Fire Perimeter
- ▲ Gap; Summit
- X Division Break
- Drop Point
- Staging Area
- Hot Spot - Spot Fire
- Landmark
- ⊙ Gate
- Resource Location
- Repair Point
- ▲ Dozer Push
- ▲ Safety Zone
- ⊙ Other Property
- ⊙ Water Tank
- ⊙ Completed Burnout
- ▨ Completed Dozer Line
- Completed Hand Line
- Completed Road as Line
- Planned Dozer Line
- Planned Hand Line
- Planned Mixed Construction Line
- Planned Road as Line
- Planned Secondary Line
- Access or Improved Road
- Fence
- Temporary Flight Restriction
- ▭ Lake / Pond
- ▭ Structure
- Needs Assessment
- Repair Needed
- Needs Assessment
- Repair Needed
- Completed - Inspected



FC Line Type	Label	Repair Status	Repairs Needed	Repair Comments
Completed Dozer Line	1	Repair Needed	Repair dozer line/contingency with water bars	Water bars where needed on slope.
Completed Dozer Line	2	Repair Needed	Repair dozer line/contingency with water bars	
Completed Dozer Line	3	Repair Needed	Repair dozer line/contingency with water bars	
Completed Dozer Line	4	Repair Needed	Yes	Repair dozer line/contingency with water bars
Completed Road as Line	17	Repair Needed	driveway rehab several loads of gravel	
Completed Dozer Line	6	Repair Needed	Yes	Grade berms on orchard side on contingency
Completed Dozer Line	12	Repair Needed		
Completed Hand Line	15	Repair Needed		
Completed Hand Line	16	Repair Needed		Water bars where needed on slope. Water bars and rye grass seed where hand line ties into creek on other side.
Access or Improved Road	Pooler Parkway	Repair Needed		
Planned Road as Line	21	Repair Needed	Motor grader, dozer 6 way blade, or box blade needed to pull gravel out of ditch and crown road	
Completed Dozer Line	13	Repair Needed	Repair dozer line/contingency with water bars	
Completed Dozer Line	14	Repair Needed	Repair dozer line/contingency with water bars	Water bars where needed on slope.
Completed Road as Line	19	Needs Assessment		
Completed Dozer Line	7	Needs Assessment		
Completed Dozer Line	5	Needs Assessment		
Completed Dozer Line	8	Needs Assessment		
Completed Dozer Line	11	Needs Assessment		
Completed Road as Line	20	Needs Assessment		
Completed Road as Line	18	Completed - Inspected	No	Paved road with no visible damage

FC Point Type	Label	Repair Status	Latitude WGS84 DDM	Longitude WGS84 DDM	Repairs Needed
Drop Point	10	Repair Needed	35° 25.951' N	82° 23.620' W	
Safety Zone	27	Repair Needed	35° 25.342' N	82° 23.450' W	25 Fraser fir seedlings needed to be replanted. Fill in with box blade and rye grass seed road shoulder. Rye grass seed needed on road at division break.
Safety Zone	26	Repair Needed	35° 25.692' N	82° 23.332' W	New paint job
Safety Zone	25	Repair Needed	35° 25.106' N	82° 23.426' W	
Repair Point	28	Repair Needed	35° 25.135' N	82° 24.147' W	Yes, Landowners notified
Safety Zone	29	Repair Needed	35° 25.864' N	82° 23.463' W	
Dozer Push	30	Repair Needed	35° 25.811' N	82° 23.338' W	
Hotspot	1	Needs Assessment	35° 24.064' N	82° 23.376' W	
Drop Point	50	Needs Assessment	35° 24.871' N	82° 23.874' W	
Staging Area	Piney View	Needs Assessment	35° 24.316' N	82° 23.199' W	
Safety Zone	24	Needs Assessment	35° 26.125' N	82° 23.551' W	