

### Structure Triage Information



SOUTHWEST AREA  
INCIDENT MANAGEMENT TEAM

**Structure Number:** 615  
**Structure Name:** Big rosa cabins  
**SubDivision:** MAP Withington  
**GPS Location, Lat.** 33 49.347  
**GPS Location, Long.** 107 26.32152  
**Safety Zone Present:** No  
**Type of Structure:** Other  
**Surrounding Fuels:** Timber  
**Structure Triage Category:** Non-Defensible, Prep and Leave  
**Roof Material:** Wood  
**Heat Traps:**  
**Electrical Power:**  
**Hazards:**  
**Access to Site:**  
**Comm with ICP:** None  
**Water Source:** None  
**Mitigation Time:** 3-4 Hours  
**Collected By:** K. Watkins

**Where is Safety Zone:**  
**Primary Structures:** 1

**Outbuildings:** 0

**Defensible Space:** None

**Siding Material:** Wood

**Gas to Structure:**

**Best Access From:**

**Collected Date/Time:** 05/29/2016 17:53:00  
Photo 2



Photo 3

Photo 4

## Structure Triage Information



SOUTHWEST AREA  
INCIDENT MANAGEMENT TEAM

**Structure Number:** 667  
**Structure Name:** Exter Spring Cabin  
**SubDivision:** Div. A  
**GPS Location, Lat.** 33 46.81314  
**GPS Location, Long.** 107 24.97626  
**Safety Zone Present:** No **Where is Safety Zone:** Black 1/3 mile north of cabin  
**Type of Structure:** Other **Primary Structures:** 1 **Outbuildings:** 0  
**Other Type of** Historic cabin  
**Surrounding Fuels:** Grass,Shrub,Timber **Defensible Space:** 30-50 Feet  
**Structure Triage**  
**Category:** Non-Defensible, Prep and Leave  
**Roof Material:** Wood **Siding Material:** Metal  
**Heat Traps:** Open Eaves,Other Receptor  
**Electrical Power:** None **Gas to Structure:** None  
**Hazards:** Terrain,Fuels  
**Hazard Notes:** Remote access  
**Access to Site:** Handcrew **Best Access From:** 378 A to the 1011  
**Comm with ICP:** Radio  
**Water Source:** None  
**Mitigation Time:** Less Than An Hour  
**Notes:** Structure has been preped, if opportunity to burn around before main fire reaches the cabin the chance of survivability is increased.  
**Collected By:** Brandon Allen **Collected Date/Time:** 05/30/2016 10:00:51  
Photo 1 Photo 2



Photo 3



Photo 4





## Structure Triage Information



SOUTHWEST AREA  
INCIDENT MANAGEMENT TEAM

**Structure Number:** 673  
**Structure Name:** Big Rosa cabin lower  
**SubDivision:** North Fire  
**GPS Location, Lat.** 33 50.0694  
**GPS Location, Long.** 107 26.21994  
**Safety Zone Present:** No  
**Type of Structure:** Other  
**Other Type of** Historic cabin  
**Surrounding Fuels:** Grass,Shrub,Timber  
**Structure Triage**  
**Category:** Non-Defensible, Prep and Leave  
**Roof Material:** Wood  
**Heat Traps:** Other Receptor  
**Electrical Power:** None  
**Hazards:** Terrain,Fuels  
**Access to Site:** Handcrew  
**Comm with ICP:** Radio  
**Water Source:** None  
**Mitigation Time:**  
**Collected By:** BA

**Where is Safety Zone:**  
**Primary Structures:** 1

**Outbuildings:** 0

**Defensible Space:** None

**Siding Material:** Wood

**Gas to Structure:** None

**Best Access From:** Big Rosa trail

**Collected Date/Time:** 06/02/2016 09:06:09

Photo 1

Photo 2



Photo 3

Photo 4