



SUPPRESSION REPAIR *South*

Rafael
 AZ-PNF-863
 7/4/2021
 78,065 acres
 at 7/1/2021 1200



- Repair Status Line
 - Completed - Inspected
 - In Use - Fire Management
 - Repair Needed
 - Unknown
- Repair Status Point
 - Completed - Inspected
 - In Use - Fire Management
 - Repair Needed
 - Unknown
- Dip Site
- Division Break
- Drop Point
- Staging Area
- Lookout
- Value at Risk
- Gate
- Repair Point
- Fence - Cut/Damaged
- Hazard
- Completed Dozer Line
- Completed Hand Line
- Completed Road as Line
- Other
- Retardant Drop
- Fire Edge
- Contained Line
- Secondary Highway
- Paved Roads
- Dirt (Not Paved)
- USFS Road
- Trail
- Tunnel; Bridge
- Railroad
- Runway
- Wildfire Daily Fire Perimeter
- Substation
- Transmission Line
- Oil and Natural Gas Well
- Oil and Natural Gas Pipeline
- Fire History
- Ranger District Boundary
- Administrative FS Boundary
- Federal Wilderness Boundary
- County Boundary
- Local or State Parks
- Other Federal
- Private
- State
- US Forest Service

FC Point Type	Label	Repair Status	Repair Comments	Comments	Latitude	Longitude
Drop Point	20	Unknown			34° 53.749' N	112° 12.386' W
Drop Point	30	Unknown			34° 55.563' N	112° 12.375' W
Drop Point	73	Unknown			34° 54.456' N	111° 50.943' W
Drop Point	77	Unknown			34° 55.081' N	111° 54.583' W
Drop Point	80	In Use - Fire Management		JNez for Pat Moore MESA JNez proposed drop point.	34° 53.304' N	111° 54.385' W
Fence - Cut/Damaged	Completed - Inspected	Completed - Inspected	fence repaired, mounded and boulders placed, trail gate not damaged, great work	Cut fence for dozer access JNez ARCH, repaired 6/29	34° 53.717' N	111° 52.952' W
Fence - Cut/Damaged	Completed - Inspected	Completed - Inspected	needs repair JNez ARCH, repaired 6/30		34° 54.726' N	111° 54.464' W
Fence - Cut/Damaged	Completed - Inspected	Completed - Inspected	dozer rolled over, wooden lathes need to be replaced, repaired 6/29 was already in bad shape JNez		34° 54.647' N	111° 54.249' W
Repair Point	Repair Needed	Repair Needed	Scatter over wider area or remove	scatter slash	34° 55.040' N	111° 53.957' W
Repair Point	Repair Needed	Repair Needed		Place boulders to prevent OHV	34° 54.744' N	111° 54.636' W

FC Line Type	Label	Repair Status	Repair Comments	Comments	Length Feet
Completed Dozer Line	DZ-20	Completed - Inspected	Will need water bars, berms pulled, slash pulled back across line, repaired per local specs, still slash, road drivable. JNez. All repair work done. No pumps or hose. Inspected and completed.	multiple drainage crossings, buried telephones JNez	9341
Completed Dozer Line	DZ-21	Completed - Inspected	obliterate berm, pull slash overline, needs ARCH monitor	masticated 6/25, repaired on 6/30 per local specs JNez	2165
Completed Hand Line	H-10	Completed - Inspected	obliterate berm, scatter slash on line	repaired on 6/30 per local specs JNez	235
Completed Hand Line	H-11	Completed - Inspected	needs ARCH	needs arch to repair, repaired 6/28 JNez	104
Completed Hand Line	H-14	Unknown		Cold trail	971
Completed Hand Line	H-15	Unknown		Cold trail	1
Completed Hand Line	H-16	Unknown		Cold trail	9
Completed Hand Line	H-17	Unknown		Cold trail	708
Completed Hand Line	H-18	Unknown		Cold trail	821
Completed Hand Line	H-5	Repair Needed			1657
Completed Hand Line	H-6	Repair Needed			315
Completed Hand Line	H-9	Completed - Inspected		no sediment to cover line, repaired 6/30 JNez	73
Completed Road as Line		In Use - Fire Management	scatter or chip slash		2656
Completed Road as Line		Completed - Inspected		scatter or chip slash	2831
Other		Completed - Inspected	None	Trail as line, fuel break, repaired and scattered, some slash piled because of veg density, barely noticeable - JNez	1373