


SUPPRESSION REPAIR North

Rafael
AZ-PNF-863
7/5/2021
78,065 acres
at 7/1/2021 1200



- | | | | |
|--|--|--|--|
| <ul style="list-style-type: none"> Repair Status Line Completed - Inspected In Use - Fire Management In Progress Repair Needed No Repair Needed Unknown Dip Site Division Break | <ul style="list-style-type: none"> Drop Point Staging Area Water Development or Draft Site Value at Risk Hazard Tree Fence - Cut/Damaged Repeater Safety Zone Hazard Water Source Completed Burnout Completed Dozer Line | <ul style="list-style-type: none"> Completed Hand Line Completed Road as Line Repair Line Road Repair Retardant Drop Fire Edge Contained Line Secondary Wire Paved Roads Dirt (Not Paved) USFS Road Trail Wildfire Daily Fire Perimeter Substation | <ul style="list-style-type: none"> Transmission Line Oil and Natural Gas Well Fire History Fuel Treatment Ranger District Boundary Administrative FS Boundary Federal Wilderness Boundary County Boundary Military Private State US Forest Service |
|--|--|--|--|

EC Point Type	Label	Repair Status	Repair Comments	Comments	Latitude	Longitude
Drop Point	50	Unknown			35° 57.965' N	112° 15.795' W
Drop Point	40	No Repair Needed			35° 03.001' N	112° 08.187' W
Drop Point	41	No Repair Needed			35° 02.782' N	112° 08.136' W
Drop Point	49	No Repair Needed	No repair	Gravelled pullout along 105 road, for sycamore canyon bike trail.	35° 04.262' N	112° 01.520' W
Drop Point	50	No Repair Needed		No disturbance	35° 04.648' N	112° 00.563' W
Drop Point	51	No Repair Needed			35° 07.012' N	112° 01.217' W
Drop Point	52	No Repair Needed	Minimal slash in this area, no repair needed.	White Horse Rec Residences	35° 06.797' N	112° 00.282' W
Drop Point	53	No Repair Needed		56/13 rd junction	35° 09.463' N	112° 00.032' W
Drop Point	55	Repair Needed	trash and flagging needs to be pulled	Boy Scout Camp	35° 08.679' N	111° 55.062' W
Drop Point	58	Unknown			35° 02.285' N	112° 04.576' W
Drop Point	59	Unknown			35° 05.153' N	111° 51.644' W
Drop Point	60	Unknown			35° 04.505' N	111° 56.554' W
Fence - Cut/Damaged		Repair Needed	Burnout operation damaged fences. Needs supplies for repairs.		35° 08.496' N	111° 58.561' W
Fence - Cut/Damaged		Completed - Inspected	Minimal slash		35° 01.150' N	112° 06.945' W
Fence - Cut/Damaged		Completed - Inspected	outside private boundary/in permittee horse pasture?		35° 01.607' N	112° 06.858' W
Fence - Cut/Damaged		Repair Needed	Requires 6 staves, 3 T-posts, wire.		35° 02.502' N	112° 08.253' W
Fence - Cut/Damaged		Completed - Inspected	Dozer damaged tree outside fence and damaged fence on private boundary, tree overhanging fence.		35° 06.925' N	112° 00.392' W
Hazard Tree		Completed - Inspected	Dozer pushed pines into rock outcrop.		35° 02.468' N	112° 08.358' W
Hazard Tree		Completed - Inspected	Remove slash and remove trees from rock outcrop.		35° 02.370' N	112° 08.476' W
Repair Point		Repair Needed	Ensure private gate is closed or left as before at entrance to BSC		35° 07.992' N	111° 58.474' W
Repair Point		Repair Needed	Slash should be scattered, partially cut Juno should be felled and topped/scattered		35° 07.947' N	111° 58.473' W
Repair Point		Completed - Inspected	and state - dispose to rock bin connector trail, pull rocks, duff over intersection and down to edge of rocks approx. 50'		35° 08.842' N	111° 58.746' W
Repair Point		Completed - Inspected	Log and scatter in old bed leveling		35° 09.488' N	112° 00.625' W
Repair Point		Completed - Inspected	Log and scatter interior.		35° 09.460' N	112° 00.891' W
Repair Point		Completed - Inspected	Ragged pink w. black polka dots. Disguise dozer line from designated trail.	Dozer line plus trail junction	35° 07.000' N	112° 00.367' W
Repair Point		Completed - Inspected	Flagged pink w. black polka dots. Sycamore Point trail was obliterated by dozer line here.		35° 06.992' N	112° 00.407' W
Repair Point		Repair Needed		Gate drive around	35° 08.820' N	111° 57.821' W
Repair Point		Completed - Inspected	chip slash along road		35° 05.410' N	111° 59.941' W
Repair Point		Completed - Inspected	chip slash		35° 04.474' N	112° 00.852' W
Repair Point		Completed - Inspected	Disguise the line running downhill toward the old road, pull rocks across.		35° 01.020' N	112° 02.233' W
Repair Point		Completed - Inspected	Disguise small handline around spot along W side 125 rd		35° 03.485' N	112° 03.026' W
Repair Point		Completed - Inspected	Disguise small handline around spot along W side 125 rd		35° 01.292' N	112° 06.531' W
Repair Point		Completed - Inspected	closure to avoid vehicle use towards private parcel	spur off dozer line into non MVAH road	35° 02.428' N	112° 08.079' W
Repair Point		Completed - Inspected	Use well paved along to A&K on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	replace burned over road closure signpost. (D&R?)	35° 04.014' N	112° 00.725' W
Repair Point		Completed - Inspected	Need to chip slash material on east side of rec. residences. Completed per KK 7/4		35° 06.788' N	112° 00.231' W
Repair Point		Completed - Inspected	Completed to repair		35° 06.579' N	112° 00.034' W
Water Development or Draft Site	Trick Tank	Repair Needed	Use well paved along to AA on 715.	Use digitized 7/4 to transition to Forest.	35° 01.091' N	112° 01.246' W

EC Point Type	Label	Repair Status	Repair Comments	Comments	Latitude	Longitude
Completed Dozer Line	01	Completed - Inspected		Area is currently only Stage One slash and slash along road to road. Road slash and slash along road to road. Road slash and slash along road to road. Road slash and slash along road to road.	35° 03.001' N	112° 08.187' W
Completed Dozer Line	02	Completed - Inspected		3/8 dump and slash across road	35° 04.262' N	112° 01.520' W
Completed Dozer Line	03	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 04.648' N	112° 00.563' W
Completed Dozer Line	04	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 07.012' N	112° 01.217' W
Completed Dozer Line	05	Completed - Inspected		Repair first part of area that is slash and slash along road to road. Road slash and slash along road to road. Road slash and slash along road to road.	35° 06.797' N	112° 00.282' W
Completed Dozer Line	06	Completed - Inspected		3/8 dump and slash across road	35° 09.463' N	112° 00.032' W
Completed Dozer Line	07	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 08.679' N	111° 55.062' W
Completed Dozer Line	08	Completed - Inspected		Repair with slash pull on burn and slash along road to road. Road slash and slash along road to road. Road slash and slash along road to road.	35° 02.285' N	112° 04.576' W
Completed Dozer Line	09	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 05.153' N	111° 51.644' W
Completed Dozer Line	10	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 04.505' N	111° 56.554' W
Completed Dozer Line	11	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 08.496' N	111° 58.561' W
Completed Dozer Line	12	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 01.150' N	112° 06.945' W
Completed Dozer Line	13	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 01.607' N	112° 06.858' W
Completed Dozer Line	14	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 02.502' N	112° 08.253' W
Completed Dozer Line	15	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 06.925' N	112° 00.392' W
Completed Dozer Line	16	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 02.468' N	112° 08.358' W
Completed Dozer Line	17	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 02.370' N	112° 08.476' W
Completed Dozer Line	18	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 07.992' N	111° 58.474' W
Completed Dozer Line	19	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 07.947' N	111° 58.473' W
Completed Dozer Line	20	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 08.842' N	111° 58.746' W
Completed Dozer Line	21	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 09.488' N	112° 00.625' W
Completed Dozer Line	22	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 09.460' N	112° 00.891' W
Completed Dozer Line	23	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 07.000' N	112° 00.367' W
Completed Dozer Line	24	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 06.992' N	112° 00.407' W
Completed Dozer Line	25	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 08.820' N	111° 57.821' W
Completed Dozer Line	26	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 05.410' N	111° 59.941' W
Completed Dozer Line	27	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 04.474' N	112° 00.852' W
Completed Dozer Line	28	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 01.020' N	112° 02.233' W
Completed Dozer Line	29	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 03.485' N	112° 03.026' W
Completed Dozer Line	30	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 01.292' N	112° 06.531' W
Completed Dozer Line	31	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 02.428' N	112° 08.079' W
Completed Dozer Line	32	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 04.014' N	112° 00.725' W
Completed Dozer Line	33	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 06.788' N	112° 00.231' W
Completed Dozer Line	34	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 06.579' N	112° 00.034' W
Completed Dozer Line	35	Completed - Inspected		Use well paved along to AA on 715. Need to order oxenoxes to replace burned over road closure signpost. (D&R?)	35° 01.091' N	112° 01.246' W