GISS Misc	RepairPrio	FC Line Type	Comments	Repair Status	Repairs Needed	Repair Comments	ARCH Clearance
	-				Recountouring, checkdams and waterbars	Seeding Needed	
1					as prescribed per Suppresion Repair		
			From fire archs, Recommended for POD		Plan.Prioritize recountouring over		
	High	Completed Dozer Line	minimal repair need D.Orozco 5.24.2022	Repair Needed	waterbars and checkdams within view of		Not Cleared
					roads and Withington Lookout.		
					Recommend reseeding in area above		
					treeline and within view of lookout. Recountouring, checkdams and waterbars		
					as prescribed per Suppresion Repair		
					Plan.Prioritize recountouring over		
2	High	Completed Dozer Line	From fire archs	Repair Needed	_	Seeding Needed	Cleared for Mechanical Repair
_	111611	Gompleted Bozer Line	Trom me arens	repair recucu	roads and Withington Lookout.	Securing recucu	Greated for Wieemaniear Repair
					Recommend reseeding. Upper portion is		
					handline and can be rehabbed by hand.		
3	T a	Completed Hand Line	From fire archs	Donair Mandad	Pull material back in, no checkdams or		Classed for Hand Cross Dancis
<b>.</b>	Low	Completed Hand Line		Repair Needed	waterbars needed. Recommend reseed.		Cleared for Hand Crew Repair
4	Unknown	Completed Road as Line	Possible water truck use for powder	Completed - Inspected	Chipping	Seeding Needed	Not Cleared
		Compressed from an arms	sections	Compressed impressed		1	1 to created
20	High	Completed Dozer Line	The real Dozer line; via DIV A,	Completed - Inspected	Recountouring, checkdams and waterbars	Seeding Needed	Cleared for Mechanical Repair
20			Recommended for POD minimal repair		as prescribed per Suppresion Repair Plan.		
		Completed Road as Line	need D.Orozco 5.24.2022	Repair Needed	Flush cut all fresh stumps. Remove all	Historic sites along road, consult ARCH.	Cleared for Hand Crew Repair
					bucked rounds and branches/slash out of		
					drainages. Chip all small diaemeter		
21	High						
	C				decayed/decomposing woody debris		
					(includding logs) in black evenly. Log deck		
					cut rounds from felling operations 5/25/22 R Washam > Additional Slash		
	High	Completed Dozer Line	From fire archs	Completed - Inspected		Seeding Needed	Cleared for Mechanical Repair
					Needed. Recountouring, checkdams and		
22					waterbars as prescribed per Suppresion		
					Repair Plan.Prioritize recountouring over		
					waterbars and checkdams within view of		
			+		roads.   5/25/22 R Washam > Additional Slash		
		Completed Dozer Line		Completed - Inspected	Needed. Recountouring, checkdams and		
00	High				waterbars as prescribed per Suppresion		
23			From fire archs		Repair Plan.Prioritize recountouring over	Seeding Needed	Cleared for Mechanical Repair
					waterbars and checkdams within view of		
					roads.		
24	High	Completed Dozer Line	Recommended for POD minimal repair need D.Orozco 5.24.2022	Repair Needed	Recountouring, checkdams and waterbars	Seeding Needed	
					as prescribed per Suppresion Repair		Cleared for Mechanical Repair
					I -		
					waterbars and checkdams within view of		
25	High	Completed Dozer Line		In Progress	roads. Seeding Needed		Cleared for Mechanical Repair
25	1 11 R11	Completed Dozer Line		In Progress	Beeding Meeded	<u> </u>	Greated for Mechanical Kepair

GISS Misc	RepairPrio	FC Line Type	Comments	Repair Status	Repairs Needed	Repair Comments	ARCH Clearance
26	High	Completed Dozer Line	From fire archs	Completed - Inspected	Recountouring, checkdams and waterbars as prescribed per Suppresion Repair Plan.	Seeding Needed	Cleared for Mechanical Repair
27	Unknown	Completed Road as Line		Repair Needed			Not Cleared
28	Unknown	Completed Dozer Line	Collected by REAF Orozco 5/08/2022	Repair Needed			Not Cleared
29	Unknown	Completed Dozer Line	collect by D.Orozco REAF 5/9/2022	Repair Needed			Not Cleared
30	Unknown	Completed Dozer Line	Collected by D.Orozco REAF 5/09/2022	Repair Needed		Historic structure nearby, check with ARCH prior to rehabilitation.	Cleared for Mechanical Repair
31	Unknown	Completed Dozer Line	Collected by REAF Orozco 5/08/2022	Repair Needed			Not Cleared
32	High	Completed Dozer Line		Repair Needed		Light water bars and slash in canyon bottoms. Heavier treatment near the ridge top. POD line. MSO recovery habitat including water sources. Consult technical speacialits prior to repair. Ensure recontouring and other measures for blocking unauthorized motorized travel. minimal Repair Needs.	Cleared for Mechanical Repair
33	Unknown	Completed Dozer Line	collected by REAFD.Orozco 5.11.2020	Repair Needed		IIIIIIIIIIIIII Nebali Needs.	Not Cleared
		1 1 1 1		1	recontour and install check dams on steep		
34	Unknown	Completed Dozer Line	Check line	Repair Needed	slopes, drag slash across to discourage OHV use	ends in nuked out snag patch	Cleared for Mechanical Repair
35	Unknown	Completed Hand Line		Repair Needed	Recountouring, checkdams and waterbars, pull material back into hand line as prescribed per Suppresion Repair Plan.		Cleared for Hand Crew Repair
36	High	Completed Hand Line		Repair Needed	Recountouring, checkdams and waterbars, pull material back into handline as prescribed per Suppresion Repair Plan.		Cleared for Hand Crew Repair
37	Unknown	Completed Dozer Line	Dozer line	Repair Needed			Not Cleared
38	Unknown	Completed Road as Line		Repair Needed	Chipping		Not Cleared
39	Unknown	Road Repair		Repair Needed			Not Cleared
40	Unknown	Completed Road as Line		Repair Needed			Not Cleared
42	Unknown	Completed Hand Line	Div K, WIHC-A, 5/15/22 handline or dozer line depending on authorizations and operator comfort. Will go through fence in 2 places. Fence is in poor condition as is.	Repair Needed			Not Cleared
43	Unknown	Completed Road as Line		Repair Needed			Not Cleared
44	Medium	Completed Road as Line		Completed - Inspected	Chipping		Cleared for Mechanical Repair
45	Unknown	Completed Hand Line	Div K, WIHC-A, 5/15/22	Repair Needed			Not Cleared
46	High	Completed Dozer Line		Repair Needed	Dozer or Handcrew Light repairs. Close the ends, light slash and light water bars. Div K, WIHC-A, 5/15/22, Recommended for POD minimal repair need D.Orozco 5.24.2022	Seeding Needed	Not Cleared

GISS Misc	RepairPrio	FC Line Type	Comments	Repair Status	Repairs Needed	Repair Comments	ARCH Clearance
			Div K, WIHC-A, 5/15/22 some dozer				
47	Unknown	Completed Road as Line	improvements any road with heavy rock	Repair Needed			Not Cleared
			was high bladed				
40	II: ab	Completed Deed on Line	Div K, WIHC-A, 5/15/22	Danair Naadad	Chipping Needed along Roadway. R		Closued for Hand Cross Donair
48	High	Completed Road as Line	DIV K, WING-A, 3/13/22	Repair Needed	Washam 5/26		Cleared for Hand Crew Repair
49	Unknown	Completed Dozer Line		Repair Needed			Not Cleared
50	Unknown	Completed Hand Line		Repair Needed			Not Cleared
51	Unknown	Completed Dozer Line		Completed - Inspected			Not Cleared
52	Unknown	Completed Hand Line		Repair Needed			Not Cleared
53	Unknown	Completed Dozer Line		Completed - Inspected			Not Cleared
54	Unknown	Completed Hand Line		Completed - Inspected			Cleared for Hand Crew Repair
55	High	Completed Dozer Line	Recommended for POD minimal repair	Rapair Needed			Cleared for Hand Crew Repair
	Tilgii	-	need D.Orozco 5.24.2022	Repair Needed			Cleared for frame Crew Repair
56	High	Completed Hand Line		Completed - Inspected			Cleared for Hand Crew Repair
57	Unknown	Completed Road as Line		Repair Needed	needs chipping, slash on side of road		Not Cleared
59	Unknown	Completed Road as Line		Repair Needed			Not Cleared
60	Unknown	Fence	Game fence needs repair	Needs Assessment			Not Cleared
61	Unknown	Completed Road as Line	Per ops	In Progress			Not Cleared
62	Unknown	Other	UTV/Small truck Road	Needs Assessment			Not Cleared
63	Unknown	Completed Hand Line	HL to DIV Break	Repair Needed			Not Cleared
64	Medium	Completed Road as Line		Repair Needed	Chipping, light blading and water truck		Cleared for Mechanical Repair
	Wicdiani	Completed Road as Line		Repair recucu	work		Greated for Mechanical Repair
65	High	Completed Dozer Line		Repair Needed	Place Slash and Waterbars as necessary.	Seeding Needed	Cleared for Mechanical Repair
					Close east end where ties into road		
66	Unknown	Completed Dozer Line		Repair Needed		Repair repair specifications for crossing	Cleared for Mechanical Repair
	Chritown	Gompieted Dozer Eme		repair recueu		drainages in Whitewater Canyon.	Gleared for Weenamear Repair
	Unknown	Completed Road as Line	Recommended for POD minimal repair need D.Orozco 5.24.2022	Repair Needed		Where road curves south entering into	Cleared for Mechanical Repair
67						canyon a historic property is present.	
0,						Consult ARCH for	
						instructions/monitoring.	
68	Unknown	Completed Dozer Line	Recommended for POD minimal repair	Repair Needed			Cleared for Mechanical Repair
		-	need D.Orozco 5.24.2022	1			
69	Unknown	Completed Hand Line		Repair Needed			Not Cleared
70	Unknown	Completed Dozer Line		Repair Needed			Not Cleared
73	Unknown	Completed Hand Line	Recommended for POD minimal repair	Repair Needed			Not Cleared
<u> </u>	Olimio Wil	Gompleted Hand Ellie	need D.Orozco 5.24.2022	Trepuii i recucu			.,,,
74	Unknown	Completed Hand Line	Div K 5/17/22, Recommended for POD	Repair Needed			Not Cleared
, 1	J	Gompietea mana Eme	minimal repair need D.Orozco 5.24.2022	Ttepuii Tteeded			
75	Unknown	Completed Road as Line	Div K 5/17/22	Completed - Inspected	Chipping completed 5/28 as per READ		Not Cleared
		T			Meeting		
	High	Completed Dozer Line		Repair Needed	Use handcrew Close both ends, light water		
76					bars, and light slash. R Washam 5/26 Div	Seeding Needed	Cleared for Mechanical Repair
					K, Recommended for POD minimal repair		
					need D.Orozco 5.24.2022		
77	Unknown	Completed Hand Line		Repair Needed			Not Cleared
79	Unknown	Completed Dozer Line		Repair Needed			Not Cleared

GISS Misc	RepairPrio	FC Line Type	Comments	Repair Status	Repairs Needed	Repair Comments	ARCH Clearance
80	Unknown	Completed Dozer Line		Repair Needed			Not Cleared
81	Unknown	Completed Dozer Line		Repair Needed			Not Cleared
82	Medium	Completed Hand Line		Repair Needed	Close the ends Completed handLine per K, Recommended for POD minimal repair need D.Orozco 5.24.2022	Needs seeding	Cleared for Hand Crew Repair
83	Unknown	Repair Line	Check line	Repair Needed			Not Cleared
84	Unknown	Completed Road as Line	Prep complete	Repair Needed			Not Cleared
85	Unknown	Completed Dozer Line	Within fire/black, single blade, old temp haul road	Repair Needed	recontour and install check dams on steep slopes, drag slash across to discourage OHV use		Cleared for Mechanical Repair
86	Unknown	Completed Hand Line	Trail/creek used as hand line. Has been brushed on north side of line. Brush moved out of creek bottom.	Repair Needed	No repair needed.		Not Cleared
87	Unknown	Completed Hand Line	Brushing along line	Repair Needed			Not Cleared
88	Unknown	Completed Road as Line	Brushed on south side of road. Slash has been chipped.	Repair Needed			Not Cleared
89	Unknown	Completed Road as Line	Brushed on south side of road. Has not been chipped as of 5/20. Slash is off steep slope, would be difficult to chip.	Repair Needed			Not Cleared
90	Unknown	Completed Road as Line	Brushed below road. Slash was burned in fire.	Repair Needed			Not Cleared
91	Unknown	Completed Hand Line	Short Handline, interior fire/black	No Repair Needed	None	Recommended no Repair	Not Cleared
92	Unknown	Completed Hand Line	Line Interior fire/Black	Repair Needed		_	Not Cleared
93	Unknown	Completed Hand Line	Handline to Natural Barrier, Recommended for POD minimal repair need D.Orozco 5.24.2022	Repair Needed			Not Cleared
94	Unknown	Completed Hand Line	From fire archs/kWood	Repair Needed	Recountouring, checkdams and waterbars as prescribed per Suppresion Repair Plan.	Prioritize recountouring over waterbars and checkdams within view of roads and Withington Lookout. Recommend reseeding. Upper portion is handline and can be rehabbed by hand.	Cleared for Mechanical Repair
95	Unknown	Completed Dozer Line	Per READ kwood	Repair Needed			Not Cleared
96	Unknown	Completed Dozer Line	spur from main dozer line pushed by skidgine	Repair Needed	recontour and pull slash across to discourage OHV use		Cleared for Mechanical Repair
97	Medium	Completed Road as Line	Road Interior fire/black; road brushed	Repair Needed	Repair road. Possible grader or dozer work. Possible chipping but very little slash in place; road surface powdery in a few locations.		Cleared for Mechanical Repair
98	Unknown	Completed Road as Line	Road Interior fire/black; road brushed average 25 feet south/west side road; very little slash created with some slash burned.	Repair Needed	Possible chipping but very little slash in place; road surface powdery in a few locations.	Recommend REAF review or discuss with DIV	Not Cleared
99	High	Completed Dozer Line	from 330 to main line on ridge, for dozer egress?	Completed - Inspected	standard, recontour, water bars when needed, disguise entrance to limit OHV access	Seeding Needed	Cleared for Mechanical Repair

GISS Misc	RepairPrio	FC Line Type	Comments	Repair Status	Repairs Needed	Repair Comments	ARCH Clearance
100	High	Completed Dozer Line	from 138 to dead end at rocky cliff above 330	Repair Needed	recontour and install check dams on steep slopes, drag slash across to discourage OHV use	Seeding Needed	Cleared for Mechanical Repair
101	Unknown	Completed Hand Line		Repair Needed			Not Cleared
102	Unknown	Completed Dozer Line		Completed - Inspected			Not Cleared
103	Unknown	Completed Hand Line	Line fires edge	Repair Needed		2 foot scrape, some underslung, large berm with trenches.	Not Cleared
104	Unknown	Completed Hand Line	Line fires edge	Repair Needed		1 foot scrape, minimal berm.	Not Cleared
105	Unknown	Completed Dozer Line	Line in fire/black, single blade width; old two-track, not on map, now dozerline.	Repair Needed		If District doesn't want public continuing to use old two-track/dozerline, in addition to repair on line, may need additional barrier work at intersection.	Not Cleared
106	Unknown	Completed Dozer Line		Repair Needed			Not Cleared
107	Unknown	Other	Historic phone line hung in old growth trees. Consult ARCH prior to repair.	Needs Assessment			Cleared for Mechanical Repair
108	Unknown	Completed Hand Line	Line in fire/black	Repair Needed			Not Cleared
109	Unknown	Completed Road as Line		Repair Needed			Not Cleared
110	Unknown	Completed Road as Line		In Progress	Chipping complete, possible slash needed (From GISS Steve as per READ Meeting 5/28		Not Cleared
111	Unknown	Completed Road as Line	Road Interior fire/black; road brushed average 25 feet north side road; very little slash created with some slash burned; no chipping needed.	No Repair Needed	None		Not Cleared
112	Medium	Completed Road as Line		Repair Needed	Light Chipping needed. Some blading of road		Cleared for Mechanical Repair
113	High	Completed Dozer Line		Repair Needed	Pull back berms and slash. Handcrew work.	Seeding Needed	Not Cleared
114	Medium	Completed Dozer Line		Repair Needed	Pull back berms and slash. Handcrew work.	Seeding Needed	Cleared for Hand Crew Repair
115	Medium	Completed Dozer Line		Repair Needed	Pull back berms and slash. Handcrew work.	Seeding Needed	Cleared for Hand Crew Repair
116	Medium	Completed Dozer Line		Repair Needed	Pull back berms and slash. Handcrew work.	Seeding Needed	Cleared for Hand Crew Repair