


Repair

Cerro Bandera
NMN6S000234
6/15/2022 Day

939 acres at 06/10/2022 1900



- Helispot
- Division Break
- Drop Point
- Staging Area
- Value at Risk
- Repair Point
- Fence - Cut/Damaged
- Safety Zone
- Wildfire Daily Fire Perimeter
- Other State Lands
- Bureau of Land Management Lands
- National Park Service Lands
- Needs Assessment
- Repair Needed
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Needs Assessment
- Repair Needed
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed


Incident Name	FC Point Type	Label	Comments	Repair Status
Cerro Bandera	Drop Point	DP 40		Needs Assessment
Cerro Bandera	Staging Area			Needs Assessment
Cerro Bandera	Safety Zone		Dry pond	No Repair Needed
Cerro Bandera	Value at Risk		Burnt Structure	No Repair Needed
Cerro Bandera	Value at Risk		Old log cabin	No Repair Needed
Cerro Bandera	Value at Risk		Foundation of an old cabin (burnt prior) concrete only	No Repair Needed
Cerro Bandera	Helispot		Unapproved	No Repair Needed
Cerro Bandera	Drop Point	DP 30		Needs Assessment
Cerro Bandera	Drop Point	DP 20		Needs Assessment
Cerro Bandera	Drop Point	DP 10		Needs Assessment
Cerro Bandera	Value at Risk		Burnt structure	Needs Assessment
Cerro Bandera	Fence - Cut/Damaged			Repair Needed
Cerro Bandera	Fence - Cut/Damaged			Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Fence	Completed - Inspected
Cerro Bandera	Fence - Cut/Damaged		Fence	Completed - Inspected
Cerro Bandera	Fence - Cut/Damaged		Fence	Completed - Inspected
Cerro Bandera	Fence - Cut/Damaged		Fence	Completed - Inspected
Cerro Bandera	Fence - Cut/Damaged		Fence	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Fence	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Broken Fence	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Burnt Corner Post	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Cut Fence	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Snap Broken Fence	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Burnt corner post	Repair Needed
Cerro Bandera	Repair Point		Debris Pile	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Burnt utility pole and fence post	No Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Burnt Brace	Other - See Comments
Cerro Bandera	Fence - Cut/Damaged		Corner brace, damage caused by fire	Other - See Comments
Cerro Bandera	Fence - Cut/Damaged		Burnt Gate Post	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Corner Brace Burnt	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Corner Of Fence	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Burnt Corner	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Burnt Corner	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Corner Post Burnt	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Cut Barb Wire	Repair Needed
Cerro Bandera	Repair Point		Electrical Box Burnt	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Gate Post Burnt	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Gate Post Burnt	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		H Brace Burnt	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Tree On Fence	Completed - Inspected
Cerro Bandera	Fence - Cut/Damaged		Tree On Fence	Completed - Inspected
Cerro Bandera	Fence - Cut/Damaged		Tree On Fence	Completed - Inspected
Cerro Bandera	Fence - Cut/Damaged		Tree On Fence	Repair Needed
Cerro Bandera	Fence - Cut/Damaged		Tree On Fence	Repair Needed
Cerro Bandera	Repair Point		Pull out area used repeatedly, could use some brush to deter park visitors from doing the same	Repair Needed

DIV D

DIV Z

DIV A

Incident Name	FC Line Type	Comments	Repair Status	Repairs Needed
Cerro Bandera	Completed Burnout		No Repair Needed	
Cerro Bandera	Completed Road as Line		No Repair Needed	No repair needed
Cerro Bandera	Completed Hand Line	Div Alpha	Completed - Inspected	
Cerro Bandera	Completed Hand Line	Div Alpha- fire perimeter is on the hand line. Adjust fire perimeter to match	Completed - Inspected	
Cerro Bandera	Completed Hand Line		Completed - Inspected	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		Completed - Inspected	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road	REAF's inspected handline.	Completed - Inspected	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road	REAF's inspected line, blends in with natural landscape	Completed - Inspected	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		Completed - Inspected	Water bar as needed, scatter brush, cover line
Cerro Bandera	Access or Improved Road	Still in use	Completed - Inspected	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		Needs Assessment	
Cerro Bandera	Access or Improved Road		Completed - Inspected	
Cerro Bandera	Access or Improved Road		Completed - Inspected	
Cerro Bandera	Access or Improved Road	READ inspected, handline blended with natural landscape	Completed - Inspected	
Cerro Bandera	Access or Improved Road		Completed - Inspected	
Cerro Bandera	Access or Improved Road	Hot spot cold trailed line	Completed - Ready for Inspection	Minimal
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road	Hot spot cold trail	Completed - Ready for Inspection	Minimal
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		Completed - Ready for Inspection	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road	HM - inspection of handline completed	Completed - Inspected	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		No Repair Needed	
Cerro Bandera	Access or Improved Road		Completed - Inspected	
Cerro Bandera	Access or Improved Road	Rehabbed handline blends in with natural landscape	Completed - Inspected	
Cerro Bandera	Access or Improved Road		Completed - Inspected	
Cerro Bandera	Access or Improved Road	Hot Spot Cold Trail	Needs Assessment	Minimal handline repair
Cerro Bandera	Road Repair	Vehicle tracks could appear to be a road.	Completed - Inspected	Vehicle two tracks off of Cerro Bandera Rd could appear to be a road to visitor in the park. Recommend placing slash at the intersection of road and two tracks to obscure entrance to the tad
Cerro Bandera	Completed Hand Line	Line is not continuous. Mix of handline and no line for hotspotting in slopover.	Repair Needed	Light scratch lines, could rehabber berms in larger segment.



B Kirk
6/14/2022 2037
Acres from IR and GPS
North American 1983 Datum, Lat/Long Grid