



Suppression Repair

Crooks Fire
AZ-PNF-000271
May 7, 2022



- Repair Status**
- Completed - Inspected
 - In Progress
 - Needs Assessment
 - No Repair Needed
 - Repair Needed

- Repair Status**
- Completed - Inspected
 - In Progress
 - Needs Assessment
 - No Repair Needed
 - Repair Needed

- X Division Break
- Gate
- Bridge
- Camp
- Clean Up Area
- Culvert
- Dip Site
- Dozer Push
- Drop Point
- Fence - Cut/Damaged
- Fire Station

- Hazard
- Hazard Tree
- Helispot
- Hot Spot - Spot Fire
- Landing or Log Deck
- Lookout
- Mobile Weather Unit
- Other
- Repair Point

- Repeater
- Retardant in Avoidance Area
- Road Repair
- Staging Area
- Stream Crossing
- Structure Wrap
- Value at Risk
- Water Development or Draft Site
- Water Source
- Completed Burnout

- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Road as Line
- Planned Fuel Break
- Access or Improved Road
- Other
- Repair Line

- Road Repair
- Contained
- Uncontained
- Cerdia Site (Avoid Heavy Equipment Use)
- BASIC CUSTODIAL CARE (CLOSED)
- HIGH CLEARANCE VEHICLES
- SUITABLE FOR PASSENGER CARS
- MODERATE DEGREE OF USER COMFORT
- HIGH DEGREE OF USER COMFORT
- Possible Hazard Mine Locations

