



Calf Canyon
 NMSNF000028
 7/26/2022
REPAIR BRIEFING NORTH REPAIR

- | | | | |
|-----------------------|-------------------------|-----------------------------------|--------------------------------|
| Air Operations | Drop Point | Completed Dozer Line | Access or Improved Road |
| Highlighted Helispot | Camp | Completed Fuel Break | Fence |
| Helispot | Staging Area | Completed Hand Line | Other |
| Sling Site | Lookout | Completed Mixed Construction Line | Road Line |
| Value at Risk | Restricted Water Source | Completed Plow Line | Road Repair |
| Division Break | | Completed Road as Line | Retardant Drop |

0 1 2 Miles
 0 1 2 Kilometers

GIS Calculated Acres from Mixed Methods
 341,735
 As of 7/5/2022 at 19:00
 NAD 1983 UTM Zone 13N
 Contour Interval 20 Feet
 1:46,000

Incident Management Team 5
 Southwest Area
 Incident Management Team 5
 REPAIR BRIEFING

NORTH REPAIR

DIV X

DIV A

- | | |
|---|---|
| In Use - Fire Management | In Use - Fire Management |
| Needs Assessment | Needs Assessment |
| Repair Needed | Repair Needed |
| In Progress | In Progress |
| Completed - Ready for Inspection | Completed - Ready for Inspection |
| Completed - Inspected | Completed - Inspected |
| No Repair Needed | No Repair Needed |
| Other - See Comments | Other - See Comments |