



Repair Status

- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Other - See Comments

Calf Canyon

NMSNF000028

8/31/2022

SUPPRESSION REPAIR NORTH EXTENT

- | |
|---|
| <ul style="list-style-type: none"> ● Dip Site ● Helibase ● Medical ● Incident Command Post ■ Drop Point ■ Staging Area ■ Structure Wrap ■ Value at Risk ● Other ● Water Development or Draft Site ● Repair Point ● Stream Crossing ● Road Repair ● Retardant in Avoidance Area ● Resource Location ● Repair Point ● Landing or Log Deck ● Hazard Tree ● Fence - Cut/Damaged ● Dazer Push ● Culvert ● Clean Up Area ● Mobile Weather Unit ● Safety Zone ● Hazard ● Water Source ● Restricted Water Source ● Summit, Gap ● Completed Burnout ● Completed Dozer Line ● Completed Fuel Break ● Completed Hand Line ● Completed Mixed Construction Line ● Other ● Repair Line ● Road Repair ● Power Lines ● Administrative FS Boundary ● Ranger District Boundary ● Federal Wilderness Boundary ● Division Areas ● Bureau of Indian Affairs (BIA) ● Bureau of Land Management (BLM) ● State ● US Forest Service (USFS) ● Private ● Needs assessment ● Repair Needed ● In Progress ● Completed ● Other - See Comments ● Camp ● Staging Area ● Other ● Gate ● Road Repair ● Clean Up Area ● Landing or Log Deck ● Fence - Cut/Damaged ● Hazard ● Dazer Push ● Important Routes |
|---|

0 1 2 3 Miles
0 1 2 3 Kilometers

GIS Calculated Acres from IR and GPS
341,735 acres as of 7/5/2022 at 19:00
NAD 1983 UTM Zone 13N
1:68,000

SOUTHWEST AREA
INCIDENT MANAGEMENT TEAM 4

SUPPRESSION REPAIR NORTH EXTENT