

# Branch 1

## DIV S/Roads Group

## DIV X

## NORTH REPAIR

## DIV O

**Repair Status**

- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Other - See Comments

**Calf Canyon**  
NMSNF000028  
9/8/2022  
**SUPPRESSION REPAIR NORTH**

● Dip Site	● Incident Command Post	● Value at Risk	● Stream Crossing	● Landing or Log Deck	● Clean Up Area	● Restricted Water Source	— Completed Hand Line	— Fence	— Ranger District Boundary	— State	● Repair Needed	● Other - See Comments	● Road Repair	● Dozer Push
● Helispot	● Drop Point	● Other	● Mobile Weather Unit	● Hazard Tree	● Safety Zone	● Summit Gap	— Completed Mixed Construction Line	— Repair Line	— US Forest Service (USFS)	● In Progress	● Camp	● Staging Area	● Repair Point	● Culvert
● Branch Break	● Staging Area	● Water Development or Draft Site	● Retardant in Avoidance Area	● Safety Zone	● Completed Dozer Line	● Completed Burnout	— Completed Road as Line	— Road Repair	— Private	● Completed	● Gate	● Other	● Landing or Log Deck	● Clean Up Area
● Medical	● Lookout	● Structure Wrap	● Resource Location	● Hazard	● Water Source	● Completed Fuel Break	— Access or Improved Road	— Road Repair	● Needs assessment	● Other	● Gate	● Other	● Hazard Tree	● Important Routes
			● Repair Point	● Culvert	● Water Source	● Completed Fuel Break	— Access or Improved Road	— Road Repair	● Needs assessment	● Other	● Gate	● Other	● Fence - Cut/Damaged	

0 1 2 3 4 5 6 Miles  
0 1 2 3 4 5 6 Kilometers

**SOUTHWEST AREA**  
INCIDENT MANAGEMENT TEAM 5

GIS Calculated Acres from IR and GPS  
341,735 acres as of 7/5/2022 at 19:00  
NAD 1983 UTM Zone 13N