



Repair Status

- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Other - See Comments

Calf Canyon

NMSNF000028

9/10/2022

SUPPRESSION REPAIR SOUTH

- | |
|--|
| <ul style="list-style-type: none"> ● Dip Site ● Helispot ● Sling Site ● Branch Break ● Medical ● Drop Point ● Staging Area ● Lookout ● Water Development or Draft Site ● Structure Wrap ● Stream Crossing ● Other ● Gate ● Resource Location ● Repair Point ● Value at Risk ● Mobile Weather Unit ● Safety Zone ● Hazard ● Water Source ● Summit; Gap ● Completed Burnout ● Completed Dozer Line ● Completed Fuel Break ● Completed Hand Line ● Completed Mixed Construction Line ● Repair Line ● Completed Road as Line ● Access or Improved Road ● Road Repair ● Retardant Drop ● Retardant ● Fence ● Administrative FS Boundary ● Ranger District Boundary ● Federal Wilderness Boundary ● State ● Bureau of Indian Affairs (BIA) ● Bureau of Land Management (BLM) ● Department of Defense (DOD) ● National Park Service (NPS) ● US Fish and Wildlife Service (USFWS) ● US Forest Service (USFS) ● Private ● Needs assessment ● Repair Needed ● In Progress ● Completed ● Other - See Comments ● Aerial Seeding and Mulching ● Other ● Gate ● Road Repair ● Repair Point ● Landing or Log Deck ● Hazard Tree ● Fence - Cut/Damaged ● Dozer Push ● Culvert ● Repeater ● Hazard ● Important Routes |
|--|

0 1 2 3 4 Miles
0 1 2 3 Kilometers

GIS Calculated Acres from IR and GPS
341,735 acres as of 7/5/2022 at 19:00
NAD 1983 UTM Zone 13N
Downloaded 9/10/2022

SOUTHWEST AREA
INCIDENT MANAGEMENT TEAM 5
SUPPRESSION REPAIR SOUTH