



Repair Status

- Needs Assessment
- Repair Needed
- Completed - Ready for Inspection
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Other - See Comments
- 🏠 Needs assessment
- 🏠 Repair Needed
- 🏠 In Progress
- 🏠 Completed
- 🏠 Other - See Comments

Calf Canyon

NMSNF000028

9/12/2022

SUPPRESSION REPAIR SOUTH

<ul style="list-style-type: none"> — Branch Break ● Dip Site ● Helispot ● Helibase ● Sling Site 	<ul style="list-style-type: none"> — Medical — Drop Point — Staging Area — Lookout 	<ul style="list-style-type: none"> ● Value at Risk ● Other ● Gate ● Water Development or Draft Site ● Structure Wrap 	<ul style="list-style-type: none"> ● Stream Crossing ● Landing or Log Deck ● Hazard Tree ● Fence - Cut/Damaged ● Dozer Push ● Culvert ● Repair Point 	<ul style="list-style-type: none"> ● Clean Up Area ● Mobile Weather Unit ● Safety Zone ● Hazard ● Water Source 	<ul style="list-style-type: none"> — Summit; Gap — Completed Burnout — Completed Dozer Line — Completed Fuel Break — Completed Hand Line — Other 	<ul style="list-style-type: none"> — Completed Mixed Construction Line — Completed Road as Line — Access or Improved Road — Fence — Other 	<ul style="list-style-type: none"> — Repair Line — Road Repair — Escape Route — Retardant Drop — Division Areas — State 	<ul style="list-style-type: none"> — Bureau of Indian Affairs (BIA) — Bureau of Land Management (BLM) — Department of Defense (DOD) — National Park Service (NPS) — State 	<ul style="list-style-type: none"> — US Fish and Wildlife Service (USFWS) — US Forest Service (USFS) — Private — Aerial Seeding and Mulching — Important Routes
--	--	---	--	--	--	---	---	--	---

0 1 2 3 4 5 6 Miles
0 1 2 3 4 5 6 Kilometers

SOUTHWEST AREA
INCIDENT MANAGEMENT TEAM 5

GIS Calculated Acres from IR and GPS
341,735 acres as of 7/5/2022 at 19:00
NAD 1983 UTM Zone 13N
Created 9/12/2022 08:17