

Branch 1

DIV S/Roads Group

DIV X

DIV O

NORTH REPAIR

Repair Status

- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Other - See Comments
- + Needs assessment
- + Repair Needed
- + In Progress
- + Completed
- + Other - See Comments

Calf Canyon

NMSNF000028

9/14/2022

SUPPRESSION REPAIR NORTH

— Branch Break	+ Branch Break	+ Staging Area	+ Water Development or Draft Site	+ Resource Location	+ Dozer Push	+ Water Source	+ Completed Fuel Break	— Access or Improved Road	— Division Areas	— Bureau of Land Management (BLM)
+ Dip Site	+ Medical	+ Lookout	+ Structure Wrap	+ Repair Point	+ Culvert	+ Restricted Water Source	+ Completed Hand Line	— Fence	— Ranger District Boundary	— State
+ Helispot	+ Incident Command Post	+ Value at Risk	+ Stream Crossing	+ Landing or Log Deck	+ Clean Up Area	+ Summit; Gap	+ Completed Mixed Construction Line	— Other	— Administrative FS Boundary	— US Forest Service (USFS)
+ Helibase	+ Drop Point	+ Other	+ Road Repair	+ Hazard Tree	+ Safety Zone	+ Completed Burnout	+ Completed Plow Line	— Repair Line	— Federal Wilderness Boundary	— Private
+ Unimproved Landing Area	+ Camp	+ Gate	+ Retardant in Avoidance Area	+ Fence - Cut/Damaged	+ Hazard	+ Completed Dozer Line	+ Completed Road as Line	— Road Repair	— Bureau of Indian Affairs (BIA)	— Important Routes

0 1 2 3 4 5 6 Miles
0 1 2 3 4 5 6 Kilometers

SOUTHWEST AREA
INCIDENT MANAGEMENT TEAM 5

GIS Calculated Acres from IR and GPS
341,735 acres as of 7/5/2022 at 19:00
NAD 1983 UTM Zone 13N
Created 9/14/2022 08:54