



FC Point Type	Label	Repair Status	Repair Comments	Lat WGS84	Long WGS84
Camp	North Spike	Repair Needed		36° 06.863 N	106° 44.720 W
Drop Point	15	No Repair Needed		36° 11.228 N	106° 51.546 W
Drop Point	17	No Repair Needed		36° 11.868 N	106° 46.274 W
Drop Point	20	Completed - Inspected		36° 09.052 N	106° 44.099 W
Drop Point	23	Completed - Inspected		36° 08.006 N	106° 42.522 W
Drop Point	40	Completed - Inspected		36° 06.423 N	106° 44.922 W
Drop Point	43	Repair Needed		36° 06.423 N	106° 44.922 W
Drop Point	45	Repair Needed		36° 06.865 N	106° 44.794 W
Drop Point	50	Completed - Inspected	Pull up 5 berry cans and one other sign when no longer needed	36° 07.018 N	106° 43.153 W
Drop Point	55	Completed - Inspected	Pull flagging when no longer needed	36° 06.602 N	106° 43.067 W
Drop Point	58	Completed - Inspected	Pull flagging when no longer needed	36° 06.009 N	106° 43.534 W
Drop Point	60	Completed - Inspected	Pull flagging when no longer needed	36° 05.706 N	106° 42.156 W
Drop Point	65	Completed - Inspected	Pull flagging when no longer needed	36° 03.942 N	106° 41.003 W
Drop Point	70	Completed - Inspected	Pull flagging when no longer needed	36° 03.689 N	106° 40.508 W
Drop Point	72	Completed - Inspected	Pull flagging when no longer needed	36° 02.879 N	106° 41.336 W
Drop Point	74	Completed - Inspected	Pull flagging when no longer needed	36° 02.159 N	106° 42.084 W
Drop Point	75	Completed - Inspected	Pull sign when no longer needed	36° 00.133 N	106° 42.878 W
Drop Point	77	Completed - Inspected	Pull sign when no longer needed	36° 00.936 N	106° 42.218 W
Drop Point	78	Completed - Inspected	Drop signs were not flagged or marked	36° 00.657 N	106° 42.899 W
Drop Point	80	Repair Needed	Being used as spike camp, needs to be longer in use.	36° 05.231 N	106° 44.301 W
Drop Point	81	Completed - Inspected	No repairs needed, 8/15/24, pull sign when no longer needed	36° 02.365 N	106° 43.908 W
Drop Point	85	In Use - Fire Management	Note each prep and complete to prep, pull sign when no longer needed	36° 02.856 N	106° 45.858 W
Drop Point	87	Repair Needed	materials needed to repair cut near door to walk through	36° 03.416 N	106° 45.534 W
Fence - Cut/Damaged		In Use - Fire Management	Rebuild fence, both posts and barbed wire are down	36° 05.880 N	106° 45.577 W

FC Line Type	Repair Status	Repair Comments	Repair Priority	Comments	Length Feet
Completed Dozer Line	Repair Needed		Unknown		5831
Completed Dozer Line	Repair Needed	Pull back berms and bushes, redistribute material, establish water bars where necessary	Unknown	See repair plan	9400
Completed Dozer Line	Repair Needed		Unknown	Not surveyed - Cobbs	10598
Completed Dozer Line	Repair Needed		Unknown	Surveyed ahead of dozer 10-Aug Gibbs	4205
Completed Dozer Line	Repair Needed	Dozer berm needs to be knocked down, water bars need to be placed, materials should be scattered over line.	Unknown	Not surveyed Gibbs	2243
Completed Dozer Line	Repair Needed	Chipping of materials or spreading on line far rehab. Dozer berm knocked down and spread out.	Unknown	Not surveyed Gibbs	3374
Completed Dozer Line	Repair Needed	berms need to be pulled back	Unknown	Materials along road side can be chipped or spread back over the road for rehab. Dozer berm along edge should be pushed and spread out.	10641
Completed Dozer Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Materials along road side can be chipped or spread back over the road for rehab. Dozer berm along edge should be pushed and spread out.	1099
Completed Dozer Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Materials along road side can be chipped or spread back over the road for rehab. Dozer berm along edge should be pushed and spread out.	8775
Completed Dozer Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Materials along road side can be chipped or spread back over the road for rehab. Dozer berm along edge should be pushed and spread out.	1856
Completed Dozer Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Materials along road side can be chipped or spread back over the road for rehab. Dozer berm along edge should be pushed and spread out.	34
Completed Hand Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	High	Planned dozer line, walk with ARCH/READ	2671
Completed Hand Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Medium	Hand line starts at road edge and goes to the west	6
Completed Hand Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line starts at road edge and goes to the west	1480
Completed Hand Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line starts at road edge and goes to the west	2219
Completed Hand Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line starts at road edge and goes to the west	1105
Completed Hand Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Medium	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	4963
Completed Mixed Construction Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	4905
Completed Mixed Construction Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	1072
Completed Road as Line	Completed - Inspected	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	1936
Completed Road as Line	Completed - Inspected	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	3523
Completed Road as Line	Completed - Inspected	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	17225
Completed Road as Line	Completed - Inspected	water bars, berms knocked down, and materials scattered over dozer line.	High	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	16349
Completed Road as Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	12352
Completed Road as Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	10888
Completed Road as Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	6642
Completed Road as Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Medium	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	2809
Completed Road as Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	740
Completed Road as Line	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	High	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	2963
Road Repair	In Use - Fire Management	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	13905
Road Repair	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	4081
Road Repair	Repair Needed	water bars, berms knocked down, and materials scattered over dozer line.	Unknown	Hand line follows the fire edge, periodically around spot fire, dips in and out of wilderness and crosses fence line. Line continues beyond bottom of mesa but we stopped for weather	7628

Feature Category (Point Type)	Label	Property Status	Trackable ID	Serial Number	Incident/Supply Number	Lat WGS84	Long WGS84
Water Tank		Unknown				36° 06.537 N	106° 44.902 W

SUPPRESSION REPAIR
 Black Feather NMSNF-000345 08/17 Day
 2,198 acres as of 08/11/2023 1714hrs
 1:37,000 - SW2 GIS - 8/16/2023 2204 - Aves from IR and GPS - North American 1983 Datum, LatLong Grid

<ul style="list-style-type: none"> In Use - Fire Management Repair Needed Completed - Inspected Completed - Inspected Water Tank Helispot In Use - Fire Management Division Break 	<ul style="list-style-type: none"> Incident Command Post Water Development or Draft Site Camp Other Gate Water Source Completed Dozer Line Completed Hand Line Completed Mixed Construction Line Completed Road as Line Repair Line Road Repair Perimeter Fence Camground Trailhead Picnic Site Interpretive Site Structure Oil and Natural Gas Pipeline Powerline Aqueduct Highway Local Connecting Road Forest Roads Access Road Local Road Paved Road Gravel Road Primitive Road Closed Roads Trail National Designated Trail County Boundary Administrative FS Boundary Ranger District Boundary Federal Wilderness Boundary FS Roadless Area Bureau of Indian Affairs (BIA) State US Forest Service (USFS) Bureau of Land Management (BLM) National Park Service (NPS) Private 	
---	---	--