FC Line Type	Comments	Strategic Line Type	Repair Comments	Repair Priority	ARCH Clearance
	Slash piled on green side. Ranges from moderate piles to nothing				
Completed Hand Line	CColt-REAF	Secondary Strategic Line			0 Not Cleared
Completed Road as Line		Secondary Strategic Line			0 Not Cleared
Completed Dozer Line		Primary Strategic Line			0 Not Cleared
Completed Hand Line		None			0 Not Cleared
Completed Hand Line		None			0 Not Cleared
Completed Hand Line		Primary Strategic Line			0 Not Cleared
Completed Dozer Line		Secondary Strategic Line			0 Not Cleared
Completed Dozer Line	Actual DL	Secondary Strategic Line			0 Not Cleared
	berm could be pulled over. nearby debris could be scattered about.				
	dozer line gains elevation. some water bars likely needed. excavator				
Completed Dozer Line	with thumb will probably do the best rehab.	Secondary Strategic Line			0 Not Cleared
Completed Dozer Line		Secondary Strategic Line			0 Not Cleared
Completed Hand Line	Smokey Bear completed hand line	Primary Strategic Line			0 Not Cleared
Completed Dozer Line		None			0 Not Cleared
Completed Mixed Construction Line		Drimany Stratogic Line	Repair Completed (REAF Novack)		0 Not Cleared
	Cilvar City IIIC hand line	Primary Strategic Line	Repair Completed (REAF Novack)		
Completed Hand Line	Silver City IHC hand line	None	1 blade wide - lightly scraped		0 Not Cleared
			surface. Pull small berm and		
			scatter slash where present.		
Completed Dozer Line	Indirect dozer line on ridge south from Skyline Campground	Secondary Strategic Line	(REAF Larsen 5/31/24).		0 Not Cleared
		, 0	Recommend closure on 107 to		
			prevent ATV/UTV access		
Completed Dozer Line		None	following fire management.		0 Not Cleared
Completed Dozer Line		Secondary Strategic Line	READ MCGERVEY		0 Not Cleared
	Steep dozerline, small berm w/ little to no organic material. Potential				
	future erosion issues. Consult State/private owner for repair standard.		25.42.4.60521/5/		
Completed Dozer Line	CColt-Lead READ	Secondary Strategic Line	READ MCGERVEY 1 blade wide. Pull berm, slash		0 Not Cleared
			line, and water bar. (REAF Larsen		
Completed Dozer Line	Proposed indirect dozer line	Secondary Strategic Line	5/31/24).		0 Not Cleared
Completed Dozel Line	The process with the control of the	Secondary Strategie Line	1 blade wide. Pull berm, scatter		140t cicured
			slash, and water bar. (Reaf Larsen	ı	
Completed Dozer Line		Secondary Strategic Line	5/31/24).		0 Not Cleared
Completed Road as Line	Currently being implemented	Primary Strategic Line			0 Not Cleared
Completed Mixed Construction Line		Primary Strategic Line			0 Not Cleared
Completed Hand Line	hand line not actually constructed.	None			0 Not Cleared
Completed Road as Line		Secondary Strategic Line			0 Not Cleared
Completed Hand Line	hand line not actually constructed.	Secondary Strategic Line			0 Not Cleared
Completed Road as Line		Secondary Strategic Line			0 Not Cleared
Completed Dozer Line		Secondary Strategic Line			0 Not Cleared
Completed Dozer Line	South of Rd 107; cut corner at entrance to Mills TH	None			0 Not Cleared
Completed Hand Line		Primary Strategic Line			0 Not Cleared
Completed Mixed Construction Line		Primary Strategic Line			0 Not Cleared

FC Line Type	Comments	Strategic Line Type	Repair Comments	Repair Priority	ARCH Clearance
	dozer line put in with backhoe by property owner-per Div F. Will need to coordinate with State and landowner. When looking at line in the area, the landowner contacted me and was appreciative of the work, but had concerns that the dozerline "we" built would cause erosion in				
Completed Dozer Line	some locations. CColt-Lead READ	None			0 Not Cleared
Completed Mixed Construction Line		Primary Strategic Line			0 Not Cleared
Completed Mixed Construction Line		Primary Strategic Line	REAF MCGERVEY Chip roadside material (5/31/24		0 Not Cleared
Completed Road as Line		Secondary Strategic Line	REAF Larsen).		0 Not Cleared
Completed Road as Line		Secondary Strategic Line			0 Not Cleared
Completed Road as Line		Secondary Strategic Line			0 Not Cleared
Completed Mixed Construction Line		Secondary Strategic Line			0 Not Cleared
Completed Road as Line		Primary Strategic Line			0 Not Cleared
Completed Mixed Construction Line		Secondary Strategic Line			0 Not Cleared
Completed Road as Line		Secondary Strategic Line			0 Not Cleared
Completed Road as Line		Secondary Strategic Line			0 Not Cleared
Access Route		None			0 Not Cleared
Completed Dozer Line		Secondary Strategic Line			0 Not Cleared
Completed Dozer Line		Secondary Strategic Line			0 Not Cleared
Completed Hand Line		None			0 Not Cleared
Completed Dozer Line	Mixed depth and berm height (0-20+"). Coordinate with State on repair needs.	Secondary Strategic Line	Coordinate with RV park as needed. READ MCGERVEY		0 Not Cleared
Completed Mixed Construction Line		Secondary Strategic Line			0 Not Cleared
Completed Hand Line		None			0 Not Cleared
Completed Road as Line		Secondary Strategic Line			0 Not Cleared
Completed Hand Line	Indirect handline	None			0 Not Cleared
Completed Hand Line	Direct handline	None			0 Not Cleared
Completed Dozer Line		None			0 Not Cleared
Completed Hand Line		None			0 Not Cleared
Completed Hand Line		None			0 Not Cleared
Completed Dozer Line		None			0 Not Cleared
Completed Mixed Construction Line		Primary Strategic Line			0 Not Cleared
	hand line mostly follows a power line trail. this hand line, at each end, connects the road to the power line trail. the end pieces are about 30 feet each in length, are newly constructed, and is a light scrape. brush				
Completed Hand Line	has been thrown to the green side. rehab needs to be determined.	Secondary Strategic Line			0 Not Cleared
Completed Hand Line	Handline follows power line to cut off steep slope above road. Slash from prep will need scattering or chipping	None			0 Not Cleared
Completed Dozer Line		None			0 Not Cleared
Completed Hand Line		None			0 Not Cleared
Samples and Line	2 foot scrape, 30 foot prep, moderate slope, cut material placed close				. Tot cicuicu
Completed Hand Line	to boundary. 2 foot scrape. a couple steep sections might need water bars. berm is	Secondary Strategic Line			0 Not Cleared
Completed Hand Line	not big. if repairs are needed, work will be light.	Secondary Strategic Line			0 Not Cleared

C Line Type	Comments	Strategic Line Type	Repair Comments	Repair Priority	ARCH Clearance
Completed Mixed Construction Line		None			0 Not Cleared
ompleted Dozer Line		None			0 Not Cleared
ompleted Dozer Line		None			0 Not Cleared
ompleted Dozer Line		None			0 Not Cleared
ompleted Dozer Line		None			0 Not Cleared
ompleted Hand Line	Combination direct and hotspot/cold trail	None			0 Not Cleared
ompleted Dozer Line		Secondary Strategic Line			0 Not Cleared
ompleted Hand Line		Primary Strategic Line			0 Not Cleared
ompleted Hand Line		Primary Strategic Line			0 Not Cleared
ompleted Mixed Construction Line		Primary Strategic Line			0 Not Cleared
ompleted Hand Line		None			0 Not Cleared
Completed Mixed Construction Line	Pull berm back over handline where berms exist, pull berm over cup trenches toward bottom of canyons with two or three water bars before the canyon bottom. Pull flagging while leaving area.	Primary Strategic Line			0 Not Cleared
ompleted Mixed Construction Line	, 35 5	Primary Strategic Line			0 Not Cleared
ompleted Dozer Line	REAF Larsen	Secondary Strategic Line			0 Not Cleared
ompleted Dozer Line		None			0 Not Cleared
ompleted Dozer Line		None			0 Not Cleared
ompleted Hand Line	REAF Larsen	None			0 Not Cleared
ompleted Hand Line	REAF Larsen	Secondary Strategic Line			0 Not Cleared
Completed Dozer Line	Light/thin dozer scrape and improved road as line on east end. CColt- Lead READ	Secondary Strategic Line	Land owner refused repair 6/3. Minimal work. READ MCGERVEY		0 Not Cleared
ompleted Hand Line	REAF Larsen	Secondary Strategic Line			0 Not Cleared
ompleted Hand Line	REAF Larsen	Secondary Strategic Line			0 Not Cleared
ompleted Hand Line		Secondary Strategic Line			0 Not Cleared
ompleted Hand Line		Primary Strategic Line			0 Not Cleared
ompleted Hand Line	REAF Larsen	Secondary Strategic Line			0 Not Cleared
ompleted Hand Line	REAF Larsen	None			0 Not Cleared
ompleted Hand Line		None			0 Not Cleared
ompleted Hand Line		None			0 Not Cleared
Access Route	Road to the top of nob with 3 occupied RV trailers	None			0 Not Cleared
ccess Route		None	Close at road. Fully close at forest boundary Add drainage READ MCGERVEY	t	0 Not Cleared
ompleted Hand Line	3 foot scrape, 33 foot saw prep, moderate slope	Secondary Strategic Line			0 Not Cleared
ompleted Dozer Line	the state of the s	None	_		0 Not Cleared
ompicted pozer zime	3 foot scrape, 33 foot saw prep, some mixed with old dozer line. Moderate slope. Some cut material placed on private toward South en				Not eleared
ompleted Hand Line	of line.	None			0 Not Cleared
completed Mixed Construction Line		Primary Strategic Line			0 Not Cleared
ompleted Hand Line	Completed by Silver City IHC 5/28-5/29. Completed burnout 5/29	None			0 Not Cleared
ompleted Hand Line	Completed by Silver City IHC 5/28, burnout 5/29	None			0 Not Cleared

FC Line Type	Comments	Strategic Line Type	Repair Comments	Repair Priority	ARCH Clearance
Completed Hand Line		None			0 Not Cleared
			Recommend closure West of		
			Southfork Road, water bars on		
Completed Dozer Line		None	steep slope.		0 Not Cleared
Completed Hand Line		None			0 Not Cleared
Completed Hand Line	REAF Larsen	None			0 Not Cleared
Completed Mixed Construction Line		Secondary Strategic Line			0 Not Cleared
Completed Mixed Construction Line		Primary Strategic Line			0 Not Cleared
Completed Mixed Construction Line		Primary Strategic Line			0 Not Cleared
Completed Dozer Line		None			0 Not Cleared
Completed Dozer Line		None			0 Not Cleared
Completed Road as Line		Secondary Strategic Line			0 Not Cleared
	2 foot scrape. small berm could be pulled back over for rehab. prepped				
	brush could be scattered or placed over line. not steep. no water bars				
Completed Hand Line	necessary.	None	READ MCGERVEY		0 Not Cleared
	2 foot scrape. had a berm that could be pulled back over line. some		Only water bar and slash on line		
	swamped brush that could be scattered around or over rehabbed line.		on the east side only READ		
Completed Hand Line	slightly steep on the eastern side that may need a water bar or two.	None	MCGERVEY		0 Not Cleared
Completed Harid Line	half the line is 2 foot scrape and the other half is cup trench. ask	None	WIEGERVET		o Not cleared
	property owner about repairs. berm could be pulled in, cup trench too.				
Completed Hand Line	water bar or two definitely.	None	READ MCGERVEY		0 Not Cleared
Completed Mixed Construction Line		None			0 Not Cleared
Completed Hand Line		None			0 Not Cleared
	30 saw prep, shaded fuel break with heavies bucked and moved				
Completed Fuel Break	interior.	Secondary Strategic Line			0 Not Cleared
			CONSULT READ TOT CONTACT		
			information for private		
			landowner to determine repair		
			needs. Update, close and repair with hand crews. Bring slash to		
	Short dozerline from end of road to wilderness boundary behind house		road switchback READ		
Completed Dozer Line	CColt- Lead READ	None	MCGERVEY		0 Not Cleared
Completed Bozer Line	Cook Ecad NEXE	None	Wedenver		o Not cicarca
	Light/thin dozer scrape and improved road as line on east end. CColt-		Closure and repair complete 6/3		
Completed Dozer Line	Lead READ	Secondary Strategic Line	still need seed. READ MCGERVEY		0 Not Cleared
Completed Fuel Break	30 feet of dead and down removed, trees limbed.	Secondary Strategic Line			0 Not Cleared
Completed Hand Line		None			0 Not Cleared
			READ MCGERVEY. Chip prep		
Access Route		None	from summer homes		0 Not Cleared
			READ MCGERVEY. Chip, use some		
			slash to match dozer crossings of		
Access Route	Chipping	None	creek/bridges.		0 Not Cleared
Completed Dance Line		News	not part of fuel break/line,		O Nat Class d
Completed Dozer Line		None	should be repaired TJ5/30; No repair needed READ		0 Not Cleared
Completed Fuel Break	30 foot fuel break, removing dead and down, snagging, limbing.	Secondary Strategic Line	MCGERVEY		0 Not Cleared
completed i del break	30 1000 fuel break, removing dead and down, snagging, infibilig.	Secondary Strategic Line	IVICOLITYLI		o Not Cleared

FC Line Type	Comments	Strategic Line Type	Repair Comments	Repair Priority	ARCH Clearance
			multiple hand lines in the area. berms could be pulled back over handline. some cup trenches were made which could be pulled back in. not very steep. probably		
Completed Hand Line		None	won't need water bars.		Not Cleared
Completed Fuel Break		None			Not Cleared
Completed Mixed Construction Line		Primary Strategic Line			Not Cleared
Completed Hand Line		None			Not Cleared
Completed Road as Line		Secondary Strategic Line			Not Cleared
Completed Hand Line		None			Not Cleared
Completed Road as Line		Secondary Strategic Line			Not Cleared
Completed Dozer Line		None			Not Cleared
Completed Hand Line		None			Not Cleared
Completed Hand Line	Light scrape, no slash	None	READ MCGERVEY.		Not Cleared