


Suppression Repair

July Lightning Incident
MN-SUF-002394
9/4/2026 Day

- Helispot
- Sling Site
- UAS Launch and Recovery
- Drop Point
- Camp
- Staging Area
- Draft Site
- Restricted Water Source
- Value at Risk
- Landmark
- Gate
- Bridge
- Stream Crossing
- Repair Point
- Landing or Log Deck
- Slash Pile
- Invasive Plant
- Dozer Push
- Culvert
- Clean Up Area
- Other Property
- Pump
- Water Tank
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Road as Line
- Repair Line
- Road Repair
- Access Route
- International Boundary

Repair Status

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Repair Deferred
- Other - See Comments
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Repair Deferred
- Other - See Comments
- Private, To be Contacted
- Owner Contacted, No Repair Requested
- Owner Contacted, Repair Requested



0 1 2 3 4 5
Miles

Published on 9/3/2026 @ 2131
North American 1983 Datum, LatLong Grid

