

Dixie Incident
CA-BTU-009205
SUPPRESSION REPAIR BRANCH 9
September 10, 2021

Clean Up
Culvert,STAT
Dozer
Fence - Cut/
Hazard
Landing or Log
Repair
Road
Stream
Value at
Culvert,FEDERA
Clean Up
Dozer
Fence - Cut/
Hazard
Landing or Log
Repair
Resource
Retardant in Avoidance
Road
Stream
Value at
Fence - Cut/
Division
Branch
Zone
Repeater
Hazard
Water
Restricted Water
Drop
Completed
Completed Dozer
Completed Fuel
H - Completed Hand
M - Completed Mixed Construction
P - Completed Plow
R - Completed Road as
Planned
Planned Dozer
Planned Fuel
H - Planned Hand
M - Planned Mixed Construction
P - Planned Plow
R - Planned Road as
S - Planned Secondary
Fence
Fire
Contained
Beckwourth Dozer
Chips 2012 Dozer
KLine
Completed -
Completed - Ready for
In
In Use - Fire
No Repair
Other - See
Repair
Unknown
Unit
Lava
NPS
USFS
Beckwourth Fire
Suppression Exclusion Area
Proposed
Administrative
Bureau of Indian
Bureau of Land
CA Dept. of Fish and
National Park
Non-Profit Conservancies and
Other State
Private
USDA Forest
Drafting Avoidance Area
Drafting Avoidance Area
Dozer Avoidance Area
Dozer Avoidance Area
DPA
CAL FIRE
USDA/Forest Service
Lassen-Modoc SRA: 130,858 Acres

VICINITY MAP

BRANCH 9
SUPPRESSION REPAIR MAP

Dixie Incident
CA-BTU-009205
September 10, 2021

0 0.75 1.5 3
Miles
1:40,000
NAD83 TEALE ALBERS

Dixie Incident
CA-BTU-009205
SUPPRESSION REPAIR BRANCH 9
September 10, 2021