SUPPRESSION REPAIR

Overview

Dixie Incident
CA-BTU-009205
07/29/2021

Dixie Incident
CA-BTU-009205
SUPPRESSION REPAIR
07/29/2021

Dixie Incident
CA-BTU-009205
SUPPRESSION REPAIR
07/29/2021

Repair
- Stream Crossing
- Road Repair
- Retardant in Avoidance Area
- Resource Location
- Repair Point
- Landing or Log Deck
- Hazard Tree

- Fence - Cut/Damaged
- Dozer Push
- Culvert
- Clean Up Area

Line Repair Status
- Repair Needed,Completed Dozer Line
- Repair Needed,Completed Hand Line
- Unknown,Completed Hand Line
- Unknown,Completed Dozer Line

Ownership
- Bureau of Indian Affairs
- Bureau of Land Management
- CA Dept. of Fish and Wildlife
- Local Government
- National Park Service
- Non-Profit Conservancies and Trusts
- Other Federal Lands
- Other State Lands
- USDA Forest Service

- CAL FIRE
- Local
- National Park Service
- USDA/Forest Service

0 1.5 3 6
Miles

1:109,000

NAD83 UTM 11N