

Dixie Incident
CA-BTU-009205
SUPPRESSION REPAIR
08/08/2021

Air Operations
- Aerial Hazard
- Check Point
- Helispot

Assignment Breaks
- Division Break
- Branch Break

Logistics
- Drop Point
- Staging Area

Fire
- Hot Spot - Spot Fire

Reference
- Other

Repair
- Stream Crossing
- Retardant in Avoidance Area
- Repair Point
- Landing or Log Deck
- Hazard Tree
- Dozer Push
- Culvert

Line Repair Status
- Repair Needed,Completed Dozer Line
- Repair Needed,Completed Hand Line
- Unknown,Completed Dozer Line

Ops Completed
- Completed Dozer Line
- Completed Fuel Break
- H - Completed Hand Line
- R - Completed Road as Line

Ops Planned
- Planned Dozer Line
- H - Planned Hand Line
- R - Planned Road as Line

Reference
- Other

Air Ops
- Retardant Drop

Fire Perimeter
- Fire Edge
- Contained Line

Direct Protection Area
- CAL FIRE
- USDA/Forest Service

Ownership
- Bureau of Land Management
- CA Dept. of Fish and Wildlife
- Local Government
- USDA Forest Service
- World Hillshade

SUPPRESSION REPAIR
BRANCH I/V

Dixie Incident
CA-BTU-009205
08/08/2021

0 0.5 1 2
Miles
1:29,000

Dixie Incident
CA-BTU-009205
SUPPRESSION REPAIR
08/08/2021