Suppression Repair Points
PointType, Repair Status

- Bridge, Repair Needed
- Chipping Slash, Repair Needed
- Chipping Slash, Completed - Approved
- Culvert Damage, Repair Needed
- Culvert Damage, Completed - Approved
- Dozer Push, Repair Needed
- Dozer Push, Completed - Approved
- Drop Point, Repair Needed
- Equipment Found, Repair Needed
- Fence Damage, Repair Needed
- Fence Damage, Completed - Approved
- Gate, Repair Needed
- Gate, Completed - Approved
- Hazard Tree, Repair Needed
- Helispot, Repair Needed
- Log and Scatter Trees, Repair Needed
- Meadow Damage, Repair Needed
- Other, <Null>
- Other, Repair Needed
- Other, Completed - Aproved
- Retardant Track Point, Repair Needed
- Road Needs Repair, Repair Needed
- Road Needs Repair, Completed - Approved
- Water Course Crossing, <Null>
- Water Course Crossing, Repair Needed
- Water Course Crossing, Completed - Approved
- Water Drafting Location, Repair Needed
- Waterbar Needed, Repair Needed
- Waterbar Needed, Completed - Approved

DP-27
DP-26
DP-23
DP-73
DP-75
DP-80
DP-29
Elk Pump Station
Div H
Div I
Div J
Tower Dip
Ivory Mill Saddle
Diamond Ranch Airport
Narrow Culvert <---
Washout <---
STATE DPA
FEDERAL DPA
Road Class shown in fuschia. Not all roads show Road Class values

Mendocino Complex
CA-MEU-008674
September 10, 2018

SUPPRESSION REPAIR
Div I

Repair Legend
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- No Repair Needed
- Other - See Comments
- Repair Needed
- Unknown

- Contained Fire Edge
- Completed Dozer Line
- H - H - H Completed Hand Line
- R - R - R Road as Completed Line
- Direct Protection Areas
- Rehab Avoidance Area

Ownership
- USDA Forest Service
- Bureau of Reclamation
- Bureau of Land Management
- Bureau of Indian Affairs
- Other Federal Lands

SoCal IMT 3 GIS
September 09, 2018
2114

QR Code

Miles
0 0.25 0.5 1

Datum: NAD 83

SOUTHERN CALIFORNIA TEAM 3 INTERAGENCY INCIDENT MANAGEMENT

SUPPRESSION REPAIR, 09/10/18
Div I