

Label	PtType	RepairStatus	Comments	Repair Comment
1	Stream Crossing	Repair Needed	Class 3 dz sing, push clean	
2	Fence - Cut/Damaged	Repair Needed	Cut Fence 3p Pasture Fence	
3	Fence - Cut/Damaged	Repair Needed	Cut Fence 1p Pasture	
4	Fence - Cut/Damaged	Repair Needed	Cut Fence 1p Pasture Fence	
5	Fence - Cut/Damaged	Repair Needed	Cut Fence 3p Pasture	
6	Fence - Cut/Damaged	Repair Needed	Cut Fence 2p, Pasture+2	
7	Stream Crossing	Repair Needed	Dozer Push Dammed Class 2	
8	Stream Crossing	Repair Needed	Dozer Push fn class 2	
9	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence 1 Post	
10	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence 7 Posts	
11	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence	
12	Fence - Cut/Damaged	Repair Needed	1p05+pasture	
13	Fence - Cut/Damaged	Repair Needed	Fence 6p05+pasture	
14	Fence - Cut/Damaged	Repair Needed	Fence 1p2s+pasture	
15	Fence - Cut/Damaged	Repair Needed	Cut Fence 2p4s	
16	Fence - Cut/Damaged	Repair Needed	Cut Fence 0p2s+pasture	
17	Fence - Cut/Damaged	Repair Needed	Cut Fence 5s Barb	
18	Hazard Tree	Repair Needed	Crew Made Hazard Tree	
19	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence	
20	Stream Crossing	Repair Needed	Dozer Push Downstream Side Of Culvert	
21	Fence - Cut/Damaged	Repair Needed	Cut Fence 0p4s	
22	Fence - Cut/Damaged	Repair Needed	Cut Fence 1p4s+pasture	
23	Fence - Cut/Damaged	Repair Needed	Cut HIGH pasture Fence 2p2s+	
24	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence 0p	
25	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence 0p	
26	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence 1p	
27	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence 3p	
28	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence 3p1s+	
29	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence 3p2s+	
30	Fence - Cut/Damaged	Repair Needed	Cut Pasture Fence 5+ Posts	
31	Stream Crossing	Repair Needed	Dozer Cross/push In Class 1 WLPZ	
32	Fence - Cut/Damaged	Repair Needed	Fence Cut 1p1s+pasture	
33	Fence - Cut/Damaged	Repair Needed	High Pasture Fence 0p	
34	Fence - Cut/Damaged	Repair Needed	High Pasture Fence 1p	
35	Fence - Cut/Damaged	Repair Needed	Pasture Fence Pushed Over	
36	Dozer Push	Other - See Comments	Found some dozer activity near Middle Creek.	Probably old dozer activity, area burned over; documented for BAER team. J.Mabe 08/27
37	Repair Point	Repair Needed	Extremely large dozer cleared area. 30 blades by 20 blades.	Pull in berms and veg. Mitigate for erosion. Arch cleared by Hutcheson 8/25
38	Road Repair	Repair Needed	Dozerline intersects existing road	Pavement torn into chunks . Arch cleared by Hutcheson 8/25
39	Repair Point	Repair Needed	Large vegetation push	Large open dozed area 15 blades by 20 blades. Needs chipper or distribute over large open dozed area. Arch cleared by ARCH Hutcheson 8/25
40	Repair Point	Repair Needed	Large open dozed area, 10 blades by 20 blades	Repair to standard . Knock down large berms, spread out trees (some up to 36" duh) Arch cleared by ARCH hutcheson
41	Repair Point	Repair Needed		Clear slash and boulders from creek to re-establish natural flow. Excavator with thumb needed.-REAF Foulk 8/25
42	Dozer Push	Repair Needed		Standard repair. J.Mabe 08/25
43	Dozer Push	Repair Needed		Very large (acre) dozer cleared area. may be safety zone. Standard repair, but may need to be replanted. J.Mabe 08/25
44	Dozer Push	Repair Needed		Big dozer push on existing landing. standard repair. J.Mabe 08/25
45	Repair Point	Repair Needed	Open area 8 blades by 6 blades	Repair to standard. ARCH cleared by ARCH Hutcheson 8/26
46	Repair Point	Repair Needed	Dozer 6 blades by 10 blades	Pull in berms and slash. ARCH cleared by Hutcheson
47	Culvert	Repair Needed	Culvert partially crushed and buried by rocks pushed off road	pull rocks and veg out of drainage. replace culvert. J.Mabe 08/26
48	Stream Crossing	Repair Needed	Drainage area at bottom of meadow. Not deep stream channel, but location where meadow grains out in spring.	Pull soil and other material out of drainage, re-contour to reestablish hydrologic connectivity. J.Mabe 08/26
49	Stream Crossing	Repair Needed	Dozers crossed intermittent stream here and obliterated channel	Romo e debris from channel and re-contour, plant willows the stabilized banks and reduce erosion. High priority. J.Mabe 08/26
50	Stream Crossing	Repair Needed	Dozer pushed across channel and buried channel.	Remove debris and re-contour to reestablish channel, plant willows to stabilize. J.Mabe 08/26
51	Stream Crossing	Repair Needed	Dozer crossed intermittent channel and obliterated channel	Pull debris out of channel and re-contour. J.Mabe 08/26.
52	Stream Crossing	Repair Needed	Dozer crossed and buried intermittent channel.	Pull debris out of channel and re-contour, plant willows to stabilize banks and reduce erosion. High priority. J.Mabe 08/26.
53	Stream Crossing	Repair Needed	Dozers pushed across drainage at bottom of small meadow, needs to be fixed to reconnect hydrology.	Remove soil and debris, re-contour and add rock to stabilize crossing. J Mabe 08/26
54	Dozer Push	Repair Needed	Big dozer push for safety zone.	Standard repair, pull back debris and cover with slash and down trees. J.Mabe 08/26
55	Stream Crossing	Repair Needed	dozer line crosses intermittent stream	Dozer lifted blade. water bar access
56	Dozer Push	Unknown	Dozer push off road into meadow	Pull back soil and knock down berms. re-contour to reestablish hydrologic connection. High priority. J.Mabe 08/26
57	Dozer Push	Unknown		1x2 chains. Mostly flat. Priority 3. Pull back berms. REAF Foulk 8/26.
58	Dozer Push	Unknown		1x1 chains.-REAF Foulk 8/26

Suppression Repair
CALDOR INCIDENT
CA ENF 024030
August 28, 2021

1:59,454

Datum: NAD 83

0 1¾ 3½ 7 Miles

Suppression Repair

Caldor Incident

CA ENF 024030

August 29, 2021

Aerial Hazard
Check Point
Dip Site
Mobile Retardant Base
Helispot
Helibase
Sling Site
Division Break
Branch Break
Drop Point
Staging Area
Hot Spot - Spot Fire
Fire Origin
Stream Crossing
Road Repair
Repair Point
Landing or Log Deck
Dozer Push
Culvert
Mobile Weather Unit
Repeater
Water Source
Completed Dozer Line
Completed Fuel Break
H - Completed Hand Line
R - Completed Road as Line
Planned Dozer Line
H - Planned Hand Line
Access or Improved Road
Contained Line

Polygon Type
Wildfire Daily Fire Perimeter

Repair Status Point
Completed - Inspected
In Use - Fire Management
Completed - Ready for Inspection
In Progress
Repair Needed
No Repair Needed
Other - See Comments
Unknown

Repair Status Line
Completed - Inspected
In Use - Fire Management
Completed - Ready for Inspection
In Progress
Repair Needed
No Repair Needed
Other - See Comments
Unknown

DISCLAIMER:
The displayed incident data is approximate and should only be used for informational purposes. The information contained in supporting base layers was generated from GIS data maintained by different sources and agencies and is not necessarily accurate to mapping, surveying, or engineering standards.

IMT 6 GIS
8/29/2021
0055 Hours

Suppression Repair
CALDOR INCIDENT
CA ENF 024030
August 29, 2021