Suppression Repair Zone Map

Walker Fire
Div Q, V & X

CA-PNF-001324

09/25/2019

California Interagency Incident Management Team 10

ACE Q V X
F G I K M

N

0 0.5 Miles

- Fence - Cut/Damaged
- Stream Crossing
- Dozer Push
- Dip Site
- Drop Point
- Staging Area
- Water Source
- Repair Point
- Other
- Zone Break
- Division Break
- Completed Dozer Line
- Completed Line
- Completed Hand Line
- Road as Completed Line
- Access or Improved Road
- Repair Line
- Other
- Non-FS
- Repair Needed
- Completed - Inspected
- Unknown
- Repair by Hand
- Special Treatment Area

DP-12

DP-31

Antelope Dip

Cottonwood Dip

DIV X

DIV V

DIV Q

DIV M

Repair with excavator

Debris was pushed into stream and will need to be removed.

Single blade width, T3 excavator

This is a sensitive resource area. A hand crew will be needed for repair with a Resource Advisor and Archaeologist present to guide the repair needs.

Repair with excavator

Round Mountain Dozer push to the west. ARCH WINGATE 9/24/19

Clear material from culvert outlet.

Large push pile- berm up ti 10 ft high

100 ft wide push 10 ft depth

Ramp/ disperse berms and restore pre-existing drainage. Spread brush. READ DRAKE 9.24

Single blade. Open country. Repair with any size excavator. READ DRAKE 9.24

Single blade. Open country. Any size excavator suitable. READ DRAKE 9.24.19

Single blade. Multiple spurs. READ DRAKE 9.24

READ DRAKE 9.23: Repair with type 3 or 4 excavator. READ Immaker: Sept 20 mostly on private but authorized for repair.

READ DRAKE 9.23: REPAIR WITH type 3 or 4 excavator. Repair on private land authorized.

READ DRAKE 9.23: REPAIR WITH type 3 or 4 excavator.

Requires scouting. May not exist. READ DRAKE 9.23

Single blade repair with excavator. READ DRAKE 9.23

Repair east of red and black flagging with ARCH present. Preferably with hand crew. READ RAY 9.22. Dozerline from road to steam channel. Hydrologist needed for repair. READ DRAKE. 9.24