

Repair Status South Zone

August Complex
CA-MNF-000753
5/17/2021

N

0 0.5 1 2 Miles

Current as of: 5/17/2021
NAD83 UTM Z10N

Aerial Hazard
Dip Site
Helispot
Sling Site
Division Break
Zone Break
Drop Point
Camp
Value at Risk
Other
Landmark
Gate
Bridge
Structure Wrap
Stream Crossing
Road Repair
Resource Location
Repair Point
Hazard Tree
Fence - Cut/Damaged
Dozer Push
Culvert
Clean Up Area
Mobile Weather Unit
Repeater
Safety Zone
Hazard
Water Source
Restricted Water Source
Completed Dozer Line
Completed Hand Line
Access or Improved Road
Fence
Repair Line
Road Repair
Road as Completed Line
Completed - Inspected (46)
Completed - Ready for Inspection (3)
In Progress (11)
Repair Needed (182)
No Repair Needed (10)
Other - See Comments (3)
Unknown (43)
Completed - Inspected (495)
Completed - Ready for Inspection (27)
In Progress (152)
Repair Needed (519)
No Repair Needed (137)
Other - See Comments (22)
Unknown (26)
Bureau of Land Management
Forest Service
Indian Reservation
State
Roads
0 - Not Maintained
1 - Basic Custodial Care (CLOSED)
2 - 5 (OPEN)
Private or County