# Courtney Incident
# CA-MMU-016429
# September 18, 2014

# Operations Map DINS

- Outbuilding - Destroyed
- Outbuilding - Damaged
- Single Family Residence - Destroyed
- Single Family Residence - Damaged
- Fire Perimeter
- Parcel Lines

NAD 83

1:1,000

Feet

0 225 450

TTT
September 18 2014
0800 hours

119°35'0"W

37°19'0"N

| ID | | ADDRESS | APN | YR Built | Land val | Improved | Damage | Destroyed |
|---|---|---|---|---|---|---|---|---|
| 1 | 52870 | ROAD 426 | 06039-059-081-016 | 1946 | 22983 | 33477 | | 100 |
| 2 | 52851 | ROAD 426 | 06039-059-081-024 | 1956 | 110499 | 210953 | | 100 |
| 3 | 52851 | ROAD 426 | 06039-059-081-024 | 1956 | 110499 | 210953 | | 100 |
| 4 | 52851 | ROAD 426 | 06039-059-081-024 | 1956 | 110499 | 210953 | | 100 |
| 5 | 52986 | ARBOR LN | 06039-059-081-025 | 1975 | 128714 | 299055 | | 100 |
| 6 | 52905 | ROAD 426 | 06039-059-082-005 | 1962 | 74221 | 203179 | | |
| 7 | 52920 | ROAD 426 | 06039-059-082-009 | | | | | |
| 8 | | | 06039-059-082-011 | | | | | |
| 9 | | | 06039-059-082-012 | | | | | |
| 10 | 52946 | ROAD 426 | 06039-059-082-013 | | | | | |
| 11 | 52992 | ROAD 426 | 06039-059-082-014 | | | | | |
| 12 | | | 06039-059-082-015 | | | | | |
| 13 | | | 06039-066-190-002 | | | | | |
| 14 | | | 06039-059-062-014 | | | | | |
| 15 | | | 06039-059-081-011 | | | | | |
| 16 | 52742 | ROAD 426 | 06039-059-081-012 | 1980 | 38209 | 172911 | | 100 |
| 17 | 52766 | ROAD 426 | 06039-059-081-013 | | | | | |
| 18 | 52772 | ROAD 426 | 06039-059-081-015 | 1996 | 70846 | 306209 | | |
| 19 | 52772 | ROAD 426 | 06039-059-081-015 | 1996 | 70846 | 306209 | 10 | |
| 20 | 52772 | ROAD 426 | 06039-059-081-015 | 1996 | 70846 | 306209 | | 100 |
| 21 | 52772 | ROAD 426 | 06039-059-081-015 | 1996 | 70846 | 306209 | | |
| 22 | 52772 | ROAD 426 | 06039-059-081-015 | 1996 | 70846 | 306209 | | |
| 23 | 52772 | ROAD 426 | 06039-059-081-015 | 1996 | 70846 | 306209 | | |
| 24 | 52772 | ROAD 426 | 06039-059-081-015 | 1996 | 70846 | 306209 | | |
| 25 | 52772 | ROAD 426 | 06039-059-081-015 | 1996 | 70846 | 306209 | | |
| 26 | 52891 | ARBOR LN | 06039-059-081-017 | | | | | |
| 27 | 52915 | ARBOR LN | 06039-059-081-018 | | | | | |
| 28 | 52933 | ARBOR LN | 06039-059-081-019 | | | | | |
| 29 | 52977 | ARBOR LN | 06039-059-081-022 | 2006 | 109683 | 288346 | | 100 |
| 30 | 52760 | BALSAM DR | 06039-059-100-002 | | | | | |
| 31 | 52623 | ROAD 426 | 06039-059-100-022 | | | | | |
| 32 | 52703 | ROAD 426 | 06039-059-110-001 | 1950 | 68260 | 152732 | | 100 |
| 33 | 52703 | ROAD 426 | 06039-059-110-001 | 1950 | 68260 | 152732 | | 100 |
| 34 | 39275 | MANZANITA DR | 06039-059-110-002 | 1972 | 9983 | 49533 | | |
| 35 | 39275 | MANZANITA DR | 06039-059-110-002 | 1972 | 9983 | 49533 | | 100 |
| 36 | 39275 | MANZANITA DR | 06039-059-110-002 | 1972 | 9983 | 49533 | | 100 |
| 37 | 39291 | MANZANITA DR | 06039-059-110-003 | 1961 | 54985 | 127872 | 10 | |
| 38 | 39303 | MANZANITA DR | 06039-059-110-004 | | | | | |
| 39 | 39333 | MANZANITA DR | 06039-059-110-007 | 1979 | 45164 | 122216 | | 100 |
| 40 | 39345 | MANZANITA DR | 06039-059-110-008 | | | | | |
| 41 | 39357 | MANZANITA DR | 06039-059-110-009 | | | | | |
| 42 | 39369 | MANZANITA DR | 06039-059-110-010 | | | | | |
| 43 | 39387 | MANZANITA DR | 06039-059-110-012 | | | | | |
| 44 | 39268 | MANZANITA DR | 06039-059-110-030 | 1965 | 59620 | 194757 | 10 | |
| 45 | 39268 | MANZANITA DR | 06039-059-110-030 | 1965 | 59620 | 194757 | 10 | |
| 46 | 39254 | MANZANITA DR | 06039-059-110-031 | 1966 | 45248 | 101246 | | 100 |
| 47 | | | 06039-059-110-032 | | | | | |
| 48 | 39377 | MANZANITA DR | 06039-059-110-035 | 1958 | 42089 | 111174 | | 100 |
| 49 | | | 06039-059-110-036 | | | | | |
| 50 | | | 06039-059-110-039 | 0 | 33844 | 33844 | | 100 |
| 51 | | | 06039-059-120-001 | | | | | |
| 52 | 52821 | CEDAR DR | 06039-059-120-002 | 1958 | 9546 | 39525 | | 100 |
| 53 | 52821 | CEDAR DR | 06039-059-120-002 | 1958 | 9546 | 39525 | | 100 |
| 54 | 52841 | CEDAR DR | 06039-059-120-003 | 1952 | 68500 | 146594 | | 100 |
| 55 | 52841 | CEDAR DR | 06039-059-120-003 | 1952 | 68500 | 146594 | | 100 |
| 56 | 52841 | CEDAR DR | 06039-059-120-003 | 1952 | 68500 | 146594 | | 100 |
| 57 | 52861 | CEDAR DR | 06039-059-120-004 | 1964 | 8898 | 50810 | | 100 |
| 58 | 52861 | CEDAR DR | 06039-059-120-004 | 1964 | 8898 | 50810 | | 100 |
| 59 | 52879 | CEDAR DR | 06039-059-120-005 | 1944 | 16936 | 42739 | | 100 |
| 60 | 52899 | CEDAR DR | 06039-059-120-006 | 1985 | 56643 | 240732 | | 100 |
| 61 | 52899 | CEDAR DR | 06039-059-120-006 | 1985 | 56643 | 240732 | | 100 |
| 62 | 52937 | CEDAR DR | 06039-059-120-007 | | | | | |
| 63 | 52937 | CEDAR DR | 06039-059-120-008 | 1962 | 25615 | 116294 | | 100 |
| 64 | 52959 | CEDAR DR | 06039-059-120-009 | 1956 | 47076 | 97094 | | 100 |
| 65 | 39249 | OAK DR | 06039-059-120-010 | | | | | |
| 66 | 39239 | OAK DR | 06039-059-120-011 | | | | | |
| 67 | 39219 | OAK DR | 06039-059-120-012 | 1957 | 40985 | 74797 | 10 | |
| 68 | 39199 | OAK DR | 06039-059-120-013 | 1976 | 51488 | 161833 | | 100 |
| 69 | 39179 | OAK DR | 06039-059-120-014 | 1950 | 8899 | 29617 | 10 | |
| 70 | | | 06039-059-120-015 | | | | | |
| 71 | 52936 | PINE DR | 06039-059-120-017 | 1965 | 26768 | 107123 | | 100 |
| 72 | 52936 | PINE DR | 06039-059-120-017 | 1965 | 26768 | 107123 | | 100 |
| 73 | 52924 | PINE DR | 06039-059-120-018 | 1963 | 70317 | 205929 | | 100 |
| 74 | 52912 | PINE DR | 06039-059-120-019 | | | | | |
| 75 | | | 06039-059-120-020 | | | | | |
| 76 | 52830 | PINE DR | 06039-059-120-021 | 1958 | 55351 | 100282 | | 100 |
| 77 | 52830 | PINE DR | 06039-059-120-021 | 1958 | 55351 | 100282 | | 100 |
| 78 | | | 06039-059-120-022 | | | | | |
| 79 | 52743 | ROAD 426 | 06039-059-120-023 | | | | | |
| 80 | 52735 | ROAD 426 | 06039-059-120-024 | 1969 | 73560 | 176548 | | 100 |
| 81 | 52735 | ROAD 426 | 06039-059-120-024 | 1969 | 73560 | 176548 | | |
| 82 | 52820 | CEDAR DR | 06039-059-120-025 | 1998 | 63916 | 178965 | | 100 |
| 83 | | | 06039-059-120-028 | | | | | |
| 84 | 52884 | CEDAR DR | 06039-059-120-029 | | | | | |
| 85 | 39240 | OAK DR | 06039-059-120-030 | 1970 | 19475 | 83096 | 10 | |
| 86 | 39240 | OAK DR | 06039-059-120-030 | 1970 | 19475 | 83096 | | |
| 87 | 39220 | OAK DR | 06039-059-120-031 | | | | | |
| 88 | 39200 | OAK DR | 06039-059-120-032 | | | | | |
| 89 | 39180 | OAK DR | 06039-059-120-033 | | | | | |
| 90 | 52931 | PINE DR | 06039-059-120-034 | | | | | |
| 91 | 52899 | PINE DR | 06039-059-120-035 | | | | | |
| 92 | 52873 | PINE DR | 06039-059-120-036 | | | | | |
| 93 | 52849 | PINE DR | 06039-059-120-037 | | | | | |
| 94 | 52976 | PINE DR | 06039-059-120-038 | 1978 | 53162 | 214430 | | 100 |
| 95 | 52956 | PINE DR | 06039-059-120-039 | 1953 | 9983 | 60523 | | 100 |
| 96 | 52842 | CEDAR DR | 06039-059-120-040 | 1991 | 78269 | 172192 | | 100 |
| 97 | 52842 | CEDAR DR | 06039-059-120-040 | 1991 | 78269 | 172192 | | 100 |
| 98 | 52862 | CEDAR DR | 06039-059-120-041 | 1954 | 96151 | 160764 | | 100 |
| 99 | 52862 | CEDAR DR | 06039-059-120-041 | 1954 | 96151 | 160764 | | 100 |
| 100 | 52648 | ROAD 426 | 06039-059-230-003 | 1958 | 76726 | 143860 | | 100 |
| 101 | 52648 | ROAD 426 | 06039-059-230-003 | 1958 | 76726 | 143860 | | 100 |
| 102 | 52682 | ROAD 426 | 06039-059-230-004 | 1979 | 23284 | 87048 | | 100 |
| 103 | 52682 | ROAD 426 | 06039-059-230-004 | 1979 | 23284 | 87048 | | 100 |
| 104 | 52632 | ROAD 426 | 06039-059-230-024 | 1959 | 28253 | 110033 | | 100 |
| 105 | 52632 | ROAD 426 | 06039-059-230-024 | 1959 | 28253 | 110033 | | 100 |
| 106 | 39215 | SKYLINE DR | 06039-059-230-028 | 1999 | 91025 | 432428 | | 100 |
| 107 | | | 06039-059-230-029 | | | | | |
| 108 | 39296 | SKYLINE DR | 06039-059-230-030 | | | | | |
| 109 | 39339 | SKYLINE DR | 06039-059-230-031 | | | | | |
| 110 | 52602 | ROAD 426 | 06039-059-230-032 | 1988 | 54941 | 270682 | | |
| 111 | | | 06039-059-230-033 | | | | | |