DIV E

DIV C

H-22

IRAWS 51

PRAWS 6

DP53

Road Closed - Impassable

CMD 47

Road Closed - Impassable

Francis Junction Cow Camp

Stump Dip

DP51

DP50

H-15

DP45

DP43

Peckinpah Meadow Cow Camp

DP41

Roush Cabin

DP40

CMD 50

Fork Dip

North Fork HS

DP37

waypoint

81

Repair Status Point
- Completed - Inspected
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown

Repair Status Line
- Completed - Inspected
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown
- Aerial Hazard

- Bridge
- Clean Up Area
- Closure
- Culvert
- Dip Site
- Drop Point
- Dozer Push
- Gate
- Hazard
- Hazard Tree
- Unimproved Landing Area
- Helispot
- Internet Access
- Landing or Log Deck
- Mobile Weather Unit
- Repair Point
- Repeater
- Resource Location
- Road Repair
- Safety Zone
- Staging Area
- Stream Crossing
- Structure Wrap
- Water Source
- Value at Risk
- Other
- Division Break
- Branch Break
- Contained Line
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Access or Improved Road
- Completed Plow Line
- Aerial Retardant Drop
- Air Tanker Retardant
- Ridge/Geographic Feature
- Repair Line
- Road Repair
- Other
- National Forest Boundary
- USDA Forest Service
- Private Lands within the Forest Boundary
- Bureau of Indian Affairs

Branch XIX, Branch XX, Branch XXI, Branch XXV

0 0.5 1 2 Miles

Scale: 1:35,000

Name: NAD 1983 California Teale Albers

Contours 40 ft