Suppression Repair

Beachie Creek
ORWIF-200299

Riverside
ORMHF-000859

Riverside 5

10/13/20
Page: 5

- Division Break
- Drop Point
- Landing or Log Deck
- Repeater
- Completed - Inspected
- Repair Needed
- No Repair Needed
- Campground
- Trailhead

Label Point 2020_GISS_Edit
- State Highway
- Major road
- Intermediate road
- Minor road
- Decommissioned or Closed
- BPA Transmission Lines
- County Boundary
- Structures
- Completed Dozer Line
- Road as Completed Line
- Access or Improved Road
- Line Break Completed

- Planned Fire Line
- Other
- Completed - Inspected
- In Use - Fire Management
- In Progress
- Repair Needed
- Unknown
- Wildfire Daily Fire Perimeter
- Ranger District Boundaries
- Forest Service Wilderness Area
- U.S. Forest Service
- Private/Unknown

FC Point Type	Repair Status	Repair Comments	Label
Drop Point	Completed - Inspected		DP-101
Drop Point	No Repair Needed		DP-100
Drop Point	No Repair Needed		DP-102
Drop Point	No Repair Needed		DP-106
Drop Point	No Repair Needed		DP-110
Drop Point	No Repair Needed		DP-111
Drop Point	No Repair Needed		DP-112
Drop Point	No Repair Needed		DP-65
Drop Point	Repair Needed		DP-114
Landing or Log Deck			4611-10
Landing or Log Deck			4611-14
Landing or Log Deck			4611-15
Landing or Log Deck			4611-16

FC Point Type	Repair Status	Repair Comments	Label
Landing or Log Deck			4611-17
Landing or Log Deck			4611-18
Landing or Log Deck			4611-19
Landing or Log Deck			4611-20
Landing or Log Deck			4611-4
Landing or Log Deck			4611-5
Landing or Log Deck			4611-6/7
Landing or Log Deck			4611-8
Landing or Log Deck			4611-9
Landing or Log Deck	No Repair Needed		4611-12
Landing or Log Deck	No Repair Needed		4611-13
Repeater	Repair Needed		CMD R-8

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Unknown		780
Road as Completed Line	Repair Needed	Chipper needed after fire-M. DeAngelo Sep 19, 2020. Equipment currently mastiicating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	6562
Road as Completed Line	In Progress	Significant merch. Slash piles will need to be disposed of. Flush cut pungees and stumps where needed. Chipping needed.	13206
Road as Completed Line	In Progress	Chipping needed	20497
Road as Completed Line	Completed - Inspected	10/10/2020mkeil_nifc-Per robertsanders_nifc Inspected 10/09/2020 Completed. unknown datesdillavou-Completed fuel break. Unknown date unkown collector-light chipping needed	420
Road as Completed Line	Completed - Inspected	Sweeping of debris	1440
Road as Completed Line	Completed - Inspected	Logs in ditch need to be removed. Chip smaller material. Berms need to be knocked down. Rocky debris behind shoulder needs additional repair	2083
Road as Completed Line	Completed - Inspected	10/10/2020mkeil_nifc-Per robertsanders_nifc Inspected 10/09/2020 Completed. unknown datesdillavou-Completed fuel break	3160
Road as Completed Line	Completed - Inspected	10/10/2020mkeil_nifc-Per robertsanders_nifc Inspected 10/09/2020 Completed. unknown datesdillavou-Completed fuel break	4331
Road as Completed Line	Completed - Inspected	Sweeping of debris and light chipping need at intersection of DP 102	4408
Road as Completed Line	Completed - Inspected	Chipping needed to clear ditches	11645
Road as Completed Line	Completed - Inspected	Chipping needed north of Shellrock Campground	13312
Planned Fire Line	Unknown		464
Planned Fire Line	Repair Needed	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	17307
Planned Fire Line	Repair Needed	Chipping needed	20841
Planned Fire Line	In Use - Fire Management	Road grading, remove berms, repair cut and fill slopes (marked separately), and chipping -Suing. Robert Sanders: stumps, slash, berm and grading underway 10/7/20. Div o.o says done by 10/9	24812
Planned Fire Line	In Progress	Chipping needed	20841
Planned Fire Line	Completed - Inspected	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch	17307
Planned Fire Line	Completed - Inspected	Chipping needed throughout NF 58 and entry to NF 5830 and NF 150. Crews needed to sweep debris.	40153
Other	Unknown		257
Other	Unknown		479

FC Line Type	Repair Status	Repair Comments	Length Feet
Other	Unknown		493
Other	Unknown		519
Other	Unknown		598
Other	Unknown		813
Other	Unknown		827
Other	Unknown		1312
Line Break Completed	Completed - Inspected	Light chipping and sweeping needed	1140
Completed Dozer Line	Repair Needed	Robert Sanders: the road edge is chewed up from machines and parking. seed and/or slash. same treatment around log deck	506
Completed Dozer Line	Completed - Inspected	Pull in berms, may not be needed until log deck is removed	194
Access or Improved Road	Unknown		29
Access or Improved Road	Unknown		155
Access or Improved Road	Unknown		341
Access or Improved Road	Unknown		479
Access or Improved Road	Unknown		576
Access or Improved Road	Unknown		601
Access or Improved Road	Unknown		842
Access or Improved Road	Unknown		2043
Access or Improved Road	Unknown		2241
Access or Improved Road	Unknown		6158
Access or Improved Road	Unknown		8554
Access or Improved Road	Unknown		20630

0 0.5 1 2
Miles

NORTHWEST INCIDENT MANAGEMENT TEAM NW 8

N

1:33,000 - - 10/12/2020 2031
Acres from GIS
North American 1983 Datum. LatLong Grid