Feature Category (Point Type)	Comments	Latitude WGS84 DDM	Longitude WGS84 DDM
Pump		33° 20.946' N	108° 04.794' W

FC Line Type	Comments	Repair Comments	Repair Priority	ARCH Clearance
Access or Improved Road	Dead end potentially connect with Dozer		Unknown	Not Cleared
Access or Improved Road	Posted private property, Cox Ranch 743-9604. Need permission to access.		Unknown	Not Cleared
Access or Improved Road			Unknown	Not Cleared
Access or Improved Road			Unknown	Not Cleared
Access or Improved Road			Unknown	Not Cleared
Completed Burnout	Hand ignitions		Unknown	Not Cleared
Completed Dozer Line	Repair complete	6/15: old road tank trapped @ road/gate and waterbarred. Needs seeding...	Unknown	Not Cleared
Completed Dozer Line	Completed by Land Owner		Unknown	Not Cleared
Completed Dozer Line	Completed by Land Owner		Unknown	Not Cleared
Completed Dozer Line	Structure protection		Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		Very rocky unable to water bar.	Unknown	Not Cleared
Completed Dozer Line			Medium	Cleared for Mechanical Repair
Completed Dozer Line	J.Ayers,06/16/22, ARCH	Pull berm. Waterbar. Slash track hoe better tool. Reseed	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		North Star 4. Waterbar, pull berm. Reseed. Not much slash. Pull large material from green side to block access.	Unknown	Cleared for Operations
Completed Dozer Line	J.Ayers,06/15/22,ARC	6/15: seeded, tank trapped, water barred, smoothed berms	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		Waterbar, cover w slash, knock down dozer berms, block access from campsite. Reestablish drainage near bottom	High	Cleared for Operations
Completed Dozer Line		Seeded. North Star 2. Will need machinery. Need to dis courage vehicle use post rehab 6/18: ripped, berms smoothed, tank trapped & blocked, slash placed in line	Unknown	Not Cleared
Completed Dozer Line		Repair will need equipment; steep so excavator w/thumb recommended		Cleared for Operations
Completed Dozer Line	Single blade along existing, then pioneers to tie into handline. Mod to heavy piles prepped for chipping	North Star 1	Medium	Cleared for Operations
Completed Dozer Line		seeded and slash placed	Unknown	Not Cleared
Completed Dozer Line	Up to 3 blades wide, ties into hand line. end of dozer line	Bloodgood 1. May need to reseed upper part where there is little slash	High	Not Cleared
Completed Dozer Line		Has been seeded; 6/19: berms smoothed access blocked with spread slash inside treeline	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		Fairly float, line reseeded	Medium	Cleared for Mechanical Repair
Completed Dozer Line	Single blade dozerline, heavy piles of prepped line	McKnight 0. 6/19: berms are smoothed, handcrew has done waterbars	High	Not Cleared
Completed Dozer Line	Single track dozerline.	FSR 152A	High	Not Cleared
Completed Dozer Line	Single blade dozer, crosses blueline	FSR 152 B	High	Cleared for Operations
Completed Dozer Line		North Star 3. 6/18: berms knocked down, slash over line, entrance blocked, seeded	Unknown	Cleared for Operations
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line	Very light scrape in meadow and used as road access	6/17: Seeding complete	Unknown	Not Cleared
Completed Dozer Line	Not a fireline, just needed for access.	FST 980 B	Unknown	Not Cleared
Completed Dozer Line	needs material pulled onto line	seeding needed	Unknown	Not Cleared
Completed Dozer Line		Needs repair	High	Not Cleared
Completed Dozer Line		spread bio mass pull in burms water bars.	High	Not Cleared
Completed Dozer Line			High	Not Cleared
Completed Dozer Line		Part of North Star 4	Unknown	Not Cleared
Completed Dozer Line		Water bar per rehab specs. On a 37-40% slope.. pull existing slash over line, especially at road intersections	Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		Water bar and pull slash per rehab specs.6/21: inspected, needs waterbars and slash covering uphill section intersecting road	Unknown	Not Cleared
Completed Dozer Line	J.Ayers,06/14/22,ARC		Unknown	Cleared for Hand Crew Repair
Completed Dozer Line	J.Ayers,06/14/22, ARCH	6/19: waterbarred, slash scattered over line	Unknown	Cleared for Mechanical Repair
Completed Dozer Line	J.Ayers,06/16/22,ARC		Unknown	Cleared for Mechanical Repair
Completed Dozer Line		Dozer had to walk around rock drop off and push up slope from drainage bottom.	Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line	J.Ayers,06/16/22,ARC	water bars, knock down berms, more slash if possible	Unknown	Cleared for Mechanical Repair
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		Repaired dozer burns in creek bottom (jreimers_nifc 6/20)	Unknown	Not Cleared
Completed Dozer Line	Hand drawn based on READ Chamberlain	FSR 152 C	High	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		No repair needed per landowner request	Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		reseed with grass, pull in burm, hay bales recommended for erosion control.	High	Not Cleared
Completed Dozer Line		Water bar per rehab specs. On a 37-40% slope.. pull existing slash over line, especially at road intersections	Unknown	Not Cleared

FC Line Type	Comments	Repair Comments	Repair Priority	ARCH Clearance
Completed Hand Line		None needed	Unknown	Not Cleared
Completed Hand Line		6/15: handline obliterated	Low	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line		6/20: obliterated, slash covered, flagging removed	Unknown	Not Cleared
Completed Hand Line	This is hand line not drive able in a vehicle please delete road as line where the handline is		Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line		6/17: seeded	Unknown	Not Cleared
Completed Hand Line	Improved existing trail		Unknown	Not Cleared
Completed Hand Line		6/19: pulled berms back, waterbarred, seeded, and slash over line	Unknown	Not Cleared
Completed Hand Line	Line for Wilson Lodge burnout. Plumbed		Unknown	Not Cleared
Completed Hand Line		Look for areas in the rocky section to get water off fire line. Do not stack large material.	Unknown	Not Cleared
Completed Hand Line			Medium	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Plumbed handline from structure #6 to two track road 6/19: no longer plumbed	Seed, spread debris back over line	Medium	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Tied into natural barrier that ties into black			Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Snagging needed minimal prep, line in place (existing)		Unknown	Not Cleared
Completed Hand Line	handline off end of dozer line		Low	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Completed 6/8/2022.		Unknown	Not Cleared
Completed Hand Line		6/17: seeding complete	Unknown	Not Cleared
Completed Hand Line	Planned handline. Fuel break from silver		Unknown	Not Cleared
Completed Hand Line	Handline along private property fence.	6/21: inspected and complete	Unknown	Not Cleared
Completed Hand Line	Connects rocky section of Dozer line.		Unknown	Not Cleared
Completed Hand Line		6/21: non-trail sections obliterated and trail sections reestablished	Unknown	Not Cleared
Completed Hand Line	6/16: dozer working tracking east from Escondido to cottonwood Well. Reassess		Unknown	Not Cleared
Completed Hand Line	From dozer line, east along fence line then turning south to Hwy 152.	6/21: inspected and repair complete	Unknown	Not Cleared
Completed Hand Line	Cleared brush off fence line and scraped fuels away from wood fence stays and posts. Follows a cow trail against the fence where it makes a V on the east portion. Prep work ends on the east side at a fence corner, 1,000 ft from N. Percha Rd..	6/21: Inspected and no repair necessary.; Crews just cleared vegetation along fence line and a light scrape around some wooden posts.	Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Hand line with brushing	Scatter back over line. 6/21: inspected	Unknown	Not Cleared
Completed Hand Line	Handlined around residence 9902 and 9906.	6/21: handline rehabbed, line obliterated and slash/ berms spread over line	Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	The dog leg in the SE portion needs to be rerouted slightly to avoid being over slung at mid-slope.	Rehab completed 6/19. 6/21: inspected and complete	Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Handline around Work Station main building and barn.		Unknown	Not Cleared
Completed Mixed Construction Line			Unknown	Not Cleared
Completed Mixed Construction Line	Road improved by single blade dozer. Light Brush cut and prepped for chipping		Unknown	Not Cleared
Completed Mixed Construction Line	Prepped line along existing 2 track		Unknown	Not Cleared
Completed Mixed Construction Line	Potential check line, single dozer line	6/19: tank trapped @ entrance, berms smoothed, slash covering line	Unknown	Not Cleared
Completed Mixed Construction Line			Unknown	Not Cleared
Completed Mixed Construction Line	Mostly all two track road that was never improved or prepped. It is in the same condition as before the incident.		Unknown	Not Cleared
Completed Mixed Construction Line	Road improvements with DOZ.		Low	Not Cleared
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC	Spoke to landowner (Solapek) regarding rehab spec. He approved of completed work.	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC	Repaired to landowner specs added Waterbars where needed (jreimers_nifc 6/20)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC No repair recommended - road in good shape. (amckeith_nifc 6/19)		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC Minimal repair needed. Smoothed section of existing road. (amckeith_nifc 6/19)		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC Tracked through. No repair to existing road required. (amckeith_nifc 6/19/22)		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC No repair recommended. Existing road in good shape. (amckeith_nifc 6/19)		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC Existing ranch road, improved with water bars. (amckeith_nifc 6/17)	Minimal dozer push from fire ops on existing ranch road. Improved with water bar installations to limit erosion.	Unknown	Cleared for Mechanical Repair

FC Line Type	Comments	Repair Comments	Repair Priority	ARCH Clearance
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC Water bar construction on steep section of dozer push (amckeith_nifc 6/19)		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC Road smoothing and water bar installation (amckeith_nifc 6/19)	Repaired to	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC With burn out off rd	Repaired to landowner specs added Waterbars where needed (jreimers_nifc 6/20)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line			Unknown	Not Cleared
Completed Mixed Construction Line			Unknown	Not Cleared
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC With burn out off rd	Repaired with Waterbars	Unknown	Cleared for Mechanical Repair
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		6/19: chipping 3/4 complete, should be complete 6/20	Unknown	Not Cleared
Completed Road as Line	6/15: brushed and prepped for chipping.		Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Old road used as line, no improvements made. Ties into handline		Unknown	Not Cleared
Completed Road as Line		6/19: graded	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Existing two track roads		Unknown	Not Cleared
Completed Road as Line	Existing two track roads		Unknown	Not Cleared
Completed Road as Line	Existing two track roads	6/19: no improvements made, gate is shut	Unknown	Not Cleared
Completed Road as Line	Existing two track roads	6/19: No suppression improvements, no repair needed	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		6/19: bladed where possible	Unknown	Not Cleared
Completed Road as Line		6/19: bladed completed where possible	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		Keep slash out of road. End of road is circle drive.	Unknown	Not Cleared
Completed Road as Line	Improved nonused road,		Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Existing road 150	Existing road, no dozerline, grading recommended	Unknown	Not Cleared
Completed Road as Line	Checkline	6/19: Berms smoothed, cowboy gate closed (needs new stays), slash spread at entrance	Unknown	Not Cleared
Completed Road as Line		6/19: chipping and lop/spread underway. ;Approxima 5 1/2 miles of mostly continuous slash. Chipper inaccessible.	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		6/18: graded	Unknown	Not Cleared
Completed Road as Line	Lopped and prepped for chipping		Unknown	Not Cleared
Completed Road as Line	graveled road. Prepped slash on east side. Prepped chipping piles on west side	6/19: chipper and hand crew working north along road spreading and chipping. crewwo	Unknown	Not Cleared
Completed Road as Line		Chipping needed at Mile Marker 30, just below Wright's Cabin and at Mile Marker 31.	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Hwy 152.	Need to chip slash from DP-140 to DP-141 at Lower Gallinas Campground. 3 chippers observed on this section of highway.	Unknown	Not Cleared
Completed Road as Line	Contingency line. Thinned fuel break along highway. Slash being chipped.	Crews currently chipping. 6/21: chipping complete and inspected	Unknown	Not Cleared
Completed Road as Line	Contingency line. Trees thinned/limbed sporadically as needed and where feasible.	Debris and slash is removed from roadway. 6/21: chipped and scattered off roadway	Unknown	Not Cleared
Completed Road as Line	Road prepped 30' to 40' on Fire side.	Chip slash.	Unknown	Not Cleared
Completed Road as Line		The lower end, in the pinyon, with a high amount of slash. 6/21: slash scattered, no sig impacts to road	Unknown	Not Cleared
Completed Road as Line	Hwy 152	6/21: chipping complete and inspected	Unknown	Not Cleared
Completed Road as Line	Brushed, piled and prepped for chipper	Chipper recommended. 6/21: chipping complete and inspected	Unknown	Not Cleared
Completed Road as Line	522 Road. Improved road travel conditions with some water turnouts. Road bladed. No veg prep work but is in scattered junipers and grass.	Much of the road has flat blade work with berms on each side of the road which will channel water. Add or reinstall water turn outs and rolling grade dips, particularly on the steeper sections.	Unknown	Not Cleared
Completed Road as Line	Prepped and chipped both sides 6/16/22	Chipping completed 6/18. No further repairs should be needed. 6/21: inspected and complete	Unknown	Not Cleared
Completed Road as Line	Lanford Repair		Unknown	Not Cleared
Completed Road as Line	Fuels reduction on the south side of the road. Road passible by truck and Type 6 engine. Small turnaround spot at the end of the road.	Chipping and back haul completed 6/19. 6/21: inspected and chipping complete and inspected	Unknown	Not Cleared
Other	ATV UTV trail		Unknown	Not Cleared
Other			Unknown	Not Cleared
Other	If fire reaches this point consider bringing fire south from Apache peak trail / hand line South to the next viable check feature.		Unknown	Not Cleared
Other	Don't show on map yet. Two-track road, narrow, grown over with grass. Very rough. Do not recommend a truck. Could be opened up with a dozer or improved as a handline.		Unknown	Not Cleared
Other	Access to "Black Range Ranch". Narrow road. Limited turnaround spots.		Unknown	Not Cleared
Repair Line			Unknown	Not Cleared
Road Repair		Spoke to landowner (Solapek) regarding rehab spec. He approved of completed work.	Unknown	Not Cleared
Road Repair			Unknown	Not Cleared
Road Repair	Left open per landowners request. Smoothed road bed for better UTV access		Unknown	Not Cleared

Feature Category (Point Type)	Comments	Latitude WGS84 DDM	Longitude WGS84 DDM
Pump		33° 20.946' N	108° 04.794' W

FC Line Type	Comments	Repair Comments	Repair Priority	ARCH Clearance
Access or Improved Road	Dead end potentially connect with Dozer		Unknown	Not Cleared
Access or Improved Road	Posted private property, Cox Ranch 743-9604. Need permission to access.		Unknown	Not Cleared
Access or Improved Road			Unknown	Not Cleared
Access or Improved Road			Unknown	Not Cleared
Access or Improved Road			Unknown	Not Cleared
Completed Burnout	Hand ignitions		Unknown	Not Cleared
Completed Dozer Line	Repair complete	6/15: old road tank trapped @ road/gate and waterbarred. Needs seeding...	Unknown	Not Cleared
Completed Dozer Line	Completed by Land Owner		Unknown	Not Cleared
Completed Dozer Line	Completed by Land Owner		Unknown	Not Cleared
Completed Dozer Line	Structure protection		Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		Very rocky unable to water bar.	Unknown	Not Cleared
Completed Dozer Line			Medium	Cleared for Mechanical Repair
Completed Dozer Line	J.Ayers,06/16/22, ARCH	Pull berm. Waterbar. Slash track hoe better tool. Reseed	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		North Star 4. Waterbar, pull berm. Reseed. Not much slash. Pull large material from green side to block access.	Unknown	Cleared for Operations
Completed Dozer Line	J.Ayers,06/15/22,ARC	6/15: seeded, tank trapped, water barred, smoothed berms	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		Waterbar, cover w slash, knock down dozer berms, block access from campsite. Reestablish drainage near bottom	High	Cleared for Operations
Completed Dozer Line		Seeded. North Star 2. Will need machinery. Need to dis courage vehicle use post rehab 6/18: ripped, berms smoothed, tank trapped & blocked, slash placed in line	Unknown	Not Cleared
Completed Dozer Line		Repair will need equipment; steep so excavator w/thumb recommended		Cleared for Operations
Completed Dozer Line	Single blade along existing, then pioneers to tie into handline. Mod to heavy piles prepped for chipping	North Star 1	Medium	Cleared for Operations
Completed Dozer Line		seeded and slash placed	Unknown	Not Cleared
Completed Dozer Line	Up to 3 blades wide, ties into hand line. end of dozer line	Bloodgood 1. May need to reseed upper part where there is little slash	High	Not Cleared
Completed Dozer Line		Has been seeded; 6/19: berms smoothed access blocked with spread slash inside treeline	Unknown	Cleared for Mechanical Repair
Completed Dozer Line		Fairly float, line reseeded	Medium	Cleared for Mechanical Repair
Completed Dozer Line	Single blade dozerline, heavy piles of prepped line	McKnight 0. 6/19: berms are smoothed, handcrew has done waterbars	High	Not Cleared
Completed Dozer Line	Single track dozerline.	FSR 152A	High	Not Cleared
Completed Dozer Line	Single blade dozer, crosses blueline	FSR 152 B	High	Cleared for Operations
Completed Dozer Line		North Star 3. 6/18: berms knocked down, slash over line, entrance blocked, seeded	Unknown	Cleared for Operations
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line	Very light scrape in meadow and used as road access	6/17: Seeding complete	Unknown	Not Cleared
Completed Dozer Line	Not a fireline, just needed for access.	FST 980 B	Unknown	Not Cleared
Completed Dozer Line	needs material pulled onto line	seeding needed	Unknown	Not Cleared
Completed Dozer Line		Needs repair	High	Not Cleared
Completed Dozer Line		spread bio mass pull in burms water bars.	High	Not Cleared
Completed Dozer Line			High	Not Cleared
Completed Dozer Line		Part of North Star 4	Unknown	Not Cleared
Completed Dozer Line		Water bar per rehab specs. On a 37-40% slope.. pull existing slash over line, especially at road intersections	Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		Water bar and pull slash per rehab specs.6/21: inspected, needs waterbars and slash covering uphill section intersecting road	Unknown	Not Cleared
Completed Dozer Line	J.Ayers,06/14/22,ARC		Unknown	Cleared for Hand Crew Repair
Completed Dozer Line	J.Ayers,06/14/22, ARCH	6/19: waterbarred, slash scattered over line	Unknown	Cleared for Mechanical Repair
Completed Dozer Line	J.Ayers,06/16/22,ARC		Unknown	Cleared for Mechanical Repair
Completed Dozer Line		Dozer had to walk around rock drop off and push up slope from drainage bottom.	Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line	J.Ayers,06/16/22,ARC	water bars, knock down berms, more slash if possible	Unknown	Cleared for Mechanical Repair
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		Repaired dozer burns in creek bottom (jreimers_nifc 6/20)	Unknown	Not Cleared
Completed Dozer Line	Hand drawn based on READ Chamberlain	FSR 152 C	High	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		No repair needed per landowner request	Unknown	Not Cleared
Completed Dozer Line			Unknown	Not Cleared
Completed Dozer Line		reseed with grass, pull in burm, hay bales recommended for erosion control.	High	Not Cleared
Completed Dozer Line		Water bar per rehab specs. On a 37-40% slope.. pull existing slash over line, especially at road intersections	Unknown	Not Cleared

FC Line Type	Comments	Repair Comments	Repair Priority	ARCH Clearance
Completed Hand Line		None needed	Unknown	Not Cleared
Completed Hand Line		6/15: handline obliterated	Low	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line		6/20: obliterated, slash covered, flagging removed	Unknown	Not Cleared
Completed Hand Line	This is hand line not drive able in a vehicle please delete road as line where the handline is		Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line		6/17: seeded	Unknown	Not Cleared
Completed Hand Line	Improved existing trail		Unknown	Not Cleared
Completed Hand Line		6/19: pulled berms back, waterbarred, seeded, and slash over line	Unknown	Not Cleared
Completed Hand Line	Line for Wilson Lodge burnout. Plumbed		Unknown	Not Cleared
Completed Hand Line		Look for areas in the rocky section to get water off fire line. Do not stack large material.	Unknown	Not Cleared
Completed Hand Line			Medium	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Plumbed handline from structure #6 to two track road 6/19: no longer plumbed	Seed, spread debris back over line	Medium	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Tied into natural barrier that ties into black			Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Snagging needed minimal prep, line in place (existing)		Unknown	Not Cleared
Completed Hand Line	handline off end of dozer line		Low	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Completed 6/8/2022.		Unknown	Not Cleared
Completed Hand Line		6/17: seeding complete	Unknown	Not Cleared
Completed Hand Line	Planned handline. Fuel break from silver		Unknown	Not Cleared
Completed Hand Line	Handline along private property fence.	6/21: inspected and complete	Unknown	Not Cleared
Completed Hand Line	Connects rocky section of Dozer line.		Unknown	Not Cleared
Completed Hand Line		6/21: non-trail sections obliterated and trail sections reestablished	Unknown	Not Cleared
Completed Hand Line	6/16: dozer working tracking east from Escondido to cottonwood Well. Reassess		Unknown	Not Cleared
Completed Hand Line	From dozer line, east along fence line then turning south to Hwy 152.	6/21: inspected and repair complete	Unknown	Not Cleared
Completed Hand Line	Cleared brush off fence line and scraped fuels away from wood fence stays and posts. Follows a cow trail against the fence where it makes a V on the east portion. Prep work ends on the east side at a fence corner, 1,000 ft from N. Percha Rd..	6/21: Inspected and no repair necessary.; Crews just cleared vegetation along fence line and a light scrape around some wooden posts.	Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Hand line with brushing	Scatter back over line. 6/21: inspected	Unknown	Not Cleared
Completed Hand Line	Handlined around residence 9902 and 9906.	6/21: handline rehabbed, line obliterated and slash/ berms spread over line	Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	The dog leg in the SE portion needs to be rerouted slightly to avoid being over slung at mid-slope.	Rehab completed 6/19. 6/21: inspected and complete	Unknown	Not Cleared
Completed Hand Line			Unknown	Not Cleared
Completed Hand Line	Handline around Work Station main building and barn.		Unknown	Not Cleared
Completed Mixed Construction Line			Unknown	Not Cleared
Completed Mixed Construction Line	Road improved by single blade dozer. Light Brush cut and prepped for chipping		Unknown	Not Cleared
Completed Mixed Construction Line	Prepped line along existing 2 track		Unknown	Not Cleared
Completed Mixed Construction Line	Potential check line, single dozer line	6/19: tank trapped @ entrance, berms smoothed, slash covering line	Unknown	Not Cleared
Completed Mixed Construction Line			Unknown	Not Cleared
Completed Mixed Construction Line	Mostly all two track road that was never improved or prepped. It is in the same condition as before the incident.		Unknown	Not Cleared
Completed Mixed Construction Line	Road improvements with DOZ.		Low	Not Cleared
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC	Spoke to landowner (Solapek) regarding rehab spec. He approved of completed work.	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC	Repaired to landowner specs added Waterbars where needed (jreimers_nifc 6/20)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC No repair recommended - road in good shape. (amckeith_nifc 6/19)		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC Minimal repair needed. Smoothed section of existing road. (amckeith_nifc 6/19)		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC Tracked through. No repair to existing road required. (amckeith_nifc 6/19/22)		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC No repair recommended. Existing road in good shape. (amckeith_nifc 6/19)		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC Existing ranch road, improved with water bars. (amckeith_nifc 6/17)	Minimal dozer push from fire ops on existing ranch road. Improved with water bar installations to limit erosion.	Unknown	Cleared for Mechanical Repair

FC Line Type	Comments	Repair Comments	Repair Priority	ARCH Clearance
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC Water bar construction on steep section of dozer push (amckeith_nifc 6/19)		Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC Road smoothing and water bar installation (amckeith_nifc 6/19)	Repaired to	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC With burn out off rd	Repaired to landowner specs added Waterbars where needed (jreimers_nifc 6/20)	Unknown	Cleared for Mechanical Repair
Completed Mixed Construction Line			Unknown	Not Cleared
Completed Mixed Construction Line			Unknown	Not Cleared
Completed Mixed Construction Line	J.Ayers,06/18/22,ARC With burn out off rd	Repaired with Waterbars	Unknown	Cleared for Mechanical Repair
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		6/19: chipping 3/4 complete, should be complete 6/20	Unknown	Not Cleared
Completed Road as Line	6/15: brushed and prepped for chipping.		Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Old road used as line, no improvements made. Ties into handline		Unknown	Not Cleared
Completed Road as Line		6/19: graded	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Existing two track roads		Unknown	Not Cleared
Completed Road as Line	Existing two track roads		Unknown	Not Cleared
Completed Road as Line	Existing two track roads	6/19: no improvements made, gate is shut	Unknown	Not Cleared
Completed Road as Line	Existing two track roads	6/19: No suppression improvements, no repair needed	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		6/19: bladed where possible	Unknown	Not Cleared
Completed Road as Line		6/19: bladed completed where possible	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		Keep slash out of road. End of road is circle drive.	Unknown	Not Cleared
Completed Road as Line	Improved nonused road,		Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Existing road 150	Existing road, no dozerline, grading recommended	Unknown	Not Cleared
Completed Road as Line	Checkline	6/19: Berms smoothed, cowboy gate closed (needs new stays), slash spread at entrance	Unknown	Not Cleared
Completed Road as Line		6/19: chipping and lop/spread underway. ;Approxima 5 1/2 miles of mostly continuous slash. Chipper inaccessible.	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line		6/18: graded	Unknown	Not Cleared
Completed Road as Line	Lopped and prepped for chipping		Unknown	Not Cleared
Completed Road as Line	graveled road. Prepped slash on east side. Prepped chipping piles on west side	6/19: chipper and hand crew working north along road spreading and chipping. crewwo	Unknown	Not Cleared
Completed Road as Line		Chipping needed at Mile Marker 30, just below Wright's Cabin and at Mile Marker 31.	Unknown	Not Cleared
Completed Road as Line			Unknown	Not Cleared
Completed Road as Line	Hwy 152.	Need to chip slash from DP-140 to DP-141 at Lower Gallinas Campground. 3 chippers observed on this section of highway.	Unknown	Not Cleared
Completed Road as Line	Contingency line. Thinned fuel break along highway. Slash being chipped.	Crews currently chipping. 6/21: chipping complete and inspected	Unknown	Not Cleared
Completed Road as Line	Contingency line. Trees thinned/limbed sporadically as needed and where feasible.	Debris and slash is removed from roadway. 6/21: chipped and scattered off roadway	Unknown	Not Cleared
Completed Road as Line	Road prepped 30' to 40' on Fire side.	Chip slash.	Unknown	Not Cleared
Completed Road as Line		The lower end, in the pinyon, with a high amount of slash. 6/21: slash scattered, no sig impacts to road	Unknown	Not Cleared
Completed Road as Line	Hwy 152	6/21: chipping complete and inspected	Unknown	Not Cleared
Completed Road as Line	Brushed, piled and prepped for chipper	Chipper recommended. 6/21: chipping complete and inspected	Unknown	Not Cleared
Completed Road as Line	522 Road. Improved road travel conditions with some water turnouts. Road bladed. No veg prep work but is in scattered junipers and grass.	Much of the road has flat blade work with berms on each side of the road which will channel water. Add or reinstall water turn outs and rolling grade dips, particularly on the steeper sections.	Unknown	Not Cleared
Completed Road as Line	Prepped and chipped both sides 6/16/22	Chipping completed 6/18. No further repairs should be needed. 6/21: inspected and complete	Unknown	Not Cleared
Completed Road as Line	Lanford Repair		Unknown	Not Cleared
Completed Road as Line	Fuels reduction on the south side of the road. Road passible by truck and Type 6 engine. Small turnaround spot at the end of the road.	Chipping and back haul completed 6/19. 6/21: inspected and chipping complete and inspected	Unknown	Not Cleared
Other	ATV UTV trail		Unknown	Not Cleared
Other			Unknown	Not Cleared
Other	If fire reaches this point consider bringing fire south from Apache peak trail / hand line South to the next viable check feature.		Unknown	Not Cleared
Other	Don't show on map yet. Two-track road, narrow, grown over with grass. Very rough. Do not recommend a truck. Could be opened up with a dozer or improved as a handline.		Unknown	Not Cleared
Other	Access to "Black Range Ranch". Narrow road. Limited turnaround spots.		Unknown	Not Cleared
Repair Line			Unknown	Not Cleared
Road Repair		Spoke to landowner (Solapek) regarding rehab spec. He approved of completed work.	Unknown	Not Cleared
Road Repair			Unknown	Not Cleared
Road Repair	Left open per landowners request. Smoothed road bed for better UTV access		Unknown	Not Cleared