

Hazard Tree	Sling Site	MANDATORY EXCLUSION AREA	Road as Completed Line	Line/Delineation	Repair Status: Completed - Inspected	Land Owner: BLM
Aerial Hazard	Spot Fire	MANDATORY EXCLUSION AREA	Access or Improved Road	MANDATORY EXCLUSION AREA	Repair Status: Completed - Ready for Inspection	Land Owner: Other Private
Bridge	Incident Command Post	MANDATORY EXCLUSION AREA	Completed Flow Line	MANDATORY EXCLUSION AREA	Repair Status: In Progress	Land Owner: Sierra Pacific Industries
Camp	Stream Crossing	MANDATORY EXCLUSION AREA	Aerial Retardant Drop	MANDATORY EXCLUSION AREA	Repair Status: In Use - Fire Management	Land Owner: Super-Wheeler
Closure	Landmark	MANDATORY EXCLUSION AREA	Escape Route	MANDATORY EXCLUSION AREA	Repair Status: No Repair Needed	Land Owner: State Land
Culvert	Landing or Log Deck	MANDATORY EXCLUSION AREA	Highlighted Manmade Feature	MANDATORY EXCLUSION AREA	Repair Status: Other - See Comments	Land Owner: USDA Forest Service
Dip Site	Lookout	MANDATORY EXCLUSION AREA	Repair Line	MANDATORY EXCLUSION AREA	Repair Status: Repair Needed	Land Owner: National Park
Drop Point	Mobile Weather Unit	MANDATORY EXCLUSION AREA	Road Repair	MANDATORY EXCLUSION AREA	Repair Status: Unknown	Land Owner: US FWS
Door Push	Repair Point	MANDATORY EXCLUSION AREA	Contained, Not Controlled	MANDATORY EXCLUSION AREA	Repair Status: Other - See Comments	Land Owner: Other Federal
Fence - Cut/Damaged	Reservoir Location	MANDATORY EXCLUSION AREA	Unknown	MANDATORY EXCLUSION AREA	Repair Status: Unknown	Land Owner: Tribal Land
Fire Station	Retardant in Assistance Area	MANDATORY EXCLUSION AREA	SF Fuelbreak	MANDATORY EXCLUSION AREA		
Gate	Road Repair	MANDATORY EXCLUSION AREA	Contained Line	MANDATORY EXCLUSION AREA		
Hazard	Safety Zone	MANDATORY EXCLUSION AREA	Completed Door Line	MANDATORY EXCLUSION AREA		
		MANDATORY EXCLUSION AREA	Completed Hand Line	MANDATORY EXCLUSION AREA		

Repair Status: Completed - Inspected	Land Owner: BLM
Repair Status: Completed - Ready for Inspection	Land Owner: Other Private
Repair Status: In Progress	Land Owner: Sierra Pacific Industries
Repair Status: In Use - Fire Management	Land Owner: Super-Wheeler
Repair Status: No Repair Needed	Land Owner: State Land
Repair Status: Other - See Comments	Land Owner: USDA Forest Service
Repair Status: Repair Needed	Land Owner: National Park
Repair Status: Unknown	Land Owner: US FWS
	Land Owner: Other Federal
	Land Owner: Tribal Land


REPAIR/OPERATIONS

North Complex

CA-PNF-001308

11/4/2020

North Complex- Overview



0 1 2 3 4 5 6 Miles

1:80,000

Map Updated: 11/4/2020 10:02 AM