


Div O/P

Meyer Repair Area - Fountain Place

Caldor
 CA-ENF-24030
 October 14, 2021



0 0.47 0.95 1.9 Miles
 1:24,000
 NAD83 UTM 11N
 Prepared by: GB Team 7 10/13/2021 20:15

- | | | | |
|---|--|--|--|
| <ul style="list-style-type: none"> Other Property Pump Water Tank Aerial Hazard Check Point Dip Site Helispot Helibase Sling Site Unimproved Landing Area Incident Command Post Drop Point Staging Area Road Repair Repair Point Landing or Log Deck Fence - Cut/Damaged Dozer Push | <ul style="list-style-type: none"> Clean Up Area Mobile Weather Unit Internet Access Repeater Hazard Water Source Completed Dozer Line Completed Fuel Break Completed Hand Line In Progress Completed Road as Line Repair Line Road Repair Route Contained Line Wildfire Daily Fire Perimeter Forest Service Land State Public Lands Other State Lands | <ul style="list-style-type: none"> Private; Local Government; Undesignated Primary Fuel Breaks Secondary Fuel Breaks HazTree Priority Roads Hazard Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown | <ul style="list-style-type: none"> In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown |
|---|--|--|--|

