



Div O/P

LAKE TAHOE BASIN MANAGEMENT UNIT

HUMBOLDT-TOIYABE NATIONAL FOREST

- Other Property
- Staging Area
- Pump
- Road Repair
- Repair Point
- Fence - Cut/Damaged
- Dozer Push
- Clean Up Area
- Mobile Weather Unit
- Helibase
- Sling Site
- Unimproved Landing Area
- Division Break
- Incident Command Post
- Drop Point
- H - Completed Hand Line
- M - Completed Mixed Construction Line
- R - Completed Road as Line
- Repair Line
- Road Repair
- Route
- Contained Line
- Wildfire Daily Fire Perimeter
- Forest Service Land
- State Public Lands
- Other State Lands
- HazTree Priority Roads
- Completed Fuel Break

- Repair Status**
- Completed - Inspected
 - In Use - Fire Management
 - Completed - Ready for Inspection
 - In Progress
 - Repair Needed
 - No Repair Needed
 - Other - See Comments
 - Unknown

Meyer Repair Area - Fountain Place

Caldor
CA-ENF-24030
October 18, 2021

