

**Repair Status**

- Completed - Inspected
- In Use - Fire Management
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown
- In Use - Fire Management
- No Repair Needed
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Other - See Comments
- Unknown




**SUPPRESSION REPAIR**  
**Lava Fire**  
 CA-SHF-000949  
 July 15, 2021

- Uncontrolled Fire Edge
- Contained Fire Edge
- o o o Completed Dozer Line
- h h h Completed Fuel Break
- h h h Completed Hand Line
- h h h Completed Mixed Constr. Line
- h h h Completed Road as Line
- Access or Improved Road
- Other
- Road Repair
- I I Branch Break
- X Division Break
- Dip Site
- Helispot
- Sling Site
- Incident Command Post

- Drop Point
- Staging Area
- Hot Spot - Spot Fire
- Value at Risk
- Stream Crossing
- Road Repair
- Repair Point
- Repeater
- Water Source
- USFS Gate

- Dozer Push
- National Forest Boundary
- Non-FS Land within Forest Boundary
- Wilderness Boundary
- Historic Fire (2000-2020; 100+ ac.)

- Timberland Owner
- Fruit Growers Supply Company
- Michigan-California Timber Company
- Roseburg Resources Company
- Shasta Cascade Timberlands LLC
- Sierra Pacific Industries



Approximate fire perimeter from infrared and GPS as of 7/13/2021 @ 2009  
 NAD 1983 UTM Zone 10N  
 Contour Interval 40 ft.

