

































REPAIR PILOT

South Fork Complex September 13, 2023

REPAIR PILOT CA-SHF-001004 September 13, 2023



		 Sling Site	 Bridge	 Landing or Log Deck	 Hazard	 Event Point	 Repair Needed	 Other - See Comments	 Repair Needed
		 Drop Point	 Road Repair	 Dozer Push	 Water Source	 In Use - Fire Management	 In Progress	 Completed - Ready for Inspection	 Completed - Ready for Inspection
		 Staging Area	 Retardant in Avoidance Area	 Internet Access		 Needs Assessment	 Completed - Inspected	 In Use - Fire Management	 Completed - Inspected
		 Other	 Repair Point			 No Repair Needed	 No Repair Needed	 Needs Assessment	 No Repair Needed

0 0.1 0.1 0.3 0.4 0.6 Miles

Datum: NAD 1983 UTM Zone 10N

