


REPAIR PILOT

South Fork Complex September 14, 2023

REPAIR PILOT CA-SHF-001004 September 14, 2023



		 Sling Site	 Bridge	 Landing or Log Deck	 Hazard
 Drop Point	 Road Repair	 Dozer Push	 Water Source	 Retardant in Avoidance Area	 Internet Access
 Staging Area	 Repair Point	 Event Point	 Repair Status	 Other - See Comments	 Repair Needed
 Other	 In Use - Fire Management	 Needs Assessment	 No Repair Needed	 Repair Needed	 In Progress
				 Completed - Ready for Inspection	 Completed - Inspected
				 In Use - Fire Management	 No Repair Needed
				 Needs Assessment	 Other - See Comments

0 0.1 0.1 0.3 0.4 0.6 Miles

Datum: NAD 1983 UTM Zone 10N