



Repair Legend

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Chipping Needed

GISS_Misc2	FeatureCategory	LatWGS84_DDM	LongWGS84_DDM	RepairStatus	RepairsNeeded
1145	Drop Point	41° 46.787' N	123° 55.718' W	Repair Needed	Pull back berms. Spread all available slash over bare soil. Spread 12 pallets of mulch over bare soil at drop point. S3 5/16/24
144	Drop Point	41° 45.535' N	123° 55.480' W	Repair Needed	Pull back berms. Spread slash over bare soil. Spread 6 pallets of mulch over bare soil at drop point area. S3 5/16/24
1132	Dozer Push	41° 45.535' N	123° 55.480' W	Repair Needed	Pull back berms. Disperse vegetation. REAF BCODE, 5/9/24
1133	Dozer Push	41° 45.535' N	123° 55.493' W	Repair Needed	Call back Burns. Dispersed vegetation. REAF BCODE, 5/9/24
1130	Dozer Push	41° 45.152' N	123° 53.490' W	Repair Needed	Need large chipper, masticator and excavator to pull out trees and brush that are on edge of road. Chips should be spread out on barren ground. Root wads need to be cut off and dispersed over the bank 6 hours work Reaf Cann 9-15-23.
1146	Dozer Push	41° 46.769' N	123° 55.723' W	Repair Needed	Pull berms back. Scatter vegetation over disturbed site. REAF BCODE, 5/9/24.
134	Repair Point	41° 45.430' N	123° 54.531' W	Repair Needed	Remove and chip slash pile on road. REAF B Code, 5/10/24.
133	Dozer Push	41° 45.423' N	123° 54.513' W	Repair Needed	Pullback berms. Remove large vegetation pile in the middle of road. REAF BCODE, 5/10/24.
1265	Drop Point	41° 47.698' N	123° 58.565' W	Needs Assessment	FULL REPAIR Pull in slash and naturalize. // Large chipper or tub grinder needed to chip large quantities of trees and brush. An excavator may be needed to move trees from down the bank up to the road. Reaf Cann 9-16-23.
1275	Dozer Push	41° 47.666' N	123° 58.717' W	Repair Needed	berms and slash exists where we want to block entrance per forest standard. reformat berms and distribute slash evenly across entrance REAF Burton 5/15/24
129	Dozer Push	41° 45.164' N	123° 53.472' W	Repair Needed	FULL REPAIR Pull in slash and naturalize. // Large chipper or tub grinder needed to chip large quantities of trees and brush. An excavator may be needed to move trees from down the bank up to the road. Reaf Cann 9-16-23.
1129	Dozer Push	41° 45.498' N	123° 55.315' W	Repair Needed	Pull back berms. Disperse vegetation. REAF BCODE , 5/9/24
1635	Hazard Tree	41° 46.882' N	123° 55.170' W	Repair Needed	remove downed hazard tree from road prism. previously flagged with pink ribbon
	Repair Point	41° 47.074' N	123° 54.860' W	Repair Needed	Hand crew and chipping needed. REAF BCODE, 05/09/24
	Closure	41° 47.056' N	123° 54.870' W	Repair Needed	mint tank trap with boulders to allow stream channel to flow. REAF Burton 5/16/24
	Closure	41° 47.019' N	123° 54.956' W	Repair Needed	

GISS_Misc2	FeatureCategory	RepairStatus	RepairsNeeded	Label	LengthFeet
165	Completed Road as Line	Repair Needed	Chip slash along road. REAF BCODE, 5/10/24	Chip	17842
24	Road Repair	Repair Needed	Grading needed on travel-way, pull back berms on out slope of roadway. Repair existing rolling dips and place where needed. REAF BCODE, 05/13/24		7588
171	Completed Road as Line	Repair Needed			607
198	Completed Road as Line	In Progress	chip piled material REAF_TONER 9/12/23, cleared ARCH Sullivan 9/14/23	Chip	7179
101	Completed Road as Line	In Progress	ARCH Leonard cleared 9/4 // Chizolla Self feeding chipper. Broadcast chips. Type 2 excavator to assist in operation. Estimated 3 days. REAF Olson 9/15	Chip	2097
106	Completed Road as Line	Repair Needed	Chip accessible masticated vegetation along both sides of roadway where available. REAF B Code, 5/10/24.	Chip	7253
107	Completed Road as Line	Repair Needed	improved road: widened and mastication along this section of road. repairs: slash needs chipped, any soil piles need pulled in and smoothed out.	Chip	351
110	Completed Road as Line	Repair Needed	Improved road w/ fuel reduction 15' upstoge from road. Pull behind chipper and Hand Crew. Broadcast chips. REAF Olson 9/16	Chip	4575
200	Road Repair	Repair Needed	Hand crew and chipping needed. REAF BCODE, 05/09/24	Chip	3049
201	Road Repair	Repair Needed	Hand crew and chipping needed. REAF BCODE, 05/09/24		1082
	Access or Improved Road	Repair Needed			552

- Helispot
- Repair Point
- Local Road
- Drop Point
- Hazard Tree
- 4WD
- POC Gate
- Dozer Push
- Closed Road
- ⊙ Water Source
- Paved Road
- Smith River Cx Wildfire Perimeter
- Drop Point
- Primitive Road
- Closed Roads
- Closure
- Closed Roads

SPRING SUPPRESSION REPAIR

Smith River Complex - Coon Repair Area

94,639 acres as of 11/13/2023
Map Date 05/17/2024

INTERAGENCY INCIDENT MANAGEMENT TEAM

FOREST SERVICE
U.S. DEPARTMENT OF AGRICULTURE

SIX RIVERS National Forest

1:9,000 NADES UTM 10N

Smith River Complex
CA-SRF-000968

REPAIR