



Repair Legend

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Chipping Needed

GISS_Misc2	FeatureCategory	LatWGS84_DDM	LongWGS84_DDM	RepairStatus	RepairsNeeded	Label	LengthFeet
149	Road Repair	41° 50.743' N	123° 56.413' W	Needs Assessment	not obviously damaged by fire looks like it was shot and then cut RMD 4/25. Assess if sign damage was result of fire, suppression, or non-fire related.	Chip	3436
1265	Drop Point	41° 47.698' N	123° 58.565' W	Needs Assessment		Chip	7588
1275	Dozer Push	41° 47.660' N	123° 58.717' W	Repair Needed	berms and slash exists where we want to block entrance per forest standard. reformat berms and distribute slash evenly across entrance REAF Burton 5/15/24	Chip	7179
1622	Repair Point	41° 50.552' N	123° 55.586' W	Repair Needed	Use hand crew to remove bucked logs and cut brush from creek.	Chip	2490
18	Completed Road as Line			Repair Needed	Straw and waddle fill slope on French Hill Road. Pull in material, and Berms on dozer line. Water bar in steep areas. Earth Barrier to block ingress from 17N40 to line.	Chip	3436
24	Road Repair			Repair Needed	Grading needed on travel-way, pull back berms on out slope of roadway. Repair existing rolling dips and place where needed. REAF BGOMEZ, 05/13/24	Chip	7588
44	Completed Road as Line			In Progress	Chip slash on side entire length of road. Install water bars to spec.	Chip	4565
198	Completed Road as Line			In Progress	Chip piled material REAF_TONER 9/12/23, cleared ARCH Sullivan 9/14/23	Chip	7179
67	Completed Road as Line			In Progress	Pile bucked logs and slash and cover with plastic, pull back in dozer pushes along roadside. Install rolling dips.	Chip	3659
94	Completed Road as Line			Repair Needed	rolling dips or waterbars along rd to facilitate drainage closer to the junction, pull back berms and even out along length of rd. REAF BGOMEZ, 05/13/24	Chip	2490

- Helispot
- ▲ Dozer Push
- 4WD
- Drop Point
- Paved Road
- Closed Road
- Water Source
- Gravel Road
- Highway
- Drop Point
- Primitive Road
- Smith River Cx Wildfire Perimeter
- ▲ Road Repair
- Closed Roads
- Local Road
- Repair Point
- Local Road

SPRING SUPPRESSION REPAIR

Smith River Complex - French Hill Repair Area

94,639 acres as of 11/13/2023
Map Date 05/17/2024

INTERAGENCY INCIDENT MANAGEMENT TEAM

FOREST SERVICE
DEPARTMENT OF AGRICULTURE

SIX RIVERS
National Forest

1:8,000 NA83S UTM 10N

Smith River Complex
CA-SRF-000968

REPAIR