

GIS5 Misc2	FeatureCategory	RepairsStatus	FeatureCategory	RepairsNeeded	RepairsComments	Label	LengthFeet
10	Completed Road as Line	Repair Needed	Repair Needed	Pull berms, water bar as needed, chip, block at USFS property line	Leonard/Meingast 8/26	Chip	1440
107	Completed Road as Line	Repair Needed	Repair Needed	Improved road: widened and mastication along this section of road. repairs: slash needs chipped, any soil piles need pulled in and smoothed out.		Chip	351
123	Completed Road as Line	Repair Needed	Repair Needed	chip cut vegetation		Chip	461
124	Completed Road as Line	Repair Needed	Repair Needed	chip cut vegetation		Chip	2241
135	Access or Improved Road	Repair Needed	Repair Needed			Chip	3247
153	Repair Line	Repair Needed	Repair Needed			Chip	9100
179	Completed Road as Line	Repair Needed	Repair Needed	Chip vegetation along road. Straw and waddle fill slope on French Hill Road. Pull in material, and Berms on dozer line. Water bar in steep areas. Earth Barrier to block ingress from 17N40 to line.	No repair needed. REAF Cann 9-12-23. Pull in berms on roadside REAF Kovasi 4/25/24	Chip	1484
18	Completed Road as Line	Repair Needed	Repair Needed	Chip vegetation along road. Straw and waddle fill slope on French Hill Road. Pull in material, and Berms on dozer line. Water bar in steep areas. Earth Barrier to block ingress from 17N40 to line.	Leonard ARCH cleared 9/4	Chip	3436
183	Planned Road as Line	Repair Needed	Repair Needed		Slash & debris chipped on 9/24 per Macker Babb.	Chip	1510
19	Completed Road as Line	Repair Needed	Repair Needed	Chipping, pull berms	Leonard/Meingast 8/27	Chip	405
24	Completed Road as Line	Repair Needed	Repair Needed	Chip, pull out-slope berms		Chip	7588
26	Completed Road as Line	Repair Needed	Repair Needed	Grade road, chip or scatter any material left from brushing	rd could use several waterbars or rolling dips, eroding at steep curves,several remaining dozer pushes obstructing drainage, pull back and even out. RMD 4/26. Leonard 8/26	Chip	3567
30	Completed Road as Line	Repair Needed	Repair Needed	recommend saw crew and chipper for piled vegetation not addressed by masticator: grader expected to add rolling dips on 0831		Chip	4313
31	Completed Road as Line	Repair Needed	Repair Needed	excavator or saw crew and chipper if masticator doesn't get to entire segment	excavator or saw crew and chipper if masticator doesn't get to entire segment	Chip	2232
35	Completed Dozer Line	Repair Needed	Repair Needed	pull berms back over line and recontour, chip and/or scatter slash, block ingress/egress. Williams 9/8	Leonard/Toner 8/31	Chip	228
73	Completed Dozer Line	Repair Needed	Repair Needed	pull berms back over line, chip fuel, potato patch on each end to stabilize and prevent ohv access. William's 9/8. ARCH Platt 9/9/23.		Chip	1955
87	Completed Dozer Line	Repair Needed	Repair Needed	Road needs chipped from here to end of 17N07.	Chipping	Chip	103
9	Completed Road as Line	Repair Needed	Repair Needed	Pull berms, disperse push piles, chip	Line travels through private property most of the way, repair comments are for F5 land. Leonard/Meingast 8/26	Chip	9043
93	Completed Road as Line	Repair Needed	Repair Needed	lots of slash pushed, recommend chipping or possibly pile and burn. REAF Jackson 9/12/23		Chip	538
99	Completed Road as Line	Repair Needed	Repair Needed	Grade road, chip or scatter any material left from brushing		Chip	3948
	Completed Road as Line	Other - See Comments	Other - See Comments	Established unauthorized road. Knock down berms to allow water runoff. Establish drainage at crossings(match gradient of stream) block ingress. Chip slash Michels/Meingast 9/21 Go back to clean/dig out ditch. 09/24 READ Gomez	Completed, inspected by Gomez. See repair point for completed ditch repair. REAF This 9/30	Chip	7697
	Completed Road as Line	Other - See Comments	Other - See Comments	mastication removed vegetation debris on north end. recommend saw crew and chipper for southern portion if not reached by masticator, grader expected to add rolling dips for drainage on 0831	This section private.	Chip	8367
	Completed Road as Line	Other - See Comments	Other - See Comments	small pocket of vegetation could be chipped if other chipping is occurring in the area, otherwise, no repair needed		Chip	318
	Completed Road as Line	Other - See Comments	Other - See Comments		9/30. Gravel public road section if possible. Material on road has been chipped.	Chip	2652
	Completed Road as Line	No Repair Needed	No Repair Needed	Grade gravel section of 4402 road.	Material has been chipped.	Chip	5313
	Completed Dozer Line	No Repair Needed	No Repair Needed	pull back berms, water bar chip and spread slash		Chip	518
	Completed Road as Line	No Repair Needed	No Repair Needed	chip roadside slash		Chip	1081
	Completed Road as Line	No Repair Needed	No Repair Needed	chip roadside slash		Chip	503
	Completed Road as Line	No Repair Needed	No Repair Needed	chip roadside slash		Chip	21653
	Completed Road as Line	No Repair Needed	No Repair Needed	Chip Slash along road	REAF Burton 9/12. no slash to chip	Chip	2018
	Completed Road as Line	No Repair Needed	No Repair Needed		Chipping	Chip	511
	Completed Dozer Line	No Repair Needed	No Repair Needed	chip slash, pull back soil berms, install water bars, and leave enough slash for erosion control		Chip	1208
	Completed Dozer Line	No Repair Needed	No Repair Needed	chip slash, pull back soil berms, install water bars, and leave enough slash for erosion control		Chip	905
	Completed Road as Line	No Repair Needed	No Repair Needed	chip slash cut on roadside. Williams 9/10	Leonard ARCH cleared 9/4	Chip	3024
	Completed Road as Line	No Repair Needed	No Repair Needed		Chipping	Chip	511
	Completed Road as Line	No Repair Needed	No Repair Needed	Chip road slash	Ok to chip down hill with pull behind but too steep pulling up hill, tracked chipper if working up hill	Chip	1467
	Completed Road as Line	No Repair Needed	No Repair Needed	None		Chip	10608
	Completed Hand Line	No Repair Needed	No Repair Needed	Pile shrub/small tree berm for chipping. REAF This 9/8	REAF Cann 9-23-23.	Chip	164
	Completed Road as Line	No Repair Needed	No Repair Needed	Potential chipping		Chip	3150
	Completed Dozer Line	No Repair Needed	No Repair Needed	water bar pull berms, chip debris spread slash		Chip	4212
	Completed Road as Line	No Repair Needed	No Repair Needed	Grade gravel section of 4402 road.	Material has been chipped	Chip	7896
	Completed Road as Line	No Repair Needed	No Repair Needed	Grade road, chip or scatter any material left from brushing		Chip	408
	Completed Dozer Line	No Repair Needed	No Repair Needed	water bar and chip		Chip	440
	Completed Road as Line	No Repair Needed	No Repair Needed	Chip road slash	Ok to chip down hill with pull behind but too steep pulling up hill, tracked chipper if working up hill	Chip	51
	Completed Dozer Line	No Repair Needed	No Repair Needed	pull back berms, water bar chip and spread slash		Chip	925
	Completed Dozer Line	No Repair Needed	No Repair Needed	pull back berms, water bar chip and spread slash		Chip	142
	Completed Dozer Line	No Repair Needed	No Repair Needed	pull back berms, water bar chip and spread slash		Chip	1057
	Completed Road as Line	No Repair Needed	No Repair Needed	yes	chip slash from along the road, mostly downslope. low stump	Chip	415
	Completed Road as Line	No Repair Needed	No Repair Needed	Chipper needed	Chip road side slash. Pull behind chipper	Chip	1261
	Completed Dozer Line	No Repair Needed	No Repair Needed	Single dozer width wide. Pull back berms, chip slash, naturalize/flatten roadbed. Keep open per landowner request. 11/7 Peppin		Chip	0
154	Repair Line	No Repair Needed	No Repair Needed	Duplicate	chip piles that were moved across road during suppression activities to treat black side	Chip	1317
POD	Completed Road as Line	No Repair Needed	No Repair Needed	None		Chip	1549
POD	Completed Road as Line	No Repair Needed	No Repair Needed	yes	chip slash along road and low stump	Chip	1479
POD	Completed Road as Line	No Repair Needed	No Repair Needed	No	limited slash does not need chipping	Chip	1705
POD	Completed Road as Line	No Repair Needed	No Repair Needed	None identified	Leonard/Toner 9/1	Chip	4438
POD	Completed Road as Line	No Repair Needed	No Repair Needed	Only a couple of branches, no piles. Ok. REAF This 10/4		Chip	7097
101	Completed Road as Line	In Progress	In Progress	ARCH Leonard cleared 9/4 // Chippita Self feeding chipper. Broadcast chips. Type 2 excavator to assist in operation. Estimated 3 days. REAF Olson 9/15	Equipment needed, cleared for hand crew work? BM 9/30.	Chip	7253
106	Completed Road as Line	In Progress	In Progress	Improved road: black dropped on road, soil berm along road side, slash piled on side, mastication along road. repairs: pull soil berms over road and smooth, chip piled slash, ensure water drainage. arch platt 9/15/23.		Chip	4575
110	Completed Road as Line	In Progress	In Progress	Improved road w/ fuel reduction 15' upslope from road. Pull behind chipper and Hand Crew. Broadcast chips. REAF Olson 9/16	slash on downside of road needs chipping. REAF_TONER 10/12	Chip	1314
122	Completed Road as Line	In Progress	In Progress	chip out vegetation	More chipping to end of road - Eric Johnson April 2024. Chipping complete. REAF Berg 10/2.	Chip	7179
198	Completed Road as Line	In Progress	In Progress	chip piled material REAF_TONER 9/12/23. cleared ARCH Sullivan 9/14/23		Chip	4273
47	Completed Hand Line	In Progress	In Progress	Line looks like it's repairing itself after the winter, excess slash could be chipped through REAF Kovasi 4-25-24. top and scatter slash or chip slash behind house- above headline on old rd bed, pull berms onto headline and spread slash REAF_TONER 10/11	Use caution with water crossing	Chip	4565
44	Completed Road as Line	In Progress	In Progress	Chip slash on side entire length of road. Install water bars to spec.	dozer line repaired and road portion of line not repaired. inspected by REAF_TONER 10/13	Chip	2620
6	Completed Mixed Construction Line	In Progress	In Progress	along rd s/n pull in berms, clear debris from culvert, chip slash. RMD 4/26CRITICAL REPAIR. Leonard 8/25 - Pull berms, water bar in steep areas, pull in slash and debris, repair road to standard, block ingress/egress of dozer y. REAF Cann 9-12-23.	John Theuerkauf (JT) private land owner says road had water bars before and would like them repaired. READ Pernas //Rolling dips installed, but may be improved. Adjustments to specs and frequency will be determined by Forest engineering. Drainage outlet.	Chip	5214
65	Completed Mixed Construction Line	In Progress	In Progress	Consider chipping intermittent brush piles. Knock drainage holes in dirt berm. REAF This 9/6	Logs have been bucked, chipping and rolling dips not done yet 10/1 REAF This	Chip	3059
67	Completed Road as Line	In Progress	In Progress	Pile bucked logs and slash and cover with plastic. pull back in dozer pushes along roadside. Install rolling dips.	Berms on outslope notched for hydro relief. dips / bars installed at drainage crossings. heavy slash along road still needs chipped and spread. berm along entire road still needs pulled and road bed out sloped to forest specs. Down trees need cleared SJ	Chip	10464
72	Completed Road as Line	In Progress	In Progress	critical repair: opened decommissioned road. Large berms along entire road. recontour soil, pull slash over, waterbar where needed. stream crossing need recontoured so outflow is open.	Slash covers hard line ~200ft on north and south side- completed and inspected- REAF Ewing 9/22/23	Chip	1092
	Completed - Inspected	Completed - Inspected	Completed - Inspected	At south end, pull brush berm to rd for chipping. Pull slash to cover 100 ft in to obscure line visibility. REAF Olson 9/18	Ok. Repair point at bottom remains. 10/2 This	Chip	1232
	Completed Hand Line	Completed - Inspected	Completed - Inspected	Super steep. Recontour line rather than water bars. Cover with slash. Bucked trees and limbs at bottom need dispersal, chipping or piling		Chip	1193
	Completed Dozer Line	Completed - Inspected	Completed - Inspected	pull back berms, water bar chip and spread slash	Chipping completed and inspected-REAF Ewing 9/22/2023	Chip	990
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Slash should be pulled back onto line and be blocked at 305 road to prevent future use of Forest wants it closed. If to remain open slash should be chipped. Still piled Busby 9/10. This section of road should be a Strategic Line. REAF Cann 9-21-23.	Chipping complete. Individual culverts needing repair were marked separately. 9/30 REAF This	Chip	8454
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip material, clear culvert inlets of debris. Material was masticated. REAF Cann 9-17-23.		Chip	5490
	Completed Road as Line	Completed - Inspected	Completed - Inspected	minimal brush chipping along road with low stumping	Ok 10/1 REAF This	Chip	2459
	Completed Hand Line	Completed - Inspected	Completed - Inspected	No waterbars needed on rock slope. Buck small trees and pull back brush or chip. REAF This 9/6		Chip	2687
	Completed Dozer Line	Completed - Inspected	Completed - Inspected	pull back berms, water bar chip and spread slash		Chip	15969
	Completed Road as Line	Completed - Inspected	Completed - Inspected	1 dozer wide w/ fuels removal along line. soil bermed along edge, large slash piles. needs chipper for larger fuel (self feeding chipper), type 3 excavator to pull soil and veg back over line, recontour and potato patch. block ingress/egress with heaves	Chipping completed and inspected-REAF Ewing 9/22/23	Chip	1751
	Completed Dozer Line	Completed - Inspected	Completed - Inspected	chip berm of small trees and shrubs. REAF This 9/7	limited slash creation.	Chip	1098
	Completed Road as Line	Completed - Inspected	Completed - Inspected	No	LIGHT REPAIR, Chip slash and clear drainage ditch; FULL REPAIR, redistribute berms, chip slash and clear drainage ditch -Jberg- 9/2	Chip	184
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Disperse out-slope berms, chip window along road	Chipping completed, some intermittent brush is remaining. If more chipping needed please add as a repair point. Road work	Chip	10994
	Completed Road as Line	Completed - Inspected	Completed - Inspected	chip roadside slash, leave enough for ground cover		Chip	4452
	Completed Mixed Construction Line	Completed - Inspected	Completed - Inspected	Rocky berm with debris needs pulled back. Consider chip 4-10 berms of brush (minimal soil). REAF This 9/6	Chipping is complete. Need excavator to pull back rocky berms, trees, and disperse roadways. REAF This 10/1	Chip	1636
	Completed Dozer Line	Completed - Inspected	Completed - Inspected	Type 3 or short 2 excavator. brush and roadways in berms. //Multiple larger dozer pushes need to be pulled back and dispersed. 10/1 This	Logs mostly bucked already 9/6//chipping was done, but excavator repair still needed 10/1 This//Excavator work complete 10/7, hand crew finished slash work 10/8 Gritzer 10/8	Chip	1202
	Completed Dozer Line	Completed - Inspected	Completed - Inspected	Pull back small soil berm/brush. What to do with logs and bucked rounds? REAF This 9/6	Some logs have been bucked and chipping was done, but berms still exist and line is open as drivable road. Berms too large for HC. 10/1 REAF This	Chip	424
	Completed Road as Line	Completed - Inspected	Completed - Inspected	chip and spread material REAF_TONER 9/13/23	repair complete and inspected REAF_TONER 9/13/23	Chip	11250
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip piles along roadway. REAF Berg 10/2.	Piles along road has been chipped. REAF Berg 10/3.	Chip	5201
	Completed Dozer Line	Completed - Inspected	Completed - Inspected	2 blades wide, large soil and slash piles, pull soil and slash in. potato patch mild slopes, water bar steep slopes, arch platt 9/14/23.	1/3 done with dozer - will need self feeding chipper REAF Sell 10/1	Chip	1876
	Completed Dozer Line	Completed - Inspected	Completed - Inspected	slash needs chipped and berms pulled on outslope REAF_TONER 10/13		Chip	1690
	Completed Hand Line	Completed - Inspected	Completed - Inspected	Where headline meets the trail, cover with brush, and pull hose lay, approximately 200 yards of hose. REAF Code SRF/ Also, pull escape route flagging and consider pulling cut brush from thick understorey for chipping. This 9/30	Hose was pulled, slash put over line. Potential stream crossings were looked at, no repair needed. 9/30 This	Chip	587
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip road slash	Ok to chip down hill with pull behind but too steep pulling up hill, tracked chipper if working up hill	Chip	470
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip road slash	Ok to chip down hill with pull behind but too steep pulling up hill, tracked chipper if working up hill	Chip	57
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip road slash	Ok to chip down hill with pull behind but too steep pulling up hill, tracked chipper if working up hill	Chip	156
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip road slash	Ok to chip down hill with pull behind but too steep pulling up hill, tracked chipper if working up hill	Chip	118
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chipper needed	Chip road side slash. Pull behind chipper	Chip	73
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip	Chipping	Chip	499
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip		Chip	4026
	Completed Road as Line	Completed - Inspected	Completed - Inspected	yes	chip slash along road and low stump	Chip	217
	Completed Road as Line	Completed - Inspected	Completed - Inspected	Potential chipping		Chip	926
	Repair Line	Completed - Inspected	Completed - Inspected	Chipping.	Chipping complete 10/5 This	Chip	995
	Completed Road as Line	Completed - Inspected	Completed - Inspected	pull berms from shallow scrape. chip slash piled along road REAF_TONER 9/17	No chipping needed along road piles have been cleared. REAF Berg 10/4.	Chip	1533
	Completed Road as Line	Completed - Inspected	Completed - Inspected	chip brush. estimate 1 day for pull behind chipper. REAF Jackson 9/18		Chip	1558
	Repair Line	Completed - Inspected	Completed - Inspected		chip piles that were moved to opposite side of road during suppression activities	Chip	0
	Repair Line	Completed - Inspected	Completed - Inspected		chip piles moved to opposite side of road during suppression activities to remove piles from active fire edge	Chip	0
126	Repair Line	Completed - Inspected	Completed - Inspected	Use hand crew to remove debris from inboard ditch. Chip or throw debris over embankment. REAF Cann 9-20-23.	Repair in progress. REAF Cann 9-21-23. Repair completed REAF Kovasi 4-25-24	Chip	2221
150	Completed Dozer Line	Completed - Inspected	Completed - Inspected	Smooth out rocky berms, and cover with slash. Cut all down trees into rounds for firewood and stack on road edge. REAF_TONER 10/11	inspected 4/30 RMD. slash spread on side of single blade dozer line. berms still need pulled to naturalize REAF_TONER 10/11. Landowners would only like first 100ft disguised. Chip rest of material. Keep line open. Cleanup garbage.	Chip	0
45	Completed Mixed Construction Line	Completed - Inspected	Completed - Inspected	Smooth berms and recontour to slope. Cut trees and down large wood into firewood. Pile slash and/in center of line and cover with plastic. SJ 4/19	inspected 4/30 RMD. Brush chipped per landowner request. Toss stumps in the woods. Keep one blade width open. 11/7 Peppin.	Chip	714
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip and row of brush and slash near dozer line on monkey ridge. Short section along the road.	FULL REPAIR, pull berms and slash, block ingress/egress.	Chip	10122
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	JAL 8/24 - Remove debris from roadside ditch	Arch cleared by Leonard 9/24 // Burn piles existed prior to suppression activities. chip only material caused by suppression activities. REAF Cann 9-12-23.	Chip	15775
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	chip or scatter unburned material	Areas are burned over, slash chipped & scattered. Completed on 9/23/23 per Macker Babb.	Chip	22626
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	recommend chipper to remove brush slash from west side of road. REAF Loose 0825	Complete. All culverts checked and ok. 9/30 This	Chip	1177
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	recommend chipper to reduce shrub slash stacked on west side of road	Ok 9/30 reaf This	Chip	2036
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected		chip slash and low stump, pretty minimal	Chip	4222
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected		REAF Olson 9/18	Chip	9673
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip material, clear culvert inlets of debris.	Ok 9/30 REAF This	Chip	4646
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	yes	chip any slash and low stump, very minimal	Chip	3790
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	yes	chip any slash and low stump, minimal	Chip	3143
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	see comments	water bar as needed, pull back berms, chip or burn slash. too much to scatter. low stump needed.	Chip	1209
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	yes	chip slash along road and low stump	Chip	2766
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	None	REAF Olson 9/18	Chip	9562
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	yes	chip slash from along the road, mostly downslope. low stump	Chip	1474
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip vegetation piles	Leonard/Toner 8/31	Chip	3617
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip vegetation piles	Leonard/Toner 8/31	Chip	746
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	Drainage, see rd repair icons REAF This 9/2 // Chipper needed to remove slash piles along road. 1/2 days worth w/ hand crew. REAF Olson 9/17	Chipping complete. Drainage has separate repair point. 10/5 This.	Chip	1307
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	needs to be chipped	REAF Olson 9/18	Chip	5170
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	chip vegetation stacked on East side of road	REAF Olson 9/18	Chip	3670
POD	Completed Road as Line	Completed - Inspected	Completed - Inspected	Chip window along road	REAF Olson 9/18	Chip	622
POD	Completed Road as Line	Completed -					