




# Suppression Repair

Dolan Fire  
 CA-LPF-002428  
 11/3/2020 DAY

124,924 acres at 9/28/2020 2000 hrs



Microsoft Building Footprints (MSBFP)	Completed Dozer Line, Completed - Inspected
Summits	Completed Dozer Line, Completed - Ready for Inspection
Camp	Completed Dozer Line, No Repair Needed
Closure	Completed Dozer Line, Other - See Comments
Culvert	Completed Dozer Line, Repair Needed
Dip Site	Completed Hand Line, Completed - Inspected
Drop Point	Completed Hand Line, No Repair Needed
Dozer Push	Completed Hand Line, Repair Needed
Fence - Cut/Damaged	Road as Completed Line, Completed - Inspected
Remote Sleeping Area	Road as Completed Line, No Repair Needed
Gate	Road as Completed Line, Repair Needed
Mining Hazard	Dolan Repair Area
Hazard Tree	Restricted Area
Unimproved Landing Area	CA State Park
Helispot	Ventana Wilderness
Hot Spot	The Pacific Ocean
Incident Command Post	Wildfire Daily Fire Perimeter
Internet Access	Trail
Repair Point	Expressway
Repeater	Secondary Hwy
Road Repair	Local Connector
Safety Zone	Local Road
Sling Site	Ramp
Staging Area	4WD
Structure Wrap	Tunnel
Water Source	Forest Service
Water Development or Draft Site	Fort Hunter Liggett
Value at Risk	Township/Range
Unknown	Land Grant
Division Break	Section
Repair Needed	Federal Responsibility Area
Unknown	Local Responsibility Area
Access or Improved Road, Completed - Inspected	State Responsibility Area
Access or Improved Road, No Repair Needed	Runway
Access or Improved Road, Repair Needed	



EAIMT GISS  
 11/2/2020 2127  
 Acres from IR and field reports  
 NAD 1983 California Teale Albers