

BRIDGER FOOTHILLS MT-CGF-000214



Structure Assessment 9/11/20

Perimeter as of 9/7/20 @ 2100 8,244 ac.



9/11/2020 1343


0 0.125 0.25 0.5 Miles

PAGE 1

Structures

Structure Damage

- Destroyed
- Major
- Minor
- No Damage



2221 Beasley Creek Rd

2219 Beasley Creek Rd

1290 Beasley Creek Rd

2000 Rising Spirits

1555 Place Creek

1927 Rising Spirits

1849 Rising Spirits

3090 Bridger Hills Dr

3095 Bridger Hills Dr

1600 Place Creek

2803 Bridger Hills Dr

1640 Place Creek

1611 Place Creek

1608 Place Creek

75 Louise Ln

80 Louise Ln

2460 Bridger Hills

1890 Bridger Hills Rd

2429 Bridger Hills

7001 Bridger Canyon

7003 Bridger Canyon

247 Mayfield Gulch

Flaming Arrow Rock 4,980

100 Mayfield Gulch

5917 Bridger Canyon

7157 Bridger Canyon Rd

Drinking Horse Mountain 5,522

Mount Baldy 7,106