


**Garner Complex**  
**Suppression Repair**  
 OR-712S-016619  
 PNL0P0 (1502)

- |  |  |  |
|--|--|--|
| <span style="color: green;">●</span> Completed - Inspected | <span style="color: yellow;">—</span> Skid Chip Drainage | <span style="color: green;">—</span> Completed                         |
| <span style="color: red;">●</span> Repair Needed           | <span style="color: purple;">—</span> Skid Drainage      | <span style="color: orange;">—</span> Completed - Ready for Inspection |
|  | <span style="color: brown;">—</span> Chip Only           | <span style="color: red;">—</span> Unknown                             |
|  | <span style="color: blue;">—</span> Drainage Only        |  |



Created by: Southwest Oregon GIS Support  
 9/14/2018 18:17 PT

September 15, 2018

